S E R V I C E   N O T E

SUPERSEDES: 5DX-97-03
Dated June 12, 1997

HP 5DX Structural Process Test System

Improper use of Diagnostic Software Tool

Situation:

There has been improper use of the Diagnostic Software Tool "HVXRAY.EXE". "HVXRAY -S" is a diagnostic tool and is only to be used as a monitor for the X-ray Tube parameters or diagnosing a failed X-Ray Tube. Using this tool as a normal means of ramping up the high voltage for the X-ray Tube can cause damage to the High Voltage Subsystem or X-ray Tube.

Solution:

Use " xrayon " or " xrayoff ' to ramp up or ramp down the High Voltage Subsystem.

DATE: September 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR: ENTITY:		ADDITIONAL INFORMATION:
SM 0982		

HEWLETT® **PACKARD**