bus

Agilent 75000 SERIES B

Agilent E1344A 16-Channel Relay Multiplexer Module

Operating Note

Agilent Technologies

Operating Note

Important Driver Information

In order for the Agilent E1344A 16-Channel Relay Multiplexer Module to operate correctly with an Agilent E1326 Multimeter in an Agilent E1300/E1301 Mainframe or with an Agilent E1306 Command Module, you need to use the new Downloadable Drivers for the multimeters.

For more information on how to download the drivers, refer to the *Installing SCPI Device Drivers* Installation Note that came with the drivers. The note has information on computer connections and running the programs.