Conceptual figure of 6 Vector Masking operation

Hue

Basic arrangement (Masking parameter OFF)

Parameter **M_HUE** is changed.

R <=> M
is expand equally.

Y <=> R
does not change.

M <=> B
is
contracted
equally.

G <=> Y
does not change.

B <=> C
does not change.

C <=> G
does not change.

Conceptual figure of 6 Vector Masking operation

Saturation

Basic arrangement (Masking parameter OFF)

parameter **M_SAT** ic changed.

It is expand in the direction of M.

Y <=> R does not change.

G <=> Y does not change.

C <=> G does not change.

B <=> C does not change.

It is expand in the direction of M.