Index

Index

A

Acquisition Memory, 2-3, 2-4, A-1
  increasing it by combining channels, 2-1
Acquisition Modes, A-1
Acquisition Status, 2-12
Acquisition Summary, 2-8
ActiveDSO, 5-1, 5-3, 5-13
ActiveX, 2-11, 5-13, 5-18
ADC (Analog–to–Digital Converter), 2-1, 2-3, 2-5
All, 5-10
Altitude, A-5
Amplifier, 2-3
Amplitude, C-5
API, 5-21
Area, C-5
Auto, 5-6
AUTO, 2-8
Auto-Calibration, A-5
Average, D-5

B

Bandwidth, 2-4, A-1
Bandwidth Limiter, A-1
Base, C-1, C-2, C-5
Block Diagram, 2-2

C

Cables, 4-1
Calibration, A-5
Centroids, C-1
Channel, 5-7, 5-11
Channels, 2-6, 2-12, A-1
Cleaning and Maintenance, 3-3
Clear, 5-10
Clock, A-2
Clock Edge, C-4
Combining Channels, 2-1
Command Panel, 5-10
Conformity, 3-1, A-5
Connections, 4-1
Cursors, A-4
Cycles, C-5
  in parameter measurements, C-2
Cyclic Mean, C-5
Cyclic Median, C-5
Cyclic Parameters, C-3
Cyclic Root Mean Square, C-5
Cyclic Standard Deviation, C-6

D

Data, C-6
Data density, C-1
Data Transfer
  for speed, D-1
DC Accuracy, A-1
Delay, 5-6, C-6
DELAY, 2-8
Differential Time Measurements, C-3
Digitizers, A-1
Display + Utility, 5-9
Dual Screen, 5-9
Duration, C-7
Duty, C-7

E

Ethernet, 2-1, 2-4, 2-11
  Address, 4-1, 4-2
  connecting to, 4-1
  connecting via, 4-1, 4-4
Ethernet Port, 2-13
External Reference, A-2
External Reference Clock In, 2-12
External Reference Clock Out, 2-12
External Trigger In, 2-12

F

Fall, C-2
Fall 80–20 %, C-7

Fall at Level, C-7
Fall time, C-2, C-7
FFT (Fast Fourier Transform), 2-10, D-3
Find, 5-7
First, C-8
Frequency, C-8
Frequency Domain, 2-10
Frequency Range, A-1
Front Panel, 2-12
Fuses, 3-3

G

Grid, 5-9

H

H Mag, 5-8
Histograms, 2-10, A-4, C-1
Humidity, 3-1
Hysteresis, C-4

I

Input Coupling, A-1
Interfacing, A-5
IP Address, 4-1, 4-2, 4-3, 4-4, 5-16, 5-20, 5-21
  resetting it, 4-7

L

Last, C-8
Leading Edge, C-2
LEVEL, 2-8

M

Maintenance, 1-2
Maximum, C-8
Maximum Input, A-1
Maximum Sample Rate, A-1
Mean, C-8
Median, C-8
Memories, 2-1, 2-3
Memory Length, 2-4
Mesial, C-2
Minimum, C-9

N

NET_CON, 5-2, 5-21, B-1
Network
  connection, 4-6
Norm, 5-6
NORM, 2-8

O

Offset (V), 5-7
Offset Range, A-1
OLE, 5-13
Operating Environment, 3-1, A-5
Over-, C-9
Over +, C-9
Overload, 3-3
Overvoltage, 3-1

P

Packing and Shipment, 1-3
Parameters, C-1, C-5, C-6, C-7, C-8, C-9, C-10, C-11
PC
  configuring it, 4-2
  connecting to, 4-1, 4-4
  operational requirements, 4-1
Peak–to–Peak, C-9
Period, C-9
Persistence, 5-9
Phase, C-9
Points, C-9
Pollution Degree, 3-1
Position scroll bar, 5-8
Post-Trigger, 2-8
Power, 3-3

Power On/Off, 2-12, 2-13
Pre-Trigger, 2-8
Processing Functions, A-4
Processor, 2-3
Processors, 2-1
Pulse Parameters, 2-9

R

RAM, 2-3
  amount needed for
    LSA1000, 4-1
Rear Panel, 2-12
Remote LSA, 2-11, 5-1, 5-3, 5-5, 5-11
Reply, 5-10
Reset, 5-8
Return, 1-3
Rise, C-2
Rise 20–80 %, C-10
Rise at Level, C-10
Rise time, C-2, C-10
Root Mean Square (rms), C-2, C-11

S

Safety, 3-1
Sample rate
  increasing it by combining
    channels, 2-1
Sample Rate, 2-4
Sample size, 5-6
Scale Factors, A-1
ScopeExplorer, 4-7, 5-1, 5-3, 5-19
Select, 5-7
Sensitivity, A-1
Service and Repair, 1-2
Set Math, 5-8
Single-Shot Acquisition, 2-5
Single-Shot Mode, 2-8
Size, A-5
Slope, 5-6
Sngl, 5-6
SNGL, 2-8
Software Tools
  examples of their use, D-1
Source, 5-6
Source Code
  NET_CON, B-1
Standard Deviation, C-11
Standard Parameters, C-1
Statistical Domain, 2-10
Stop, 5-6
System Memory, 2-3

T

TCP, 4-2, 4-3, 4-4, 5-21
TCP/IP, 2-11, 5-3, 5-16, 5-21
Temperature, 3-1
  LSA1000 Series, A-5
Time at Level, C-11
Time Domain, 2-10
Time intervals, C-2
Time Parameter measurements,
  C-2
TIME/DIV, 2-8
Time/Div., 5-6
Timebase + Trigger, 5-6, 5-11
Top, C-1, C-2, C-11
Trace On/Off, 5-7, 5-8
Trailing Edge, C-2
Trending, A-4
Trigger, 2-6
  Amplitude, 2-7
  Coupling, 2-6
  Level, 2-6, 2-8
  Range, 2-7
  Slope, 2-6
  Source, 2-6, 2-8
Trigger Coupling, A-3
Trigger Delay, 2-8, A-3
Trigger Maximum Input, A-3
Trigger Modes, 2-8
Trigger Range, A-3
Trigger Slope, A-3
Triggering, A-3

U

UBS Port, 2-13
Utility, 5-9

V

V Mag, 5-8
Vertical Resolution, A-1
VICP (Versatile Instrument Control Protocol, 2-11

W

Warnings, 3-2
Warranty, 1-1, A-5
Waveform Math, 2-9
Waveform Processing
  Averaging, D-5
  FFT, D-3
  pulse parameters, D-2
Weight, A-5
Width, C-11
Windows, 4-1, 4-4, 5-3, 5-21
WinSock, 5-21

Z

Zoom + Math, 5-8

Index