SASTracer/Trainer Version 2.02 Release Notes

IMPORTANT: This release of SASTracer software supports the new SASTracer analyzer and SASTrainer Exerciser option designed for the UPAS 10000. Changing the SASTracer configuration from analyzer only to SASTrainer Exerciser option requires updating the SASTracer BusEngine. Each time you exchange plugin modules, the software will automatically update the BusEngine and Firmware to the appropriate release when you click the record button in the SASTracer application.

This release also contains the following components, which are necessary for SASTracer/Trainer Analyzer & Exerciser to function correctly with this release:

- CATC SASTracer Firmware Version 2.07
- CATC SASTrainer Exerciser Firmware Version 2.07
- Analyzer only (Pod PN#SAS001MA & PN#SAS002MA) BusEngine Version 1.11
- Analyzer plus Exerciser (Pod PN#SAS001MG) BusEngine Version 2.21

Changes in SASTracer version 2.02

- Fixing some problems with connecting to certain SATA drives

Additional Notes about SASTracer version 2.02

- Several bugs fixed and performance improvements added