UPT Version 1.20 Release Notes

This release includes the following:

- If get hub descriptor failed, will try again with descriptor id=0x29. This should fix problems of not finding any ports in certain systems.
- Copyright message changed from '1999' to '1999-2001'