Chapter 7

Service Accessories

AMENDMENT RECORD SHEET

| Amendment Number	Date	Inserted By	Comments

CONTENTS

Fast Travel Charger ACH–6E

Product Code

      Fast Travel Charger ACH–6E: 0675084

View of ACH–6E

Service Adapter JBT–8

The Service Adapter JBT–8 serves as a test and service platform for the RPE–1 transceiver card.

Product Code

Service Adapter JBT–8:   0770099

View of JBT–8

Baseband Fixed Supply

LAPTOP

ACH-6

JBT-8

RPE-1

Baseband Test

LAPTOP

ACH-6

Jumper

PCS-1

JBT-8

S4

S3

RPE-1

Lab-power
supply

Antenna Cable XRP–1

Product Code

       Antenna Cable XRP–1:   0730124

View of XRP–1

MBUS Cable DAU–9P

Product Code

       MBUS Cable DAU–9P: 0730109

View of DAU–9P

Power Connector PCS–1

Suitable adapter between JBT–8 and the power supply.

Product code

Power Connector PCS–1:   0730012

View of PCS–1

S0730012

Service Cable SCH–5

System cable SCH–5 is a cable between the service adapter and the Flash security box. SCH–5 allows data to be transferred to and from the transceiver.

Product Code

System Cable SCH–5:   0730098

View of SCH–5

Flash Security Box TDF–4

Product Code

      Flash Security Box TDF–4:   0770106

View of TDF–4

Cable Assembly AXS–4

To connect the Flash Security Box TDF–4 to the computer.

Product Code

Cable Assembly AXS–4:   0730090

View of AXS–4

SW Security Device PKD–1

SW security device is a piece of hardware enabling the use of the service software when connected to the parallel (LPT) port of the PC. Whitout the dongle present it is not possible to use the service software. Printer or any such device can be connected to the PC through the dongle if needed.

Caution: Make sure thet you have switched off the PC and the printer before making connections!

Caution: Do not connected the PKD–1 to the serial port. You may damage your PKD–1!

Product Code

SW Security Device PKD–1:   0750018

View of SW Security Device

G0750018

This page intentionally left blank.