

*IC6704 is not supplied in the form of an individual part.When replacing,be sure to replace the

B

A

1

2