

ure to replace the digital p.c.b.and not IC6704 singly.