
CN3
RJS1A7105T
SW1
SW2
*SW3
SW4
GND
* SW3
RAJ2713
RAJ2719
X (Jumper)
SW1
ESE11SH2
SW1
RESET
SW
MT1
TRAVERSE
MOTOR
LAND1
LAND2
IC3
FOCUS, TRACKING COIL DRIVE/
LOADING, SPINDLE, TRAVERESE MOTOR DRIVE
BA6795FPE2
IC3
MT2
SPINDLE
MOTOR
SPR
SPB
CN4
RJP2G17ZA
MT3
LOADING
MOTOR
LOADING.M
IC4
CD SYSTEM
CONTROL
IC4
C2BBD000218
RAJ2719 only
2SD1819A-TX
Q102
Q101
2SD1819A-TX
CN2
RJS1A7114T
GND
OUT. R
A. GND
OUT. L
+5V
ACC
C1
DATA
C2
+B5V
RST
P. GND
D. MUTE
+7. 5V
CN1
RJS2A1816T
Vcc
F
E
LD
LDGND
GND
NB
GND
NA
Vref
LPD
GND
T-
T+
F-
F+
TRACKING-COIL
FOCUS-COIL
IC1
AN88355BE1V
IC1
SERVO AMP
IC2
MN6627481RPM
IC2
SERVO PROCESSOR/
DIGITAL SIGNAL PROCESSOR/
DIGTAL FILTER/
D/A CONVERTER
Q1
2SA1037AKTXR
40nS, 2V/DIV
2uS, 2V/DIV
2mS, 2V/DIV
1.0uS, 2V/DIV
20nS, 2V/DIV
5V