SONY

Hi-Fi Products

Service Bulletin

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey, 07656

Model: D4

No. 97

Subject: Reference Number Is Incorrectly Listed In The Service Manual

Date: January 19, 1990

Symptom:
(**)

The Part Number for Reference Number 904 is not listed in the service manual. Reference 904 should be listed as Reference 903. Reference 903 should be 902.

Solution: Please update your service manual to include these corrections.

Ref. No.		Description	Part Number
Incorrect	Correct		
904	903	Control PC Board	1-625-771-11
903	902	LED PC Board	1-626-480-11



Reference: FPR K0665

PRINTED IN U.S.A.
CSA-131289-1