Hi-Fi Products

Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

CSA-13

Model: STR-GX700ES

No.   468

Subject: **Unit goes into Protection when Powered On**

Date: February 15, 1996

Symptom:

(**)   The unit will go into protection when it is powered on.

Solution: Add missing jumper wire, JW623 on the Amp Board. The See diagram below