VESTEL
ELEKTRONİK A.Ş ORGANİZE SANAYİ BÖL.MANİSA/ TURKEY

PRODUCT CONTENT CHANGE BULLETIN

REF NO
UMB - 1212

CHANGE REQUEST

EXPLANATION:

Vestel will use 11AK19Y11 PCB instead of 11AK19Y12 PCB, for all products with 11AK19Y12 PCB. The reason of change is to unite the pcb mould in 11AK19Y11 and 11AK19Y12. There is no layout change. The only difference between 11AK19Y12 PCB and 11AK19Y11 PCB is the holes of the FBT feet.

APPLICATION REQUEST DATE	* IMMEDIATELY ☒	* RUNNING CHANGE ☐

AFFECTED PRODUCTS :
All products with 11AK19Y12 PCB (21" RF JVC models)

ADD. LIST ☐

COMPONENTS OUT

No	PCB Code / Pic. No	VESTEL Code	Description	Position	Amount
1		30016884	PCB 11AK19Y12		1
2					
3					
4					
5					
6					
7					
8					
9					
10					

COMPONENTS IN

No	PCB Code / Pic. No	VESTEL Code	Description	Position	Amount
1		30016433	PCB 11AK19Y11		1
2					
3					
4					
5					
6					
7					
8					
9					
10					

COMPONENT IN	ALTERNATIVES FOR COMPONENTS IN		EXIST ☐ NOT EXIST ☒
	COMPONENT IN	ALTERNATIVE	DIFFERENCE COMP.
			ADD. LIST ☐

RESPONSIBLE ENGINEER	App. Eng. Manager Approval	FINAL NOTES
NAME SURNAME / SIGNATURE DATE/TIME ONUR DAĞTEKİN 04.12.2001-12-04	SIGNATURE BEYHAN DAĞITAN	