ENGINEERING CHANGE NOTICE

NO. 963 SHEET 1 OF 1

DATE RELEASED: 9/6/79

APPROVED:

PROJ. ENG. [signature]

CHIEF ENG. [signature]

STAGE OF PRODUCTION AFFECTED

Per Purchasing department schedule

ASSEMBLIES AFFECTED

2002A Sweep Generator

EXPLANATION OF CHANGE:

The 2002A Sweep Generator is to be built ~~with~~ Weinschel Attenuator 3010-52-0003 instead of the Allen Attenuator 3010-52-0001.

This requires a new output cable (2 3/8" long - 1217-90-0038) in place of 1217-90-0026. (Jim McGovern to bend cable on fixture.)

A new pot bracket (1410-00-9950) in place of (1410-00-8940) and new front panel artwork (FPD-51-2) in place of FPD-51-1.

PARTS TO BE ADDED			PARTS TO BE DELETED			PARTS LISTS AFFECTED (USE SYSTEM NOS.)
REF DES	QTY	SYSTEM PART NO.	REF DES	QTY	SYSTEM PART NO.	
None	1	1217-90-0038	None	1	1217-90-0026	1010-00-0141
None	1	1410-00-9950	None	1	1410-00-9940	1118-00-0018
A1	1	3010-52-0003	A1	1	3010-52-0001	1118-00-0018