READ ME FIRST: NI-VXI™ FOR WINDOWS DRIVER PATCH AND PCI-MXI™-2 DOCUMENTATION LOCATION

The PCI-MXI-2 Universal board requires a special patch to the NI-VXI for Windows driver. **You must install this patch before using the PCI-MXI-2 Universal board**. You can find the patch at the following location:

```
ftp://ftp.ni.com/support/vxi/drivers/pcimxi2/
win2000_nt_me_98/3.2.2_patch/
```

Your PCI-MXI-2 Universal board kit does not include documentation. For installation and configuration information, refer to the *MXI-2 Configuration Reference Manual* and the getting started manual for your board. You can download these documents by clicking on **Product Manuals** at `ni.com/documents/`.

To obtain the Declaration of Conformity for your product, click **Declaration of Conformity** at `ni.com/hardref.nsf/`. This Web site lists the DoCs by product family. Select the appropriate product family, followed by your product, and a link to the DoC appears in Adobe Acrobat format. Click the Acrobat icon to download or read the DoC.

NATIONAL INSTRUMENTS™