## READ ME FIRST

# NI-VXI 3.3.1 for Windows Driver Patch

If a VXI-1394 or VXI-834x remote VXI controller is used in combination with other NI hardware products on the same PC, upgrade to NI-VXI 3.3.1 to prevent conflicts between NI-VXI and other National Instruments device drivers. You can search for the following KnowledgeBase article on `ni.com` for more information:

KnowledgeBase **33KAACF7**: *After Upgrading Various Drivers, My VXI-1394 or VXI-834x (MXI-3) Controller Stops Working*

You can find the updated NI-VXI driver linked through the KnowledgeBase listed above or at the following location:

`ftp://ftp.ni.com/support/vxi/drivers/pcimxi2/win2000_nt_me_98/3.3.1/`

NATIONAL INSTRUMENTS™

MXI™, National Instruments™, NI™, ni.com™, and NI-VXI™ are trademarks of National Instruments Corporation. Product and company names mentioned herein are trademarks or trade names of their respective companies. For patents covering National Instruments products, refer to the appropriate location: **Help»Patents** in your software, the `patents.txt` file on your CD, or `ni.com/patents`.

© 2004 National Instruments Corp. All rights reserved.

323791A-01 Jan04