NI Networking Protocol and Windows XP SP2 Firewall Note to Users

The current networking technology (Logos) included in National Instruments products is incompatible with the firewall included in Service Pack 2 of the Microsoft Windows XP operating system. In order for networking to function correctly, the firewall must be disabled. For more information on this issue, visit the National Instruments Web site at ni.com/info and enter the info code exnj38.

ni.com

NATIONAL INSTRUMENTS