NI PXI-1052 Front Rack Mount Kit

To mount the NI PXI-1052 in an instrument rack, complete the following steps.

| 1 | Mounting Bracket | 3 | Bottom Feet | 5 | Side Handle |
| 2 | Side Feet | 4 | COA Label Plate | 6 | M4 × 8 Flathead Screw (Qty. 6) |

Figure 1. NI PXI-1052 in Rack Mount Configuration

1. Remove the side feet, bottom feet, side handle, and COA label plate as required from the NI PXI-1052 chassis.

2. Install the mounting brackets onto each side of the chassis using the M4 × 8 flathead screws supplied. Notice that you can recess the chassis in the cabinet rack at .5 in. increments.

3. Install the chassis in the instrument rack using four screws (not supplied).

NATIONAL INSTRUMENTS™

371036A-01   Apr04