



cotes non tolérancié =  $\pm 1$   
 Toutes soudures = Mig 131  
 $a = 4$   
 Soudures plates, mené.  
 Boulonnerie jointe d'inox.

3	2	GUIDE	E24	PN 30
2	2	PLATINE	E24	120x4
1B	1	TUBULURE	E24	90x3
1A	2	TUBULURE	E24	90x3
REP	NB	DESIGNATION	MATIERE	OBSERVATION

SUPPORT DE MAT  
 ECHELLES 1/2 - 1/10