

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

SEE DN55 NOTICE LETTER FOR APPLICABLE LAST TIME BUY TERMS, CONDITIONS AND CODE DEFINITIONS FOR THESE DISCONTINUED PRODUCTS.

FOR ADDED INFORMATION REFER TO PHILIPS WEB-SITE "<http://www.semiconductors.philips.com/eol>

TYPE CODE:

T = Type number fully withdrawn
N = Part type package option only withdrawn

CODE:

C = Customer Specific Product
M = Multiple Source Product
S = Sole Source Product

AVAILABILITY CODE:

1 = Non-availability. No last time buy possible
2 = Limited availability (check with your usual sales contact)
3 = Standard availability

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
1	1N914B		SWITCHING DIODES	933029610113	T	M	3	31-Dec-05	30-Jun-06	1N4448	direct replacement. Consult Marketing.
2	1N914B		SWITCHING DIODES	933029610133	T	M	3	31-Dec-05	30-Jun-06	1N4448	direct replacement. Consult Marketing.
3	1N914B		SWITCHING DIODES	933029610143	T	M	3	31-Dec-05	30-Jun-06	1N4448	direct replacement. Consult Marketing.
4	1PS59SB21		S.S. SCHOTTKY DIODES	934054916115	T	M	3	31-Dec-05	30-Jun-06	BAT721	Standard Discontinuation. same function in similar package. Consult Marketing.
5	1PS89SB74		SCHOTTKY BARRIER DIODE	934056235115	T	M	3	31-Dec-05	30-Jun-06	BAS70-04W	Standard Discontinuation. Same function in different package. See Replacement. Consult Marketing.
6	74ABT162240DGG	BT162240 DGG	MB/ABT16	935213370112	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
7	74ABT162240DGG	BT162240 DGG	MB/ABT16	935213370118	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
8	74ABT162240DGG		MB/ABT16	935213370512	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
9	74ABT162240DGG		MB/ABT16	935213370518	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
10	74ABT162240DL	BT162240 DL	MB/ABT16	935213360112	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
11	74ABT162240DL	BT162240 DL	MB/ABT16	935213360118	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
12	74LV4799SD		LV/HC-MOS	935156120118	T	S	1	30-Jun-05	30-Jun-05	74LV4799N, 74LV4799D, 74LV4799DB & 74LV4799PW	Non-Manufacturable. New version available. See replacement part types. Consult Marketing.
13	AU5232D		MATCHED DUAL LOW VOLTAGE OP A	935272147112	T	S	2	30-Mar-06	30-Jun-06	AU5232D/01	Limited Supply. See Replacement. Albuquerque die transferred to ASMC. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
14	AU5232D		MATCHED DUAL LOW VOLTAGE OP A	935272147118	T	S	2	30-Mar-06	30-Jun-06	AU5232D/01	Limited Supply. See Replacement. Albuquerque die transferred to ASMC. Consult Marketing.
15	AU5232N		MATCHED DUAL LOW VOLT OP AMP	935272148112	T	S	2	30-Mar-06	30-Jun-06	AU5232N/01	Limited Supply. See Replacement. Albuquerque die transferred to ASMC. Consult Marketing.
16	AU7555D	AU7555 D	LINEAR INDUSTRIAL	933995370602	T	S	1	30-Jun-05	30-Jun-05	AU7555D/01	Non-Manufacturable. Albuquerque die transferred to MOS2. See Replacement. Consult Marketing.
17	AU7555D	AU7555 D	LINEAR INDUSTRIAL	933995370118	T	S	2	30-Mar-06	30-Jun-06	AU7555D/01	Limited Supply. Albuquerque die replaced by MOS2 die. See Replacement. Consult Marketing.
18	BAS221/A		General purpose diode	934058859115	T	S	2	31-Mar-06	30-Jun-06	none	Limited Supply. Consult Marketing.
19	BAS221/A		General purpose diode	934058859135	T	S	2	31-Mar-06	30-Jun-06	none	Limited Supply. Consult Marketing.
20	BAS240		SCHTTKY BARRIER DIODE	934055783115	T	S	3	31-Mar-06	30-Jun-06	1PS76SB40	Standard Discontinuation. Same function in different package. See Replacement. Consult Marketing.
21	BB145C		VCO VARICAP	934056505115	T	M	3	31-Dec-05	30-Jun-06	None	Standard Discontinuation. No replacement available. Consult Marketing.
22	BB147		VHF variable capacitance diode	934042250115	T	M	3	31-Dec-05	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
23	BB147		VHF variable capacitance diode	934042250135	T	M	3	31-Dec-05	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
24	BFC520		NPN 7 GHz wideband transistor	934041420115	T	M	3	31-Dec-05	30-Jun-06	BFM520	Standard Discontinuation. See Replacement. Consult Marketing.
25	BFQ34/01		NPN 4 GHz wideband transistor	933608850112	T	M	1	30-Jun-05	30-Jun-05	BFG35	Non-Manufacturable. . See Replacement.
26	BFQ68		NPN 4 GHz wideband transistor	933461190112	T	M	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
27	BGB112		BLUETOOTH MODULE	934058295518	T	S	2	30-Mar-06	30-Jun-06	BGB102	Limited Supply. See Replacement. Consult Marketing.
28	BGB201/S1		2ND GEN BLUETOOTH FULL MODULE	934058213135	T	S	1	30-Jun-05	30-Jun-05	BGB204	Non-Manufacturing. See Replacement. Consult Marketing.
29	BGB201/S2		2ND GEN BLUETOOTH FULL MODULE	934058214135	T	S	1	30-Jun-05	30-Jun-05	BGB204	Non-Manufacturing. See Replacement. Consult Marketing.
30	BGB201/S3		2ND GEN BLUETOOTH FULL MODULE	934058215135	T	S	1	30-Jun-05	30-Jun-05	BGB204	Non-Manufacturing. See Replacement. Consult Marketing.
31	BGB202/S1		BLUETOOTH SIP	934058701518	N	S	3	31-Mar-06	30-Jun-06	BGB202/S2, BGB203/1/Sxx, BGB204/1/Sxx	Standard Discontinuation. See Replacement. Consult Marketing.
32	BGO847		CATV MODULES	934055702112	T	M	3	31-Dec-05	30-Jun-06	BGO827	Standard Discontinuation. See Replacement. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
33	BGO847/SC0	CATV MODULES	934055705112	T	M	3	31-Dec-05	30-Jun-06	BGO827/SC0	Standard Discontinuation. See Replacement. Consult Marketing.
34	BUK7560-100A	100V N CHANNEL GEN 2TRE	934056278127	T	M	3	31-Dec-05	30-Jun-06	None	Standard Discontinuation. No replacement available. Consult Marketing.
35	BUK7840-55	TrenchMOS transistor	934045310115	T	M	3	31-Dec-05	30-Jun-06	None	Standard Discontinuation. No replacement available. Consult Marketing.
36	BUK9006-55A	> 30V N CHANNEL TRENCHFET	934057963005	T	M	1	30-Jun-05	30-Jun-05	OP546/B	Non-Manufacturable. See Replacement. Consult Marketing.
37	BUK9120-48TC	TOPFET 9	934054967118	T	M	3	31-Dec-05	30-Jun-06	None	Standard Discontinuation. No replacement available. Consult Marketing.
38	BUK92150-55	TrenchMOS transistor	934054960118	T	M	3	31-Dec-05	30-Jun-06	BUK92150-55A	Standard Discontinuation. See Replacement. Consult Marketing.
39	BUK9508-55	TrenchMOS transistor	934045190127	T	M	3	31-Dec-05	30-Jun-06	BUK9508-55B	Standard Discontinuation. See Replacement. Consult Marketing.
40	BUK9560-100A	100V N CHANNEL GEN 2TRE	934056279127	T	M	3	31-Dec-05	30-Jun-06	None	Standard Discontinuation. No replacement available. Consult Marketing.
41	BUK9618-55	TrenchMOS transistor	934045290118	T	M	3	31-Dec-05	30-Jun-06	BUK9618-55A	Standard Discontinuation. See Replacement. Consult Marketing.
42	BYQ40EW-200	LV EPITAXIAL RECTIFIER	934055374127	T	M	3	31-Dec-05	30-Jun-06	None	Standard Discontinuation. No replacement available. Consult Marketing.
43	CBT3253D	CBT3253	935272583112	T	M	2	30-Dec-05	30-Jun-06	CBT3253AD	Limited Supply. See Replacement. Consult Marketing.
44	CBT3253D	CBT3253	935272583118	T	M	2	30-Dec-05	30-Jun-06	CBT3253AD	Limited Supply. See Replacement. Consult Marketing.
45	CBT3253DB	CBT3253	935272581112	T	M	2	30-Dec-05	30-Jun-06	CBT3253ADB	Limited Supply. See Replacement. Consult Marketing.
46	CBT3253DB	CBT3253	935272581118	T	M	2	30-Dec-05	30-Jun-06	CBT3253ADB	Limited Supply. See Replacement. Consult Marketing.
47	CBT3253DS	CBT3253	935272580112	T	M	2	30-Dec-05	30-Jun-06	CBT3253ADS	Limited Supply. See Replacement. Consult Marketing.
48	CBT3253DS	CBT3253	935272580118	T	M	2	30-Dec-05	30-Jun-06	CBT3253ADS	Limited Supply. See Replacement. Consult Marketing.
49	CBT3253PW	CBT3253	935272579112	T	M	2	30-Dec-05	30-Jun-06	CBT3253APW	Limited Supply. See Replacement. Consult Marketing.
50	CBT3253PW	CBT3253	935272579118	T	M	2	30-Dec-05	30-Jun-06	CBT3253APW	Limited Supply. See Replacement. Consult Marketing.
51	CBT3257D	CBT3257	935272331112	T	M	2	30-Dec-05	30-Jun-06	CBT3257AD	Limited Supply. See Replacement. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments	
52	CBT3257D		CBT3257	935272331118	T	M	2	30-Dec-05	30-Jun-06	CBT3257AD	Limited Supply. See Replacement. Consult Marketing.
53	CBT3257DB		CBT3257	935272332112	T	M	2	30-Dec-05	30-Jun-06	CBT3257ADB	Limited Supply. See Replacement. Consult Marketing.
54	CBT3257DB		CBT3257	935272332118	T	M	2	30-Dec-05	30-Jun-06	CBT3257ADB	Limited Supply. See Replacement. Consult Marketing.
55	CBT3257DS		CBT3257	935272333112	T	M	2	30-Dec-05	30-Jun-06	CBT3257ADS	Limited Supply. See Replacement. Consult Marketing.
56	CBT3257DS		CBT3257	935272333118	T	M	2	30-Dec-05	30-Jun-06	CBT3257ADS	Limited Supply. See Replacement. Consult Marketing.
57	CBT3257PW		CBT3257	935272330112	T	M	2	30-Dec-05	30-Jun-06	CBT3257APW	Limited Supply. See Replacement. Consult Marketing.
58	CBT3257PW		CBT3257	935272330118	T	M	2	30-Dec-05	30-Jun-06	CBT3257APW	Limited Supply. See Replacement. Consult Marketing.
59	CBT3857PW	CBT3857PW DH	10 BIT FET BUS SWITCH	935263050112	T	M	2	30-Dec-05	30-Jun-06	None	Limited Supply. Consult Marketing.
60	CBT3857PW	CBT3857PW DH	10 BIT FET BUS SWITCH	935263050118	T	M	2	30-Dec-05	30-Jun-06	None	Limited Supply. Consult Marketing.
61	CE1619D		AUTO CUSTOM ASIC	935183480512	T	S	2	30-Mar-06	30-Jun-06	None	Limited Supply. Consult Marketing.
62	CE1619D		AUTO CUSTOM ASIC	935183480518	T	S	2	30-Mar-06	30-Jun-06	None	Limited Supply. Consult Marketing.
63	CE1639N	CE1639 N	AUTO CUSTOM ASIC	935204680112	T	C	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
64	CE1667N	CE1667 N	AUTO CUSTOM ASIC	935200290112	T	C	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
65	ICM7555CD	ICM7555C D	LINEAR INDUSTRIAL	933975610602	T	M	1	30-Jun-05	30-Jun-05	ICM7555CD/01	Non-Manufacturable. Albuquerque die replaced by MOS2 die. Consult Marketing.
66	ICM7555CD	ICM7555C D	LINEAR INDUSTRIAL	933975610623	T	M	2	30-Dec-05	30-Jun-06	ICM7555CD/01	Limited Supply. Albuquerque die replaced by MOS2 die. See Replacement. Consult Marketing.
67	ICM7555CN	ICM7555C N	LINEAR INDUSTRIAL	933975600602	T	M	1	30-Jun-05	30-Jun-05	ICM7555CN/02	Non-Manufacturable. Albuquerque die replaced by MOS2 die. Consult Marketing.
68	ICM7555ID	ICM7555I D	LINEAR INDUSTRIAL	933975630602	T	M	2	30-Dec-05	30-Jun-06	ICM7555ID/01	Limited Supply. Albuquerque die replaced by MOS2 die. See Replacement. Consult Marketing.
69	ICM7555ID	ICM7555I D	LINEAR INDUSTRIAL	933975630623	T	M	2	30-Dec-05	30-Jun-06	ICM7555ID/01	Limited Supply. Albuquerque die replaced by MOS2 die. See Replacement. Consult Marketing.
70	ICM7555IN	ICM7555I N	LINEAR INDUSTRIAL	933975620602	T	M	2	30-Dec-05	30-Jun-06	ICM7555IN/01	Limited Supply. Albuquerque die replaced by MOS2 die. See Replacement. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
71	ISP1160BD/01/CP2146	USB1.1 HOST CONTROLLER	935273998118	T	C	3	31-Mar-06	30-Jun-06	ISP1160BD/01	Standard Discontinuation. See Replacement.
72	ISP1160BD/01/CP2146	USB1.1 HOST CONTROLLER	935273998151	T	C	3	31-Mar-06	30-Jun-06	ISP1160BD/01	Standard Discontinuation. See Replacement.
73	ISP1160BD/01/CP2146	USB1.1 HOST CONTROLLER	935273998157	T	C	3	31-Mar-06	30-Jun-06	ISP1160BD/01	Standard Discontinuation. See Replacement.
74	ISP1181ABS/CP2142	16 BIT USB DEVICE CONTROLLER	935272814518	T	S	3	31-Mar-06	30-Jun-06	ISP1181ABS / ISP1181BBS	Standard Discontinuation. See Replacement. Consult Marketing.
75	ISP1181ABS/CP2142	16 BIT USB DEVICE CONTROLLER	935272814557	T	S	3	31-Mar-06	30-Jun-06	ISP1181ABS / ISP1181BBS	Standard Discontinuation. See Replacement. Consult Marketing.
76	ISP1362EE/01	ISP1362EE	935275038518	T	S	3	31-Mar-06	30-Jun-06	ISP1362EE	Standard Discontinuation. See Replacement. Consult Marketing.
77	ISP1362EE/01	ISP1362EE	935275038551	T	S	3	31-Mar-06	30-Jun-06	ISP1362EE	Standard Discontinuation. See Replacement. Consult Marketing.
78	ISP1362EE/01	ISP1362EE	935275038557	T	S	3	31-Mar-06	30-Jun-06	ISP1362EE	Standard Discontinuation. See Replacement. Consult Marketing.
79	ISP1520BD/CP2151	ISP1520	935274446118	T	C	3	31-Mar-06	30-Jun-06	ISP1520BD	Standard Discontinuation. See Replacement. Consult Marketing.
80	ISP1520BD/CP2151	ISP1520	935274446151	T	C	3	31-Mar-06	30-Jun-06	ISP1520BD	Standard Discontinuation. See Replacement. Consult Marketing.
81	ISP1520BD/CP2151	ISP1520	935274446157	T	C	3	31-Mar-06	30-Jun-06	ISP1520BD	Standard Discontinuation. See Replacement. Consult Marketing.
82	ISP1521BE/CP2148	ISP1521	935274237518	T	S	3	31-Mar-06	30-Jun-06	ISP1521BE	Standard Discontinuation. See Replacement. Consult Marketing.
83	ISP1521BE/CP2148	ISP1521	935274237551	T	S	3	31-Mar-06	30-Jun-06	ISP1521BE	Standard Discontinuation. See Replacement. Consult Marketing.
84	ISP1521BE/CP2148	ISP1521	935274237557	T	S	3	31-Mar-06	30-Jun-06	ISP1521BE	Standard Discontinuation. See Replacement. Consult Marketing.
85	ISP1581BD/CP2145	USB2.0 DEVICE CONTROLLER	935273653518	T	S	3	31-Mar-06	30-Jun-06	ISP1581BD	Standard Discontinuation. See Replacement. Consult Marketing.
86	ISP1581BD/CP2145	USB2.0 DEVICE CONTROLLER	935273653557	T	S	3	31-Mar-06	30-Jun-06	ISP1581BD	Standard Discontinuation. See Replacement. Consult Marketing.
87	ISP1581BD/CP2152	USB2.0 DEVICE CONTROLLER	935274516518	T	C	3	31-Mar-06	30-Jun-06	ISP1581BD	Standard Discontinuation. See Replacement. Consult Marketing.
88	ISP1581BD/CP2152	USB2.0 DEVICE CONTROLLER	935274516557	T	C	3	31-Mar-06	30-Jun-06	ISP1581BD	Standard Discontinuation. See Replacement. Consult Marketing.
89	LP2985AB-28UK	LDO REGULATOR	935275008023	T	M	3	31-Dec-05	30-Jun-06	National LP2985A-28UK	Standard Discontinuation. See Replacement. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
90	MAX8878-30D	LDO REGULATOR	935272764115	T	M	3	31-Dec-05	30-Jun-06	Maxime MAX8878-30D	Standard Discontinuation. See Replacement. Consult Marketing.
91	MAX8878-33D	LDO REGULATOR	935272765115	T	M	3	31-Dec-05	30-Jun-06	Maxime MAX8878-33D	Standard Discontinuation. See Replacement. Consult Marketing.
92	MAX8878-36D	LDO REGULATOR	935272766115	T	M	3	31-Dec-05	30-Jun-06	Maxime MAX8878-36D	Standard Discontinuation. See Replacement. Consult Marketing.
93	NE5232D	MATCHED DUAL LOW VOLT OP AMP	935272100112	T	M	2	30-Dec-05	30-Jun-06	NE5232D/01	Albuquerque die transfer to ASMC. Limited Supply. Consult Marketing.
94	NE5232D	MATCHED DUAL LOW VOLT OP AMP	935272100118	T	M	2	30-Dec-05	30-Jun-06	NE5232D/01	Albuquerque die transfer to ASMC. Limited Supply. Consult Marketing.
95	NE5232N	MATCHED DUAL LOW VOLT OP AMP	935272101112	T	M	2	30-Dec-05	30-Jun-06	NE5232N/01	Albuquerque die transfer to ASMC. Limited Supply. Consult Marketing.
96	NE5234D	LINEAR INDUSTRIAL	935027390512	T	M	2	30-Dec-05	30-Jun-06	NE5234D/01	Albuquerque die transfer to ASMC. Limited Supply. Consult Marketing.
97	NE5234D	LINEAR INDUSTRIAL	935027390518	T	M	2	30-Dec-05	30-Jun-06	NE5234D/01	Albuquerque die transfer to ASMC. Limited Supply. Consult Marketing.
98	NE5234D	NE5234 D LINEAR INDUSTRIAL	935027390602	T	M	2	30-Dec-05	30-Jun-06	NE5234D/01	Albuquerque die transfer to ASMC. Limited Supply. Consult Marketing.
99	NE5234D	NE5234 D LINEAR INDUSTRIAL	935027390623	T	M	2	30-Dec-05	30-Jun-06	NE5234D/01	Albuquerque die transfer to ASMC. Limited Supply. Consult Marketing.
100	NE5234N	NE5234 N LINEAR INDUSTRIAL	935027380602	T	M	2	30-Dec-05	30-Jun-06	NE5234N/01	Albuquerque die transfer to ASMC. Limited Supply. Consult Marketing.
101	OM4028U/5/03	WAFER SERVICE	935080700015	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
102	OM4028U/5/04	WAFER SERVICE	935084020015	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
103	OM4028U/5/05	WAFER SERVICE	935180620015	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
104	OM4032U/5/F3	WAFER SERVICE	935212180015	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
105	OM4056U/5/F3	WAFER SERVICE	935205390015	T	S	3	31-Mar-06	30-Jun-06	OM4056U/5DA/3 (12NC=9352 775 07015)	Standard Discontinuation. See Replacement. Consult Marketing.
106	OM4085T/F1	OM4085T D DISPLAY DRIVERS	935232960118	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
107	OM5178HN/C3	OM5178HN	935269644118	T	C	1	30-Jun-05	30-Jun-05	UAA3537HN/C1,518	Non-Manufacturable. See Replacement. Consult Marketing. Consult Marketing.
108	OM5178HN/C3	OM5178HN	935269644518	T	C	2	30-Mar-06	30-Jun-06	UAA3537HN/C1,518	Limited Supply. See Replacement. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
109	OM5185E/C100	SECURITY CAMERA DSP	935268477518	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
110	OM5185E/C100	SECURITY CAMERA DSP	935268477551	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
111	OM5956HN/C1	OM5956HN	935274613518	T	C	2	30-Mar-06	30-Jun-06	OM5956HN/C2,518	Limited Supply. See Replacement. Consult Marketing.
112	OM6217U/2DA/1	67X96 PIXELS MATRIX LCD	935271739026	T	C	3	31-Mar-06	30-Jun-06	OM6213U/2DB/1	Standard Discontinuation. See Replacement.
113	OM6310	EVITA KIT	935272191599	T	S	3	31-Mar-06	30-Jun-06	None noted	Standard Discontinuation. Consult Marketing.
114	OM6311	DAUGHTERBOARD	935272192599	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
115	OM6312	REFERENCE DESIGN	935272193599	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
116	OM6314	PCF5213 EVALUATION KIT	935272633599	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
117	OM6315	SMCP BOARD	935272757599	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
118	OM6316	PCF5213 EVALUATION KIT	935273037599	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
119	OM6318/C/D	DRAGON FLY REF DESIGN	935275693599	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
120	OM6318/C/R	DRAGON FLY REF DESIGN	935275689599	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
121	OM6320/A/D	SYSOL ME1	935275408599	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
122	OM6320/A/R	SYSOL ME1	9352 75401 599	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
123	OM6320/B/D	SYSOL ME1	935275409599	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
124	OM6320/B/R	SYSOL ME1	935275402599	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
125	OM6357EL/3C3/5/M2	GPRS BB&BAI	935272910518	T	S	3	31-Mar-06	30-Jun-06	OM6357EL/3C3/5	Standard Discontinuation. See Replacement. Consult Marketing.
126	OM6357EL/3C3/5/M4	GPRS BB&BAI	935275396518	T	S	2	30-Mar-06	30-Jun-06	OM6357EL/3C3/5	Limited Supply. See Replacement. Consult Marketing.
127	OM6357EL/3C3/5/M5	GPRS BB&BAI	935276746518	T	S	2	30-Mar-06	30-Jun-06	OM6357EL/3C3/5	Limited Supply. See Replacement. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
128	OM6380ET/1		THIRD GENERATION GSM SMARTPHC	935271122528	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
129	OM6388EL/2		KODIAK	935276213518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
130	OM6388EL/2		KODIAK	935276213557	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
131	OM6705	OM6705 SD	CAI UNDIVIDED	935267108112	T	S	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
132	OM7101H/J77/3		DECT BASE CHIP	935272304518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
133	OM7105HL/V01/3		DECT BASE CHIP	935270262518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
134	OM7105HL/V09/3		DECT BASE CHIP	935273515518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
135	OM7106HL/W06/4		DECT BASE CHIP	935272318518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
136	OM7106HL/W09/4		DECT BASE CHIP	935273516518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
137	ON4185		NPN BROADBAND TRANSISTORS CO	933800230412	T	M	3	31-Dec-05	30-Jun-06	BFR93A	Standard Discontinuation. See Replacement.
138	ON4636		80V/100V MOSFET	934013720127	T	C	1	30-Jun-05	30-Jun-05	None	No replacement part available. Consult Marketing
139	ON5028		BU2508 DEFL.TR.FAMILY	934050710127	T	C	3	31-Mar-06	30-Jun-06	None	No replacement part available. Consult Marketing
140	ON5111		BU2508 DEFL.TR.FAMILY	934054739127	T	C	3	31-Mar-06	30-Jun-06	None	No replacement part available. Consult Marketing
141	ON5138		HIGHSIDE TOPFET 2	934055204118	T	C	1	30-Jun-05	30-Jun-05	BUK207-50Y	Non-Manufacturable. See Replacement.
142	ON5180		LOW VOLTAGE POWER MOS	934055663127	T	C	1	30-Jun-05	30-Jun-05	None	No replacement part available. Consult Marketing
143	ON5181		LOW VOLTAGE POWER MOS	934055664127	T	C	1	30-Jun-05	30-Jun-05	None	No replacement part available. Consult Marketing
144	ON5182		LOW VOLTAGE POWER MOS	934055665118	T	C	1	30-Jun-05	30-Jun-05	None	No replacement part available. Consult Marketing
145	ON5184		LOW VOLTAGE POWER MOS	934055667135	T	C	1	30-Jun-05	30-Jun-05	None	No replacement part available. Consult Marketing
146	ON5187		LOW VOLTAGE POWERMOS	934055671135	T	C	1	30-Jun-05	30-Jun-05	None	No replacement part available. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
147	ON5189	POWER MOSFET	934055710127	T	C	1	30-Jun-05	30-Jun-05	None	No replacement part available. Consult Marketing
148	ON5191	POWER TRANSISTOR	934055722127	T	C	3	31-Mar-06	30-Jun-06	None	No replacement part available. Consult Marketing
149	ON5237	TRENCH GEN 2	934056849118	T	C	1	30-Jun-05	30-Jun-05	BUK7611-55A	Non-Manufacturable. See Replacement.
150	ON5243	LIGHTING TRANSISTORS	934056968127	T	C	3	31-Mar-06	30-Jun-06	None	No replacement part available. Consult Marketing
151	OP532	30V ><60V N CHANNEL TRENCHFET	934054947005	T	C	3	31-Mar-06	30-Jun-06	None	No replacement part available. Consult Marketing
152	OP552	LIGHTING TRANSISTORS	934056932005	T	C	3	31-Mar-06	30-Jun-06	None	No replacement part available. Consult Marketing
153	OP553	LIGHTING TRANSISTORS	934056933005	T	C	3	31-Mar-06	30-Jun-06	None	No replacement part available. Consult Marketing
154	OP572	GEN PURPOSE THYRISTORS	934057937005	T	C	3	31-Mar-06	30-Jun-06	None	No replacement part available. Consult Marketing
155	OT331	4 QUADRANT TRIACS	934052600127	T	C	3	31-Mar-06	30-Jun-06	None	No replacement part available. Consult Marketing
156	OT334	GEN. PURPOSE THYRISTORS	934054640118	T	C	3	31-Mar-06	30-Jun-06	None	No replacement part available. Consult Marketing
157	OT388	4 QUADRANT TRIACS	934056814127	T	C	3	31-Mar-06	30-Jun-06	None	No replacement part available. Consult Marketing
158	P16WX064AEU/009A2W	16BIT SXA	935273355006	T	C	2	30-Mar-06	30-Jun-06	See Comments	Consult Marketing for replacement
159	P16WX064AEV/01105P	16BIT SXA	935274091118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
160	P16WX064AEV/01306S	16BIT SXA	935274234118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for Replacement.
161	P16WX064AEW/00302W	16BIT SXA	935271164005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
162	P16WX064AEW/00503W	16BIT SXA	935272415005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for replacement
163	P16WX064AEW/00604W	16BIT SXA	935272588005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for Replacement
164	P16WX064AEW/01006W	16BIT SXA	935274137005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for replacement
165	P16WX064AEW/021A6W	16BIT SXA	935278725005	T	C	2	30-Mar-06	30-Jun-06	P16WX064AEU/021A6W	Limited Supply. Consult Marketing for replacement

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
166	P5CC009EW1/T0M5906		08BIT CC	935277483005	T	C	2	30-Mar-06	30-Jun-06	P5CC009/T1D4108	Limited Supply. Consult Marketing for replacement
167	P80C32UFPN	P80C32UFP N	51 FAMILY CMOS ROML - 80C32	935255920112	T	M	3	31-Dec-05	30-Jun-06	P80C32X2FN	Standard Discontinuation. See Replacement. Consult Marketing.
168	P80C51SBBB/CV5191	CV5191 B	51 FAMILY CMOS ROM - 80C51	935269906518	T	S	3	31-Mar-06	30-Jun-06	P87C51X2BBD	Standard Discontinuation. See Replacement. Consult Marketing.
169	P80C52SBAA/CV5717	CV5717 A	51 FAMILY CMOS ROM - 80C52	935263901518	T	S	3	31-Mar-06	30-Jun-06	P87C52X2FA	Standard Discontinuation. See Replacement. Consult Marketing.
170	P80C554SBBB		P80C554SBBB	935268882157	T	S	3	31-Mar-06	30-Jun-06	P80C554SFBD	Standard Discontinuation. See Replacement. Consult Marketing.
171	P80C557E4EFB/01	P80C557E4F B	BLM - ADC	935263156551	N	S	3	31-Mar-06	30-Jun-06	See Comments	Standard Discontinuation. Bulk pack, 557, avail. Consult Marketing.
172	P80C592FFA/00/N		BLM - CAN PRODUCTS	935278393518	T	S	3	31-Mar-06	30-Jun-06	P80C592FFA/00	Standard Discontinuation. See Replacement. Consult Marketing.
173	P82CF201BDH		P82CF201	935271898518	T	S	3	31-Mar-06	30-Jun-06	P87LPC762FDH	Standard Discontinuation. See Replacement. Consult Marketing.
174	P83C528EBA/218		BLM - I2C	935243270512	T	S	3	31-Mar-06	30-Jun-06	See Comments	Standard Discontinuation. Migrate to P87C66x series. Consult Marketing.
175	P83C528EBA/278		BLM - I2C	935262147518	T	S	3	31-Mar-06	30-Jun-06	See Comments	Standard Discontinuation. Migrate to P87C66x series. Consult Marketing.
176	P83C557E2EFB/208		BLM - ADC	935269075518	T	S	3	31-Mar-06	30-Jun-06	P87C557E8EFB/01	Standard Discontinuation. See Replacement. Consult Marketing.
177	P83C557E4EFB/213		BLM - ADC	935277017518	T	S	3	31-Mar-06	30-Jun-06	P87C557E8EFB/01	Standard Discontinuation. See Replacement. Consult Marketing.
178	P83C654EBB/593		BLM - I2C	935270738557	T	S	3	31-Mar-06	30-Jun-06	P87C654X2BBD	Standard End of Life. See Replacement. Consult Marketing.
179	P83C654EFB/132		BLM - I2C	935271035518	T	S	3	31-Mar-06	30-Jun-06	P87C654X2BBD	Standard Discontinuation. See Replacement. Consult Marketing.
180	P83C754EBDDB/CV8720	CV8720 DB	83C754 SSOP	935262623518	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
181	P83C754EBDDB/CV8738		83C754 SSOP	935268073518	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
182	P83CE560EFB/047		RADIO/AUDIO/LCD/OTHER MICR.DER	935266530557	T	S	3	31-Mar-06	30-Jun-06	P87C557E8EFB/01	Standard Discontinuation. See Replacement. Consult Marketing.
183	P83CE560EFB/060		RADIO/AUDIO/LCD/OTHER MICR.DER	935270791557	T	S	3	31-Mar-06	30-Jun-06	P87C557E8EFB/01	Standard Discontinuation. See Replacement. Consult Marketing.
184	P83LPC762BD/CV8611/G		83LPC762	935277597518	T	S	3	31-Mar-06	30-Jun-06	P83LPC762BD/CV8611	Standard Discontinuation. See Replacement. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
185	P83LPC762BD/CV8619		83LPC762	935275471518	T	S	3	31-Mar-06	30-Jun-06	P87LPC762FD	Standard Discontinuation. See Replacement. Consult Marketing.
186	P83LPC762FDH/CV8616		83LPC762	935273191518	T	S	3	31-Mar-06	30-Jun-06	P87LPC762FDH	Standard Discontinuation. See Replacement. Consult Marketing.
187	P87C51FB-JA	P87C51FB-J A	C51 FAMILY OTP/EPROM-87C51FB	935258410512	T	M	3	31-Dec-05	30-Jun-06	P87C51RB2FA	Standard Discontinuation. See Replacement. Consult Marketing.
188	P87C51FC-4N	P87C51FC-4 N	51 FAMILY OTP/EPROM - 87C51FC	935253490112	T	M	3	31-Dec-05	30-Jun-06	P87C51RC2FN	Standard Discontinuation. See Replacement. Consult Marketing.
189	P87C51RB2FA		87C51RB2	935271249529	N	M	3	31-Dec-05	30-Jun-06	See Comments	Standard Discontinuation. Bulk pack, 512, avail. Consult Marketing.
190	P87C51RC2BA		87C51RC2	935272106512	T	M	3	31-Dec-05	30-Jun-06	P87C51RC2FA	Standard Discontinuation. See Replacement. Consult Marketing.
191	P87C554SBBD		87C554 QFP	935268841157	T	S	3	31-Mar-06	30-Jun-06	P87C554SFBD	Standard Discontinuation. See Replacement. Consult Marketing.
192	P87C58X2BA	P87C58X2B A	P87C58X2	935270375512	T	M	3	31-Dec-05	30-Jun-06	P87C58X2FN	Standard Discontinuation. See Replacement. Consult Marketing.
193	P87LPC762BD		P87LPC762 SO	935264003529	N	S	3	31-Mar-06	30-Jun-06	See Comments	Standard Discontinuation. Bulk pack, 512, avail. Consult Marketing.
194	P87LPC768BD		87LPC768 SO20	935267360529	N	S	3	31-Mar-06	30-Jun-06	See Comments	Standard Discontinuation. Bulk pack, 512, avail. Consult Marketing.
195	P89C52X2FA/00		MTP FLASH MCOS	935271451529	N	M	3	31-Dec-05	30-Jun-06	See Comments	Standard Discontinuation. Bulk pack, 512, avail. Consult Marketing.
196	P89C54X2BA/00		MTP FLASH MCOS	935271456512	T	M	3	31-Dec-05	30-Jun-06	P89C54X2FA	Standard Discontinuation. See Replacement. Consult Marketing.
197	P89C668HBA/00		BLM - FLASH MCU	935265418529	N	S	3	31-Mar-06	30-Jun-06	See Comments	Standard Discontinuation. Bulk pack, 512, avail. Consult Marketing.
198	P8RF5016AEV/12100B1		08BIT DIF	935272310118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
199	P8RF5016AEV/12205B1		08BIT DIF	935272234118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
200	P8RF5016AEV/128M0B1		08BIT DIF	935272810118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
201	P8RF5016AEW/12407W0		08BIT DIF	935272242005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
202	P8RF6008AEW/10303W0		08BIT DIF	935274185005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for Replacement.
203	P8WE5016AEW/00411W		08BIT CC	935270396005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
204	P8WE5016AEW/00512W		08BIT CC	935271140005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
205	P8WE5016AEW/00613W		08BIT CC	935271338005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
206	P8WE5016AEW/00714W		08BIT CC	935272254005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
207	P8WE5016AEW/02506W		08BIT CC	935267309005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
208	P8WE5017AEW/00505W		08BIT CC	935270729005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
209	P8WE5017AEW/00505WP		08BIT CC	935270849005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for replacement
210	P8WE5017AEW/00909W		08BIT CC	935271382005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
211	P8WE5017AEW/00909WP		08BIT CC	935271384005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
212	P8WE5017AEW/01010WP		08BIT CC	935271385005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
213	P8WE5017AEW/01816W		08BIT CC	935273913005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
214	P8WE5017AEW/01816WP		08BIT CC	935273956005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
215	P8WE5017AEW/040A4W		08BIT CC	935275144005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
216	P8WE5032AET/01000	CWE5032010 D	08BIT CC	935264435512	T	C	1	30-Jun-05	30-Jun-05	See Comments	Non-Manufacturable. Consult Marketing
217	P8WE5032AEV/035328I		08BIT CC	935270637118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
218	P8WE5032AEV/058AD8I		08BIT CC	935271837118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
219	P8WE5032AEW/01711W	CWE5032711 CA	08BIT SC	935267153005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
220	P8WE5032AEW/02726W		08BIT SC	935268219005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
221	P8WE5032AEW/02727W		08BIT SC	935268220005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
222	P8WE5032AEW/02930W		08BIT SC	935268632005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
223	P8WE5032AEW/05900W		08BIT SC	935272532005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for replacement
224	P8WE5032AEW/064ACW		08BIT SC	935267413005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
225	P8WE5032AEW/06708W	CWE5032708 CA	08BIT SC	935267372005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
226	P8WE5033AEV/021S28I		08BIT CC	935270804118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for replacement
227	P8WE5033AEV/022088I		08BIT CC	935270803118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for replacement
228	P8WE5033AEV/022128I		08BIT CC	935270897118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for replacement
229	P8WE5033AEV/024A18I		08BIT CC	935271824118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
230	P8WE5033AEV/025138I		08BIT CC	935272024118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
231	P8WE5033AEV/032008I		08BIT CC	935272427118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for replacement
232	P8WE5033AEW/01107W		08BIT CC	935269595005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
233	P8WE5033AEW/01502W		08BIT CC	935270183005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
234	P8WE5033AEW/03016WP		08BIT CC	935275129005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
235	P8WE5033AEW/037A4WP		08BIT CC	935275173005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
236	P8WE6004AEV/00202P		08BIT SC	935269822118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
237	P8WE6004AEV/003038I		08BIT SC	935270010118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
238	P8WE6004AEW/007A5W		08BIT SC	935272155005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
239	P8WE6004AEW/007A5WP		08BIT SC	935272156005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
240	P8WE6004AEW/007A7W		08BIT SC	935271024005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for replacement
241	P8WE6004AEW/007A8W		08BIT SC	935271025005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for replacement

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
242	P8WE6004AEW/007B1W		08BIT SC	935271796005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
243	P8WE6004AEW/007B2W		08BIT SC	935272426005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for replacement
244	P8WE6004AEW/008A3W		08BIT SC	935270811005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for replacement
245	P8WE6004AEW/009A4W		08BIT SC	935271086005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for replacement
246	P8WE6004AEW/009A4WP		08BIT SC	935271021005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for replacement
247	P8WE6008AEV/108108I		08BIT SC	935271467118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
248	P8WE6008AEV/108108R		08BIT SC	935271825118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
249	P8WE6008AEV/10810P		08BIT SC	935271365118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
250	P8WE6008AEV/10810PP		08BIT SC	935271438118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
251	P8WE6008AEW/10810W		08BIT SC	935271361005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
252	P8WE6008AEW/10810WP		08BIT SC	935271439005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
253	P8WE6017AEV/131248I		08BIT SC	935271018118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for replacement
254	P8WE6017AEV/140218I		08BIT SC	935272225118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
255	P8WE6017AEV/144028I		08BIT SC	935272044118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
256	P8WE6017AEV/144028R		08BIT SC	935272030118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
257	P8WE6017AEV/14402P		08BIT SC	935271844118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
258	P8WE6017AEV/14402PP		08BIT SC	935271842118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
259	P8WE6017AEV/15140PP		08BIT SC	935275182118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
260	P8WE6017AEW/115ABW		08BIT SC	935269266005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
261	P8WE6017AEW/13422WP		08BIT SC	935271402005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
262	P8WE6017AEW/13526WP		08BIT SC	935271403005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
263	P8WE6017AEW/13820WP		08BIT SC	935271399005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
264	P8WE6017AEW/13913WP		08BIT SC	935271401005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
265	P8WE6017AEW/14332W		08BIT SC	935272041005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
266	P8WE6017AEW/143ACW		08BIT SC	935272256005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
267	P8WE6017AEW/143ACWP		08BIT SC	935272259005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
268	P8WE6017AEW/143ADW		08BIT SC	935272257005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
269	P8WE6017AEW/143ADWP		08BIT SC	935272258005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
270	P8WE6017AEW/143G3W		08BIT SC	935277532005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing
271	P8WE6032AEV/153078I		08BIT SC	935271865118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
272	P8WE6032AEV/153078R		08BIT SC	935271823118	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing.
273	P8WE6032AEW/107A2W		08BIT SC	935271028005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for replacement
274	PCA1461U/10/F2		CLOCKS AND WATCHES	935240130005	T	S	3	31-Mar-06	30-Jun-06	PCA2000U/10AB/1 (12NC=9352 780 82005)	Standard Discontinuation. See Replacement. Consult Marketing.
275	PCA1602T/F2	PCA1602T D	CLOCKS AND WATCHES	935203670113	T	S	3	31-Mar-06	30-Jun-06	PCA2002T/1 (12NC=9352 725 69113)	Standard Discontinuation. See Replacement. Consult Marketing.
276	PCA8840L7/C/1		TFT GATE DRIVER WITH 128CH	935272288523	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
277	PCA8840L9/C/1		TFT GATE DRIVER WITH 120CH	935272857523	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
278	PCA8845M1/A/1		TFT GATE DRIVER WITH 256CH	935274924516	T	C	3	31-Mar-06	30-Jun-06	None	Non-Manufacturable. Consult Marketing.
279	PCA8851L16/C/2		TFT GATE DRIVER WITH 256CH	935272847523	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
280	PCA8851L23/C/1		TFT GATE DRIVER WITH 256CH	935273288523	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
281	PCA8900L4/G/2		384CH TFT SOURCE DRIVER	935276041523	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
282	PCA9545D/G		PCA9545	935278881118	T	S	1	30-Jun-05	30-Jun-05	PCA9545AD	Non-Manufacturable. See Replacement. Consult Marketing.
283	PCA9548D/G		PCA9548	935276417118	T	S	1	30-Jun-05	30-Jun-05	PCA9548AD	Non-Manufacturable. See Replacement. Consult Marketing.
284	PCD50914H/A39/1		DECT HANDSET CHIP	935274364518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
285	PCD50914H/A42/1		DECT HANDSET CHIP	935274688518	T	C	3	31-Mar-06	30-Jun-06	None	Non-Manufacturable. Consult Marketing.
286	PCD50914H/A50/1		DECT HANDSET CHIP	935275737518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
287	PCD50914H/A62/1		DECT HANDSET CHIP	935276545518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
288	PCD50921HL/F10/3		DECT BASEBAND 48K	935274145518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
289	PCD50923H/C61/3		DECT BASESTATION CHIP	935270722518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
290	PCD50923H/C71/3		DECT BASESTATION CHIP	935271507518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
291	PCD50923H/C72/3		DECT BASESTATION CHIP	935271801518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
292	PCD50923H/C74/3		DECT BASESTATION CHIP	935272090518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
293	PCD50923H/C83/3		DECT BASESTATION CHIP	935273050518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
294	PCD50923H/C85/3		DECT BASESTATION CHIP	935273293518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
295	PCD50923H/C89/3		DECT BASESTATION CHIP	935273494518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
296	PCD50923H/C90/3		DECT BASESTATION CHIP	935273551518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
297	PCD50923H/C93/3		DECT BASESTATION CHIP	935273711518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
298	PCD50924H/C18/1		DECT BASEBAND	935270294518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
299	PCD50924H/C33/1		DECT BASEBAND	935273707518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
300	PCD50924H/C44/1		DECT BASEBAND	935275114518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
301	PCD50924H/C46/1		DECT BASEBAND	935275368518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
302	PCD50924H/C47/1		DECT BASEBAND	935275459518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
303	PCD50924H/C48/1		DECT BASEBAND	935275491518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
304	PCD50951HL/P05/3		DECT HANDSET 48K	935272197518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
305	PCD50951HL/P12/3		DECT HANDSET 48K	935275192518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
306	PCD50953H/E46/3		DECT HANDSET CHIP	935270291518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
307	PCD50953H/E61/3		DECT HANDSET CHIP	935270723518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
308	PCD50953H/E71/3		DECT HANDSET CHIP	935271508518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
309	PCD50953H/E74/3		DECT HANDSET CHIP	935272089518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
310	PCD50953H/E75/3		DECT HANDSET CHIP	935272206518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
311	PCD50953H/E76/3		DECT HANDSET CHIP	935272217518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
312	PCD50953H/E81/3		DECT HANDSET CHIP	935272884518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
313	PCD50953H/E82/3		DECT HANDSET CHIP	935272919518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
314	PCD50953H/E86/4		DECT HANDSET CHIP	935273474518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
315	PCD50953H/E89/3		DECT HANDSET CHIP	935273495518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
316	PCD50954H/E15/1		DECT HANDSET CHIP	935269791518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
317	PCD50954H/E25/1		DECT HANDSET CHIP	935272762518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
318	PCD50954H/E31/1		DECT HANDSET CHIP	935273613518	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
319	PCF2104NU/2/F1		DISPLAY DRIVERS	935262231026	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
320	PCF5079HK/C/1		PA CONTROLLER	935269522118	T	S	3	31-Mar-06	30-Jun-06	None	Standard End of Life. Consult Marketing.
321	PCF5079HK/C/1		PA CONTROLLER	935269522518	T	S	3	31-Mar-06	30-Jun-06	None	Standard End of Life. Consult Marketing.
322	PCF7341ATS/B0200		IMMO COMBI CHIP	935274294112	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for Replacement.
323	PCF8548U/2/F1	PCF8548U/2 CK	LCD GRAPHIC DRIVER	935262435026	T	S	3	31-Mar-06	30-Jun-06	PCF8548U/2DA/3	Standard Discontinuation. See Replacement. Consult Marketing.
324	PCF8548U/2DB/1		LCD GRAPHIC DRIVER	935268013026	T	S	3	31-Mar-06	30-Jun-06	PCF8548U/2DA/3	Standard Discontinuation. See Replacement. Consult Marketing.
325	PCF8558U/2/F2		DISPLAY DRIVERS	935231410026	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
326	PCF87752U/2		BLUEBERRY VOICE	935273786005	N	S	3	31-Mar-06	30-Jun-06	BGB203/1/Sxx, BGB204/1/Sxx	Standard Discontinuation. See Replacement. Consult Marketing.
327	PCF8814U/2DA/2		LCD DRIVER	935270409026	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
328	PCF8820U/2/F1	PCF8820U/2 CK	67X101XGREY SCALE L	935265825026	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
329	PCF8833M1/EB/1		PCF8833 IN COF PACKAGE	935275991116	T	C	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
330	PCF8833U/2DC/1		132X132 4K COLOUR DRIVER	935276044026	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
331	PCF8833U/2DD/1		132X132 4K COLOUR DRIVER	935277129026	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
332	PCF8834U/2DA/1		84X104 COLOR DRIVER	935273883026	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
333	PCF8837U/2DA/1		176X132, 65K CSTN DRIVER	935274662026	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. See Replacement. Consult Marketing.
334	PCF8839AU/2DA/2		132X132, 65K,CSTN DRIVER	935276228026	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
335	PCH7371AW/C0BxB06		TIRE PRESSURE MON	935276186005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Consult Marketing for replacement
336	PCH7371AW/C0BxB07		TIRE PRESSURE MON	935276602005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Limited Supply. Consult Marketing for replacement

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
337	PCH7371AW/C0BxB12		TIRE PRESSURE MON	935278945005	T	C	2	30-Mar-06	30-Jun-06	PCH7372AW/C0BxB12	Consult Marketing for Replacement
338	PCH7371AW/XB006		TIRE PRESSURE MON	935275676005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Consult Marketing for replacement
339	PCH7970AW/C0CXB07		TPM SYSTEMS	935278554005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Consult Marketing for replacement
340	PCH7970AW/C0CXB08		TPM SYSTEMS	935278969005	T	C	2	30-Mar-06	30-Jun-06	See Comments	Consult Marketing for replacement
341	PCK111BD/S900		PCK111	935275528118	T	M	2	30-Dec-05	30-Jun-06	PCK111BD	Limited Supply. See Replacement. Consult Marketing.
342	PCK111BD/S900		PCK111	935275528151	T	M	2	30-Dec-05	30-Jun-06	PCK111BD	Limited Supply. See Replacement. Consult Marketing.
343	PCK111BD/S900		PCK111	935275528157	T	M	2	30-Dec-05	30-Jun-06	PCK111BD	Limited Supply. See Replacement. Consult Marketing.
344	PDIUSBD12PW/CP2141		USB	935272813112	T	S	3	31-Mar-06	30-Jun-06	PDIUSBD12PW	Standard Discontinuation. See Replacement. Consult Marketing.
345	PDIUSBD12PW/CP2141		USB	935272813118	T	S	3	31-Mar-06	30-Jun-06	PDIUSBD12PW	Standard Discontinuation. See Replacement. Consult Marketing.
346	PHB63NQ03LT		<= 30V N CHANNEL TRENCHFET	934057021118	T	M	3	31-Dec-05	30-Jun-06	PHB66N03LT	Standard Discontinuation. See Replacement. Consult Marketing.
347	PHB64N03LT		<=30V N CHANNEL TRENCHFET	934057254118	T	M	3	31-Dec-05	30-Jun-06	PHB66N03LT	Standard Discontinuation. See Replacement. Consult Marketing.
348	PHB9NQ20T		100V><300V N CHANNEL TRENCHFET	934055768118	T	M	3	31-Dec-05	30-Jun-06	PHD9NQ20T	Standard Discontinuation. See Replacement. Consult Marketing.
349	PHN103T		30V N TRENCHFET	934056038118	T	M	3	31-Dec-05	30-Jun-06	SI9410DY	Standard Discontinuation. See Replacement. Consult Marketing.
350	PHN103T		30V N TRENCHFET	934056038518	T	M	3	31-Dec-05	30-Jun-06	SI9410DY	Standard Discontinuation. See Replacement. Consult Marketing.
351	PHP83N06T		<=60V N CHANNEL TRENCHFET	934056886127	T	M	3	31-Dec-05	30-Jun-06	PHP73N06T	Standard Discontinuation. See Replacement. Consult Marketing.
352	PI4884		<=30V N CHANNEL TRENCHFET	934056990118	T	M	3	31-Dec-05	30-Jun-06	PHK13N03LT, PHK12NQ03LT	Both are not equivalent but are the closest to the PI4884 we can recommend. Consult Marketing.
353	PI4884		<=30V N CHANNEL TRENCHFET	934056990518	T	M	3	31-Dec-05	30-Jun-06	PHK13N03LT, PHK12NQ03LT	Both are not equivalent but are the closest to the PI4884 we can recommend. Consult Marketing.
354	PMWD18UN		<=30V N CHANNEL TRENCHFET	934057601118	T	M	3	31-Dec-05	30-Jun-06	PMWD20XN	Standard Discontinuation. See Replacement. Consult Marketing.
355	PMWD18UN		<=30V N CHANNEL TRENCHFET	934057601518	T	M	3	31-Dec-05	30-Jun-06	PMWD20XN	Standard Discontinuation. See Replacement. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
356	PNX8526EH/M0		VIPER1.1	935272401557	T	S	2	30-Sep-05	31-Dec-05	PNX8526EH/M0/G	Phase out of lead-containing product. Replacement by lead-free version
357	PTD2112EB		PTD2112EB	935271676557	T	C	2	30-Sep-05	31-Dec-05	None	Limited Supply-- Manufacturing agreement expired.
358	PTD2114EB		PTD2114EB	935271677557	T	C	2	30-Sep-05	31-Dec-05	None	Limited Supply-- Manufacturing agreement expired.
359	PTD2210EB		PTD2210EB	935272406557	T	C	2	30-Sep-05	31-Dec-05	None	Limited Supply. Manufacturing agreement expired.
360	PTD2412EB		PTD2412EB	935271681557	T	C	2	30-Sep-05	31-Dec-05	None	Limited Supply-- Manufacturing agreement expired.
361	PTD2414EB		PTD2414EB	935271679557	T	C	2	30-Sep-05	31-Dec-05	None	Limited Supply-- Manufacturing agreement expired.
362	PXAG37KBBD		PXAG37KBBD	935263503157	T	S	3	31-Mar-06	30-Jun-06	PXAG37KFBD	Standard Discontinuation. See Replacement. Consult Marketing.
363	SA5209D	SA5209 D	RF/WIRELESS	935030700602	T	S	2	30-Mar-06	30-Jun-06	SA5209D/01	Limited Supply. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
364	SA5209D	SA5209 D	RF/WIRELESS	935030700623	T	S	2	30-Mar-06	30-Jun-06	SA5209D/01	Limited Supply. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
365	SA5211D	SA5211 D	LINEAR DATACOM	935003950118	T	S	2	30-Mar-06	30-Jun-06	SA5211D/01	Limited Supply. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
366	SA5211D	SA5211 D	LINEAR DATACOM	935003950602	T	S	2	30-Mar-06	30-Jun-06	SA5211D/01	Limited Supply. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
367	SA5212AD	SA5212A D	LINEAR DATACOM	935028520602	T	S	2	30-Mar-06	30-Jun-06	SA5212AD/01	Limited Supply. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
368	SA5212AD	SA5212A D	LINEAR DATACOM	935028520623	T	S	2	30-Mar-06	30-Jun-06	SA5212AD/01	Limited Supply. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
369	SA5214D	SA5214 D	LINEAR DATACOM	935003960602	T	S	2	30-Mar-06	30-Jun-06	SA5214D/01	Limited Supply. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
370	SA5214D	SA5214 D	LINEAR DATACOM	935003960623	T	S	2	30-Mar-06	30-Jun-06	SA5214D/01	Limited Supply. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
371	SA5217D	SA5217 D	LINEAR DATACOM	935003980118	T	S	2	30-Mar-06	30-Jun-06	SA5217D/01	Limited Supply. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
372	SA5217D	SA5217 D	LINEAR DATACOM	935003980602	T	S	2	30-Mar-06	30-Jun-06	SA5217D/01	Limited Supply. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
373	SA5219D	SA5219 D	RF/WIRELESS	935056440602	T	S	2	30-Mar-06	30-Jun-06	SA5219D/01	Limited Supply. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
374	SA5219D	SA5219 D	RF/WIRELESS	935056440623	T	S	2	30-Mar-06	30-Jun-06	SA5219D/01	Limited Supply. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments	
375	SA5232D		MATCHED DUAL LOW VOLT OP AMP	935272098112	T	M	2	30-Dec-05	30-Jun-06	SA5232D/01	Albuquerque die transfer to ASMC. Limited Supply. Consult Marketing.
376	SA5232D		MATCHED DUAL LOW VOLT OP AMP	935272098118	T	M	2	30-Dec-05	30-Jun-06	SA5232D/01	Albuquerque die transfer to ASMC. Limited Supply. Consult Marketing.
377	SA5232N		MATCHED DUAL LOW VOLT OP AMP	935272099112	T	M	2	30-Dec-05	30-Jun-06	SA5232N/01	Albuquerque die transfer to ASMC. Limited Supply. Consult Marketing.
378	SA5234N	SA5234 N	LINEAR INDUSTRIAL	935030650602	T	M	2	30-Dec-05	30-Jun-06	SA5234N/01	Albuquerque die transfer to ASMC. Limited Supply. Consult Marketing.
379	SA56202TW		DVD MOTOR DRIVER	935273589518	T	M	3	31-Dec-05	30-Jun-06	SA56203	Standard Discontinuation. Improved successor available. See Replacement. Consult Marketing.
380	SA57000-33UK		CAPFREE 150MA LOW DROP-OUT RE	935273602023	T	S	3	31-Mar-06	30-Jun-06	None noted	Standard Discontinuation. Consult Marketing.
381	SA57016-18UK		CAPFREE 150MA LOW DROP-OUT RE	935274062023	T	S	3	31-Mar-06	30-Jun-06	None noted	Standard Discontinuation. Consult Marketing.
382	SA5775AD	SA5775A D	AUTO CUSTOM ASIC	935219130112	T	S	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
383	SA5775AD	SA5775A D	AUTO CUSTOM ASIC	935219130118	T	S	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
384	SA5775AD/CE1674	CE1674 D	AUTO CUSTOM ASIC	935203980118	T	C	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
385	SA5775AD/CE1674/N		AUTO CUSTOM ASIC	935277464118	T	C	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
386	SA5775AD/CE1708	CE1708 D	AUTO CUSTOM ASIC	935220880112	T	C	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
387	SA5775AD/CE1708	CE1708 D	AUTO CUSTOM ASIC	935220880118	T	C	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
388	SA5775AD/CE1712	CE1712 D	AUTO CUSTOM ASIC	935220890112	T	C	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
389	SA5775AD/CE1712	CE1712 D	AUTO CUSTOM ASIC	935220890118	T	C	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
390	SA5775AD/CE1712	CE1712 D	AUTO CUSTOM ASIC	935220890512	T	C	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
391	SA5775AD/CE1712	CE1712 D	AUTO CUSTOM ASIC	935220890518	T	C	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
392	SA5775AD/CE1712/N		AUTO CUSTOM ASIC	935279346118	T	C	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
393	SA5775AD/S420		AUTO CUSTOM ASIC	935273325118	T	C	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
394	SA5775AD/S420/N	AUTO CUSTOM ASIC	935277465118	T	C	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
395	SA5775AN	SA5775A N	935219120112	T	S	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
396	SA5775AN/CE1499	CE1499 N	935117230112	T	C	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
397	SA5775AN/CE1707	CE1707 N	935220860112	T	C	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
398	SA5775AN/CE1711	CE1711 N	935220870112	T	S	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
399	SA5777AD	SA5777A D	935221510112	T	S	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
400	SA5777AD	SA5777A D	935221510118	T	S	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
401	SA5777AD	SA5777A D	935221510512	T	S	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
402	SA5777AD/CE1710	CE1710 D	935221330112	T	S	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
403	SA5777AD/CE1710	CE1710 D	935221330118	T	S	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
404	SA5777AN/CE1709	CE1709 N	935221300112	T	C	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
405	SA602AD	SA602A D	935030750602	T	S	1	30-Jun-05	30-Jun-05	SA602AD/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
406	SA602AD	SA602A D	935030750623	T	S	1	30-Jun-05	30-Jun-05	SA602AD/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
407	SA602AN	SA602A N	935030770602	T	S	1	30-Jun-05	30-Jun-05	SA602AN/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
408	SA604AD	SA604A D	933948930602	T	S	1	30-Jun-05	30-Jun-05	SA604AD/01	Non-Manufacturable. Albuquerque die replaced by ASMC die. See Replacement. Consult Marketing.
409	SA604AD	SA604A D	933948930623	T	S	1	30-Jun-05	30-Jun-05	SA604AD/01	Non-Manufacturable. Albuquerque die replaced by ASMC die. See Replacement. Consult Marketing.
410	SA605D	SA605 D	933948970602	T	S	1	30-Jun-05	30-Jun-05	SA605D/01	Non-Manufacturable. Albuquerque die replaced by ASMC die. See Replacement. Consult Marketing.
411	SA605D	SA605 D	933948970623	T	S	1	30-Jun-05	30-Jun-05	SA605D/01	Non-Manufacturable. Albuquerque die replaced by ASMC die. See Replacement. Consult Marketing.
412	SA605DK	SA605 DK	935040870112	T	S	1	30-Jun-05	30-Jun-05	SA605DK/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
413 SA605DK	SA605 DK	RF/WIRELESS	935040870118	T	S	1	30-Jun-05	30-Jun-05	SA605DK/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
414 SA606D	SA606 D	RF/WIRELESS	935051630118	T	S	1	30-Jun-05	30-Jun-05	SA606D/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
415 SA606D	SA606 D	RF/WIRELESS	935051630602	T	S	1	30-Jun-05	30-Jun-05	SA606D/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
416 SA606DK	SA606 DK	RF/WIRELESS	935051650112	T	S	1	30-Jun-05	30-Jun-05	SA606DK/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
417 SA606DK	SA606 DK	RF/WIRELESS	935051650118	T	S	1	30-Jun-05	30-Jun-05	SA606DK/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
418 SA607DK	SA607 DK	RF/WIRELESS	935059610112	T	S	1	30-Jun-05	30-Jun-05	SA607DK/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
419 SA607DK	SA607 DK	RF/WIRELESS	935059610118	T	S	1	30-Jun-05	30-Jun-05	SA607DK/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
420 SA608DK	SA608 DK	RF/WIRELESS	935063370112	T	S	1	30-Jun-05	30-Jun-05	SA608DK/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
421 SA608DK	SA608 DK	RF/WIRELESS	935063370118	T	S	1	30-Jun-05	30-Jun-05	SA608DK/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
422 SA612AD	SA612A D	RF/WIRELESS	935051900118	T	S	1	30-Jun-05	30-Jun-05	SA612AD/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
423 SA612AD	SA612A D	RF/WIRELESS	935051900602	T	S	1	30-Jun-05	30-Jun-05	SA612AD/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
424 SA612AN	SA612A N	RF/WIRELESS	935065560112	T	S	1	30-Jun-05	30-Jun-05	SA612AN/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
425 SA614AD	SA614A D	RF/WIRELESS	933995410118	T	S	1	30-Jun-05	30-Jun-05	SA614AD/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
426 SA614AD	SA614A D	RF/WIRELESS	933995410602	T	S	1	30-Jun-05	30-Jun-05	SA614AD/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
427 SA615D	SA615 D	RF/WIRELESS	933995450602	T	S	1	30-Jun-05	30-Jun-05	SA615D/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
428 SA615D	SA615 D	RF/WIRELESS	933995450623	T	S	1	30-Jun-05	30-Jun-05	SA615D/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
429 SA615DK	SA615 DK	RF/WIRELESS	935040890112	T	S	1	30-Jun-05	30-Jun-05	SA615DK/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
430 SA615DK	SA615 DK	RF/WIRELESS	935040890118	T	S	1	30-Jun-05	30-Jun-05	SA615DK/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
431 SA616DK	SA616 DK	RF/WIRELESS	935054340112	T	S	1	30-Jun-05	30-Jun-05	SA616DK/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
432	SA616DK	SA616 DK	RF/WIRELESS	935054340118	T	S	1	30-Jun-05	30-Jun-05	SA616DK/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
433	SA630D	SA630 D	RF/WIRELESS	935052500118	T	S	1	30-Jun-05	30-Jun-05	SA630D/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
434	SA630D	SA630 D	RF/WIRELESS	935052500602	T	S	1	30-Jun-05	30-Jun-05	SA630D/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
435	SA636DK	SA636 DK	RF/WIRELESS	935166750112	T	S	1	30-Jun-05	30-Jun-05	SA636DK/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
436	SA636DK	SA636 DK	RF/WIRELESS	935166750118	T	S	1	30-Jun-05	30-Jun-05	SA636DK/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
437	SA639DH	SA639 DH	RF/WIRELESS	935198840512	T	S	1	30-Jun-05	30-Jun-05	SA639DH/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
438	SA639DH	SA639 DH	RF/WIRELESS	935198840518	T	S	1	30-Jun-05	30-Jun-05	SA639DH/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
439	SA676DK	SA676 DK	RF/WIRELESS	935084010112	T	S	1	30-Jun-05	30-Jun-05	SA676DK/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
440	SA676DK	SA676 DK	RF/WIRELESS	935084010118	T	S	1	30-Jun-05	30-Jun-05	SA676DK/01	Non-Manufacturable. Albuquerque die transfer to ASMC. See Replacement. Consult Marketing.
441	SAA4848PS/V1006		DIG DEFL CONTROLLER WITH MCU	935276584112	T	C	2	31-Dec-05	31-Mar-06	SAA4849PS/V1	Limited Supply. See Replacement. Consult Marketing.
442	SAA6713AH/V1		XGA AVI-ONLY	935270681557	T	S	2	30-Mar-06	30-Jun-06	No direct replacement, propose SAA6734AHL	Limited Supply. Consult Marketing.
443	SAA6713H/V1		XGA TFT DISPLAY CONTROLLER	935267865557	T	S	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
444	SAA7133HL/V101		PCI 9BIT VIDEO/STEREO DECODER	935271281518	T	S	2	30-Dec-05	31-Mar-06	SAA7133HL/V203	Limited Supply. See Replacement. Consult Marketing.
445	SAA7133HL/V101		PCI 9BIT VIDEO/STEREO DECODER	935271281557	T	S	2	30-Dec-05	31-Mar-06	SAA7133HL/V203	Limited Supply. See Replacement. Consult Marketing.
446	SAA7133HL/V101/G		PCI 9BIT VIDEO/STEREO DECODER	935276197518	T	S	1	30-Jun-05	30-Jun-05	SAA7133HL/V203	Non-Manufacturable. See Replacement. Consult Marketing.
447	SAA7133HL/V101/G		PCI 9BIT VIDEO/STEREO DECODER	935276197557	T	S	1	30-Jun-05	30-Jun-05	SAA7133HL/V203	Non-Manufacturable. See Replacement. Consult Marketing.
448	SAA7133HL/V103		PCI 9BIT VIDEO/STEREO DECODER	935277126518	T	S	1	30-Jun-05	30-Jun-05	SAA7133HL/V203	Non-Manufacturable. See Replacement. Consult Marketing.
449	SAA7133HL/V103		PCI 9BIT VIDEO/STEREO DECODER	935277126557	T	S	1	30-Jun-05	30-Jun-05	SAA7133HL/V203	Non-Manufacturable. See Replacement. Consult Marketing.
450	SAA7135HL/V101		PCI 9BIT VIDEO/STEREO DECODER	935271282518	T	S	2	30-Dec-05	31-Mar-06	SAA7135HL/V203	Limited Supply. See Replacement. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
451	SAA7135HL/V101		PCI 9BIT VIDEO/STEREO DECODER	935271282557	T	S	2	30-Dec-05	31-Mar-06	SAA7135HL/V203	Limited Supply. See Replacement. Consult Marketing.
452	SAA7135HL/V101/G		PCI 9BIT VIDEO/STEREO DECODER	935276192518	T	S	1	30-Jun-05	30-Jun-05	SAA7135HL/V203	Non-Manufacturable. See Replacement. Consult Marketing.
453	SAA7149AH/V1		DIGITAL VIDEO ENCODER	935269517518	T	S	2	30-Mar-06	30-Jun-06	SAA7129AH/V1	Limited Supply. See Replacement. Consult Marketing.
454	SAA7149AH/V1		DIGITAL VIDEO ENCODER	935269517557	T	S	2	30-Mar-06	30-Jun-06	SAA7129AH/V1	Limited Supply. See Replacement. Consult Marketing.
455	SAA7149AH/V1/G		DIGITAL VIDEO ENCODER	935276311518	T	S	2	30-Mar-06	30-Jun-06	SAA7129AH/V1	Limited Supply. See Replacement. Consult Marketing.
456	SAA7149AH/V1/G		DIGITAL VIDEO ENCODER	935276311557	T	S	2	30-Mar-06	30-Jun-06	SAA7129AH/V1	Limited Supply. See Replacement. Consult Marketing.
457	SAA7149H/V1		BASIC-TYPENR NOT USED	935262589518	T	S	2	30-Mar-06	30-Jun-06	SAA7129H/V1	Limited Supply. See Replacement. Consult Marketing.
458	SAA7149H/V1/G		BASIC-TYPENR NOT USED	935276219518	T	S	2	30-Mar-06	30-Jun-06	SAA7129H/V1	Limited Supply. See Replacement. Consult Marketing.
459	SAA7354HL/T/M0B		IGUANA1.7 (AMLOGIC)	935273146557	T	S	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
460	SAA7706H/N108		DIRAC-1	935267719518	T	S	1	30-Jun-05	30-Jun-05	SAA7706H/N108Y	Non-Manufacturable. See Replacement. Consult Marketing.
461	SAA7706H/N108		DIRAC-1	935267719557	T	S	1	30-Jun-05	30-Jun-05	SAA7706H/N108Y	Non-Manufacturable. See Replacement. Consult Marketing.
462	SAA7709H/N108		DIRAC-2	935271279518	T	S	1	30-Jun-05	30-Jun-05	None noted	Standard End of Life. Consult Marketing.
463	SAA7709H/N108		DIRAC-2	935271279557	T	S	1	30-Jun-05	30-Jun-05	None noted	Standard End of Life. Consult Marketing.
464	SAA7724H/N106		MADRE2	935273067518	T	S	1	30-Jun-05	30-Jun-05	None noted	Non-Manufacturable. Consult Marketing.
465	SAA7724H/N106		MADRE2	935273067557	T	S	1	30-Jun-05	30-Jun-05	None noted	Non-Manufacturable. Consult Marketing.
466	SAA7804H/M1/S006		MUSIC	935276666557	T	C	1	30-Jun-05	30-Jun-05	SAA7804H/M1/S008	Non-Manufacturable. See Replacement. Consult Marketing.
467	SAA7804H/M1/S007		MUSIC	935278112557	T	C	2	30-Mar-06	30-Jun-06	SAA7804H/M1/S008	Limited Supply. See Replacement. Consult Marketing.
468	SAA7813HL/M0A		LIZARD	935269445557	T	S	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
469	SAA7817HL		IGUANA 1.7	935271910557	T	S	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
470	SAA7818HL/E		IGUANA 1.7 AUTOMOTIVE	935273194557	T	S	1	30-Jun-05	30-Jun-05	None noted	Non-Manufacturable. Consult Marketing.
471	SAA7818HL/N		IGUANA 1.7 AUTOMOTIVE	935279296557	T	S	1	30-Jun-05	30-Jun-05	None noted	Non-Manufacturable. Consult Marketing.
472	SC28C94A1N	SC28C94A1 N	SC28C941AN	935262535112	T	S	2	30-Mar-06	30-Jun-06	SC28C94A1A	Limited Supply. See Replacement. Consult Marketing.
473	SC28C94A1N		SC28C941AN	935262535129	T	S	2	30-Mar-06	30-Jun-06	SC28C94A1A	Limited Supply. See Replacement. Consult Marketing.
474	SZF2002HL/K1	SZF2002HL BE	TELECOM TERMINALS	935251070557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
475	TDA10046HT/C1		CHANNEL DECODING	935270784518	T	S	3	31-Mar-06	30-Jun-06	TDA10046AHT	Standard Discontinuation. See Replacement. Consult Marketing.
476	TDA10046HT/C1		CHANNEL DECODING	935270784551	T	S	3	31-Mar-06	30-Jun-06	TDA10046AHT	Standard Discontinuation. See Replacement. Consult Marketing.
477	TDA10046HT/C1		CHANNEL DECODING	935270784557	T	S	3	31-Mar-06	30-Jun-06	TDA10046AHT	Standard Discontinuation. See Replacement. Consult Marketing.
478	TDA1308/N1	TDA1308 N	Class AB stereo headphone driver	935172510112	T	S	1	30-Jun-05	30-Jun-05	TDA1308/N2	8 inch conversion
479	TDA1308AT/N1		DIGITAL AUDIO MISCELLANEOUS	935262200112	T	S	1	30-Jun-05	30-Jun-05	TDA1308AT/N2	Non-Manufacturable. 8 inch conversion. See Replacement. Consult Marketing.
480	TDA1308AT/N1		DIGITAL AUDIO MISCELLANEOUS	935262200115	T	S	1	30-Jun-05	30-Jun-05	TDA1308AT/N2	Non-Manufacturable. 8 inch conversion. See Replacement. Consult Marketing.
481	TDA1308T/N1	TDA1308T D	DIGITAL AUDIO MISCELLANEOUS	935072110112	T	S	1	30-Jun-05	30-Jun-05	TDA1308T/N2	Non-Manufacturable. 8 inch version. See Replacement. Consult Marketing.
482	TDA1308T/N1	TDA1308T D	DIGITAL AUDIO MISCELLANEOUS	935072110115	T	S	1	30-Jun-05	30-Jun-05	TDA1308T/N2	Non-Manufacturable. 8 inch version. See Replacement. Consult Marketing.
483	TDA1308TT/N1		CLASS AB STEREO HEADPHONE DRIV	935271400118	T	S	1	30-Jun-05	30-Jun-05	TDA1308TT/N2	Non-Manufacturable. See Replacment. 8 inch conversion. Consult Marketing.
484	TDA4859PS/V6		DEFLECTION CONTROLLER	935273070112	T	S	1	30-Jun-05	30-Jun-05	No direct replacement, propose TDA4841PS/V6	Non-Manufacturable. Consult Marketing.
485	TDA4866J/V5		VERTICAL BOOSTER	935267815112	T	S	2	30-Mar-06	30-Jun-06	No direct replacement, propped TDA4867J/V1	Limited Supply. See the suggested Replacement. Consult Marketing.
486	TDA6108AJF/N1		RGB Amplifier	935263645112	T	S	3	31-Mar-06	30-Jun-06	TDA6108AJF/N2	Standard Discontinuation. See Replacement. Consult Marketing.
487	TDA8270HN/C1		SINGLE CHIP TUNER FOR CABLE APP	935272707518	T	S	2	30-Sep-05	31-Dec-05	TDA8270AHN/C1	Limited Supply. See Replacement. Some changes to the tuning software required. Consult Marketing.
488	TDA8270HN/C1		SINGLE CHIP TUNER FOR CABLE APP	935272707557	T	S	2	30-Sep-05	31-Dec-05	TDA8270AHN/C1	Limited Supply. See Replacement. Some changes to the tuning software required. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
489	TDA8271HN/C1		HARQUIN O. BL66/CAEN	935273213157	T	S	2	30-Sep-05	31-Dec-05	TDA8271AHN/C1	some changes to the tuning software required
490	TDA8271HN/C1		HARQUIN O. BL66/CAEN	935273213518	T	S	2	30-Sep-05	31-Dec-05	TDA8271AHN/C1	some changes to the tuning software required
491	TDA8271HN/C1		HARQUIN O. BL66/CAEN	935273213557	T	S	2	30-Sep-05	31-Dec-05	TDA8271AHN/C1	some changes to the tuning software required
492	TDA8274HN/C1		SINGLE CHIP TUNER FOR CABLE APP	935273215518	T	S	2	30-Sep-05	31-Dec-05	TDA8274AHN/C1	some changes to the tuning software required
493	TDA8274HN/C1		SINGLE CHIP TUNER FOR CABLE APP	935273215557	T	S	2	30-Sep-05	31-Dec-05	TDA8274AHN/C1	some changes to the tuning software required
494	TDA8275HN/C1		SINGLE CHIP TUNER FOR CABLE APP	935273216518	T	S	2	30-Sep-05	31-Dec-05	TDA8275AHN/C1	Limited Supply. See Replacement. Some changes to the tuning software required. Consult Marketing.
495	TDA8275HN/C1		SINGLE CHIP TUNER FOR CABLE APP	935273216557	T	S	2	30-Sep-05	31-Dec-05	TDA8275AHN/C1	Limited Supply. See Replacement. Some changes to the tuning software required. Consult Marketing.
496	TDA8541/N1	TDA8541 N	Mono 1 W / 8 e amplifier	935211660112	T	S	1	30-Jun-05	30-Jun-05	See Comments	Non-Manufacturable. Convert to S08 package. Consult Marketing.
497	TDA8543T/N1	TDA8543T D	MULTI MEDIA POWER AMPLIFIERS	935227370112	T	S	1	30-Jun-05	30-Jun-05	TDA8543T/N1	Non-Manufacturable. Use 935227370512. Consult Marketing.
498	TDA8580J/N1	TDA8580J U	NEW AUDIO POWER AMPLIFIER	935263147112	T	M	3	31-Dec-05	30-Jun-06	None noted	Standard Discontinuation. Consult Marketing.
499	TDA8752BH/8/C7		TRIPLE ADC 8 BIT 100 MHZ	935267819551	T	S	2	30-Sep-05	31-Dec-05	None noted	Limited Supply. Consult Marketing.
500	TDA8752BH/8/C7		TRIPLE ADC 8 BIT 100 MHZ	935267819557	T	S	2	30-Sep-05	31-Dec-05	None noted	Limited Supply. Consult Marketing.
501	TDA8768AH/7/C3		12BITS HIGH SPEED ADC	935271199551	N	S	1	30-Jun-05	30-Jun-05	TDA8768AH/7/C4	Non-Manufacturable. See Replacement. Consult Marketing.
502	TDA8926J/N1		POWER STAGE	935267166112	T	M	3	31-Dec-05	30-Jun-06	TDA8922J/N1 or TDA8922BJ/N2	Standard Discontinuation. See Replacement. Consult Marketing.
503	TDA8927TH/N2		POWER STAGE 2 X 100W	935270687518	T	M	3	31-Dec-05	30-Jun-06	TDA8920BH/N2	Standard Discontinuation. See Replacement. Consult Marketing.
504	TDA9800T/V3	TDA9800T D	VISION SOUND (HAMBURG) CONT.	935057030118	T	S	3	31-Mar-06	30-Jun-06	None noted	Standard Discontinuation. Consult Marketing.
505	TDA9952HL/C3		10 BITS IMAGING FRONT-END 18MSPS	935270655118	T	S	3	31-Mar-06	30-Jun-06	None noted	Standard End of Life. Consult Marketing.
506	TDA9952HL/C3		10 BITS IMAGING FRONT-END 18MSPS	935270655151	T	S	3	31-Mar-06	30-Jun-06	None noted	Standard End of Life. Consult Marketing.
507	TDA9952HL/C3		10 BITS IMAGING FRONT-END 18MSPS	935270655157	T	S	3	31-Mar-06	30-Jun-06	None noted	Standard End of Life. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
508	TDA9952HN/C3		10BITS 3V 25MSPS FRONT END IMAG	935270654518	T	S	3	31-Mar-06	30-Jun-06	None noted	Standard End of Life. Consult Marketing.
509	TDA9952HN/C3		10BITS 3V 25MSPS FRONT END IMAG	935270654551	T	S	3	31-Mar-06	30-Jun-06	None noted	Standard End of Life. Consult Marketing.
510	TDA9952HN/C3		10BITS 3V 25MSPS FRONT END IMAG	935270654557	T	S	3	31-Mar-06	30-Jun-06	None noted	Standard End of Life. Consult Marketing.
511	TDA9962HL/C3		10 BITS IMAGING FRONT-END 20MSPS	935270657118	T	S	3	31-Mar-06	30-Jun-06	None noted	Standard End of Life. Consult Marketing.
512	TDA9962HL/C3		10 BITS IMAGING FRONT-END 20MSPS	935270657151	T	S	3	31-Mar-06	30-Jun-06	None noted	Standard End of Life. Consult Marketing.
513	TDA9962HL/C3		10 BITS IMAGING FRONT-END 20MSPS	935270657157	T	S	3	31-Mar-06	30-Jun-06	None noted	Standard End of Life. Consult Marketing.
514	TEA1095T/C2		BIPOLAR ANALOG TELECOM (CAEN)	935276562112	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
515	TEA1095T/C2		BIPOLAR ANALOG TELECOM (CAEN)	935276562118	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
516	TEA1095TS/C2		BIPOLAR ANALOG TELECOM (CAEN)	935276567112	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
517	TEA1095TS/C2		BIPOLAR ANALOG TELECOM (CAEN)	935276567118	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
518	TEA1095TS/C2		BIPOLAR ANALOG TELECOM (CAEN)	935276567518	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
519	TEA1202TS/N2		DC/DC CONVERTER	935270842118	T	S	3	31-Mar-06	30-Jun-06	None noted	Standard End of Life. Consult Marketing.
520	TEA1208T/N1		DC/DC CONVERTER	935270107118	T	S	3	31-Mar-06	30-Jun-06	None noted	Standard End of Life. Consult Marketing.
521	TEA5757HL/V1	TEA5757HL BE	SELF TUNED RADIO	935264107118	T	M	3	31-Dec-05	30-Jun-06	TEA5777HL/N2; TEA5777HN/N2	Standard Discontinuation. See Replacement. Consult Marketing.
522	TEA5757HL/V1	TEA5757HL BE	SELF TUNED RADIO	935264107157	T	M	3	31-Dec-05	30-Jun-06	TEA5777HL/N2; TEA5777HN/N2	Standard Discontinuation. See Replacement. Consult Marketing.
523	TEA5757HL/V1		SELF TUNED RADIO	935264107518	T	M	3	31-Dec-05	30-Jun-06	TEA5777HL/N2; TEA5777HN/N2	Standard Discontinuation. See Replacement. Consult Marketing.
524	TEA5757HL/V1		SELF TUNED RADIO	935264107557	T	M	3	31-Dec-05	30-Jun-06	TEA5777HN/N2; TEA5777HL/N2	Standard Discontinuation. See Replacement. Consult Marketing.
525	TEA5759H/V1		RADIO FRONT END (HAMBURG)	935198880518	T	M	3	31-Dec-05	30-Jun-06	None noted	Standard Discontinuation. Consult Marketing.
526	TEA5759H/V1	TEA5759H B	RADIO FRONT END (HAMBURG)	935198880557	T	M	3	31-Dec-05	30-Jun-06	None noted	Standard Discontinuation. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
527	TEA5880TS/N1		ZERO COMPONENTS STEREO FM RA	935272643512	T	M	1	30-Jun-05	30-Jun-05	TEA5767 or TEA5761	Non-Manufacturable. See Replacement. Consult Marketing.
528	TEA5880TS/N1		ZERO COMPONENTS STEREO FM RA	935272643518	T	M	1	30-Jun-05	30-Jun-05	TEA5767 or TEA5761	Non-Manufacturable. See Replacement. Consult Marketing.
529	TEA6848H/V1/S3		NICE PACS	935273975557	T	S	1	30-Jun-05	30-Jun-05	None noted	Non-Manufacturable. Consult Marketing.
530	TEA6849H/V1/M5		NICE/PACS SONY	935266959518	T	S	1	30-Jun-05	30-Jun-05	None noted	Non-Manufacturable. Consult Marketing.
531	TEA6849H/V1/S5		NICE/PACS SONY	935264516518	T	S	1	30-Jun-05	30-Jun-05	None noted	Non-Manufacturable. Consult Marketing.
532	TZA1017HL		TZA1035AMLOGIC	935273144118	T	S	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
533	TZA1020HP/M1	TZA1020HP B	COMPACT DISC SYSTEMS (SOTON)	935261972518	T	S	3	31-Mar-06	30-Jun-06	None noted	Standard Discontinuation. Consult Marketing.
534	TZA1020HP/M1	TZA1020HP B	COMPACT DISC SYSTEMS (SOTON)	935261972557	T	S	3	31-Mar-06	30-Jun-06	None noted	Standard Discontinuation. Consult Marketing.
535	TZA1033HL/M1A		VDDALAS2PLUS	935271503118	T	S	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
536	TZA1035HL		DVDALASLITE 48 PIN	935270855118	T	S	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
537	TZA1035HL/E		DVDALASLITE 48 PIN	935271834118	T	S	2	30-Mar-06	30-Jun-06	None noted	Limited Supply. Consult Marketing.
538	TZA1038HW/E		DVDALASLITE AUTOMOTIVE	935273192118	T	S	1	30-Jun-05	30-Jun-05	None noted	Non-Manufacturable. Consult Marketing.
539	TZA1038HW/N		DVDALASLITE AUTOMOTIVE	935279297118	T	S	1	30-Jun-05	30-Jun-05	None noted	Non-Manufacturable. Consult Marketing.
540	TZA1044TM		PAEDIC-S	935274545518	T	M	2	30-Dec-05	30-Jun-06	None noted	Limited Supply. Consult Marketing.
541	UAA1281T/V1	UAA1281T D	DOMESTIC APPLIANCES (HAMBURG)	935211150512	T	M	1	30-Jun-05	30-Jun-05	See Comments	Please Consult BL CAR Marketing for information on replacement parts
542	UAA1281T/V1	UAA1281T D	DOMESTIC APPLIANCES (HAMBURG)	935211150518	T	M	1	30-Jun-05	30-Jun-05	See Comments	for information on replacement parts please Consult BL CAR marketing
543	UDA1355H/N2		SPDIF CODED	935271552518	T	M	3	31-Dec-05	30-Jun-06	None noted	Standard Discontinuation. Consult Marketing.
544	UDA1355H/N2		SPDIF CODED	935271552551	T	M	3	31-Dec-05	30-Jun-06	None noted	Standard Discontinuation. Consult Marketing.
545	UDA1355H/N2		SPDIF CODED	935271552557	T	M	3	31-Dec-05	30-Jun-06	None noted	Standard Discontinuation. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
546	UZZ9002		SIGNAL CONDITIONG IC	934055834118	T	C	1	30-Jun-05	30-Jun-05	UZZ9001	Non-Manufacturable. See Replacement.
547	VM06935-A	VM06935-A V	VM06935-A	935265964157	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
548	VM21672C5	VM21672C5 E	VM21672C5	935269084528	T	C	1	30-Jun-05	30-Jun-05	VM22547	Not Manufacturable – Quality or manufacturing reason. See Replacement.
549	VM21672C6	VM21672C6 E	VM21672C6	935269196557	T	C	1	30-Jun-05	30-Jun-05	VM22547	Not Manufacturable – Quality or manufacturing reason. See Replacement.
550	VP05567-2	VP05567-2 A	VP05567-2	935266412112	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
551	VP21136B4	VP21136B4 E	VP21136B4	935264816557	T	C	2	30-Mar-06	30-Jun-06	None	Non-Manufacturable. Consult Marketing.
552	VP21452A2	VP21452A2 Q	VP21452A2	935266217157	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
553	VP21538-2	VP21538-2 E	VP21538-2	935265102557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
554	VP21697-2		VP21697-2	935265223557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
555	VP22049A2	VP22049A2 A	VP22049A2	935266420112	T	C	2	30-Mar-06	30-Jun-06	None	Limited Supply. Consult Marketing.
556	VP22049A3	VP22049A3 A	VP22049A3	935266314518	T	C	2	30-Mar-06	30-Jun-06	None	Limited Supply. Consult Marketing.
557	VP22127D2	VP22127D2 E	VP22127D1	935269639557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
558	VP22297B2		VP22297B2	935270999557	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
559	VP22381-2		VP22381-2	935270751557	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
560	VP40575-4	VP40575-4 E	VP40575-4	935267022528	T	M	3	31-Dec-05	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
561	VP40575-5	VP40575-5 E	VP40575-5	935268779557	T	M	3	31-Dec-05	30-Jun-06	None	Standard Discontinuation. See Replacement. Consult Marketing.
562	VP40581H3	VP40581H3 E	VP40581H3	935269805557	T	M	3	31-Dec-05	30-Jun-06	None	Standard Discontinuation. See Replacement. Consult Marketing.
563	VP40581H4	VP40581H4 E	VP40581H4	935269806528	T	M	3	31-Dec-05	30-Jun-06	None	Standard Discontinuation. See Replacement. Consult Marketing.
564	VP40581H6	VP40581H6 E	VP40581H6	935270098528	T	M	3	31-Dec-05	30-Jun-06	None	Standard Discontinuation. See Replacement. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
565	VP40581H7		VP40581H7	935271034557	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
566	VP40581J2		ONE C 1.2CH	935273758528	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
567	VP40581J3		ONE C 1.2CH	935273775557	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
568	VP40584B2		VP40584-1	935272079557	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
569	VP40584B3		VP40584-1	935272080528	T	S	3	31-Mar-06	30-Jun-06	VP40584B3/M1	Standard Discontinuation. See Replacement. Consult Marketing.
570	VP40584B4		VP40584-1	935272081557	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
571	VP40584B5		VP40584-1	935272082528	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
572	VP40586A2		VP40586A2	935273451557	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
573	VP40586A3		VP40586A3	935273452528	T	C	3	31-Mar-06	30-Jun-06	VP40586A3/M1	Standard Discontinuation. Consult Marketing.
574	VP40586A4		VP40586A4	935273453557	T	S	3	31-Mar-06	30-Jun-06	None	Standard Discontinuation. Consult Marketing.
575	VP40586A5		VP40586A5	935273454528	T	S	3	31-Mar-06	30-Jun-06	VP40586A5/M1	Standard Discontinuation. See Replacement. Consult Marketing.
576	VT22309-4	VT22309-4 E	VT22309-4	935270640557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
577	VT22309-6		VT22309-6	935272051551	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
578	VT22309-6		ASIC - Cuda	935272051551	T	S	1	30-Jun-06	30-Jun-06	None	Non-Manufacturable. Consult Marketing.
579	VT22309-6		ASIC - Cuda	935272051557	T	S	1	30-Jun-06	30-Jun-06	None	Non-Manufacturable. Consult Marketing.
580	VT22341B3		VT22341B3	935273279528	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
581	VW22100DDB	VW22100DDB SD	VW22100DDB	935266890112	T	S	3	31-Mar-06	30-Jun-06	None noted	Standard Discontinuation. Consult Marketing.
582	VW22110DG	VW22110DG SD	VW22110DG	935266884112	T	S	3	31-Mar-06	30-Jun-06	None noted	Standard Discontinuation. Consult Marketing.
583	VY06795-2	VY06795-2 E	VY06795-2	935264744557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
584	VY06802D2	VY06802D2 E	VY06802D2	935265515557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
585	VY16692-2	VY16692-2 B	VY16692-2	935264614557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
586	VY21182C2	VY21182C2 E	VY21182C2	935265517557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
587	VY21182D2	VY21182D2 E	VY21182D2	935264640557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
588	VY21183A2		VY21183A2	935266457557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
589	VY21240A2	VY21240A2 E	VP21240A2	935266459157	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
590	VY21240A2		VP21240A2	935266459557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
591	VY21241B2		VY21241B2	935266461557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
592	VY21243A2	VY21243A2 E	VY21243A2	935264643557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
593	VY21245-B2	VY21245-B2 E	VY21245-B2	935266800557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
594	VY21245C2	VY21245C2 E	VY21245C2	935264644557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
595	VY21278A2	VY21278A2 E	VY21278A2	935264647557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
596	VY21283-2	VY21283-2 E	VY21283-2	935264649557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
597	VY21290-2	VY21290-2 B	VY21290-2	935264652557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
598	VY21314D2	VY21314D2 E	VY21314D2	935264809557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
599	VY21366-2	VY21366-2 B	VY21366-2	935265097557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
600	VY21397-2	VY21397-2 B	VY21397-2	935266165557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
601	VY21420-2	VY21420-2 V	VY21420-2	935266302157	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
602	VY21436-3	VY21436-3 E	VY21436-3	935266349528	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
603	VY21495-2		VY21495-2	935265152557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
604	VY21496-2		VY21496-2	935266540557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
605	VY21519A2	VY21519A2 E	VY21519A2	935265161557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
606	VY21523-2	VY21523-2 B	VY21523-2	935265166557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
607	VY21548-2		VY21548-2	935266492557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
608	VY21562-2	VY21562-2 B	VY21562-2	935265184557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
609	VY21597-2	VY21597-2 B	VY21597-2	935265195557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
610	VY21641-2	VY21641-2 E	VY21641-2	935265205557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
611	VY21674A2		VY21674A2	935264920557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
612	VY21705-2	VY21705-2 B	VY21705-2	935266167557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
613	VY21749-2	VY21749-2 B	VY21749-2	935264973557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
614	VY21750-2	VY21750-2 E	VY21750-2	935264975557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
615	VY21750-3	VY21750-3 E	VY21750-3	935267239528	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
616	VY21751-2	VY21751-2 E	VY21751-2	935266317557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
617	VY21752A2	VY21752A2 E	VY21752A2	935266421557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
618	VY21775-2	VY21775-2 E	VY21775-2	935264988557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
619	VY21775-3		VY21775-3	935274982557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
620	VY21820-2	VY21820-2 E	VY21820-2	935264996557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
621	VY21820-4	VY21820-4 E	VY21820-4	935266361528	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
622	VY21826-2	VY21826-2 E	VY21826-2	935264998557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
623	VY21826-3	VY21826-3 E	VY21826-3	935266362528	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
624	VY21826A2	VY21826A2 E	VY21826A2	935266320557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
625	VY21826A3	VY21826A3 E	VY21826A3	935265001528	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
626	VY21867-2	VY21867-2 E	VY21867-2	935266322557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
627	VY21976-2	VY21976-2 E	VY21976-2	935267267557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
628	VY21976A2	VY21976A2 E	VY21976A2	935268711557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
629	VY21993-3	VY21993-3 E	VY21993-3	935266363528	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
630	VY22012-3	VY22012-3 E	VY22012-3	935266796528	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
631	VY22099B2	VY22099B2 E	VY22099B2	935266822557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
632	VY22099D4	VY22099D4 E	VY22099D4	935267277557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
633	VY22099G3	VY22099G3 E	VY22099G3	935267294557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
634	VY22262-2	VY22262-2 E	VY22262-2	935268486557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
635	VY22331-2		VY22331-2	935270519551	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
636	VY22331-2	VY22331-2 E	VY22331-2	935270519557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
637	VY22356-2	VY22356-2 E	VY22356-2	935269575557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
638	VY22356A2		VY22356A2	935270753557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
639	VY22356B2		VY22356B2	935271230557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
640	VY22356C2		VY22356C2	935271873557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
641	VY22356D2		VY22356D2	935272585557	T	C	2	30-Mar-06	30-Jun-06	None	Limited Supply. Consult Marketing.
642	VY22365-2		VY22365-2	935271742557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
643	VY22370-2	VY22370-2 E	VY22370-2	935269592557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
644	VY22372-2		VY22372-2	935271332024	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
645	VY22372A1		VY22372A1	935274106024	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
646	VY22391-1		VY22391-1	935270250151	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
647	VY22396-2		VY22396-2	935270357551	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
648	VY22399-2		VY22399-2	935271261557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
649	VY22418-6		VY22418-6	935273437557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
650	VY22450-2		VY22450-2	935271118557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
651	VY22452-1		VY22452-1	935272232157	T	C	2	30-Mar-06	30-Jun-06	None	Limited Supply. Consult Marketing.
652	VY22452A2		VY22452A2	935273636557	T	C	2	30-Mar-06	30-Jun-06	None	Limited Supply. Consult Marketing.
653	VY22453-2		VY22453-2	935273347024	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
654	VY22453-2		VY22453-2	935273347557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
655	VY22453A2		VY22453A2	935275643557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
656	VY22454-2		VY22454-2	935273407024	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
657	VY22454A2		VY22454A2	935274984024	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
658	VY22454A2		VY22454A2	935274984557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
659	VY22454B2		VY22454B2	935277793026	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
660	VY22458-2		VY22458-2	935271355024	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
661	VY22475-2		VY22475-2	935273499551	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
662	VY22475-2		VY22475-2	935273499557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
663	VY22477-2		VY22477-2	935274548551	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
664	VY22477-2		VY22477-2	935274548557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
665	VY22533-2		VY22533-2	935274691557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
666	VY22533A2		VY22533A2	935276054557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
667	VY22541-2		VY22541-2	935273853551	T	C	2	30-Mar-06	30-Jun-06	None	Limited Supply. Consult Marketing.
668	VY22541-2		VY22541-2	935273853557	T	C	2	30-Mar-06	30-Jun-06	None	Limited Supply. Consult Marketing.
669	VY22541-3		VY22541-3	935273854528	T	C	2	30-Mar-06	30-Jun-06	None	Limited Supply. Consult Marketing.
670	VY22544-2		VY22544-2	935274493551	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
671	VY22544-2		VY22544-2	935274493557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
672	VY22544-3		VY22544-3	935274494551	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
673	VY22544-3		VY22544-3	935274494557	N	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
674	VY22544-3		ASIC - Fusion	935274494551	T	S	1	30-Jun-06	30-Jun-06	None	Non-Manufacturable. Consult Marketing.
675	VY22544-3		ASIC - Fusion	935274494557	T	S	1	30-Jun-06	30-Jun-06	None	Non-Manufacturable. Consult Marketing.
676	VY22558-2		VY22558-2	935276092557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
677	VY22561-2		VY22561-2	935274638551	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
678	VY22561-2		VY22561-2	935274638557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.

Philips Semiconductors, Inc.
Product Discontinuation Notice DN55
June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
679	VY22563-2		VY22563-2	935274571551	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
680	VY22563-2		VY22563-2	935274571557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
681	VY22563A2		VY22563A2	935276779557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
682	VY22563A3		VY22563A3	935278289557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
683	VY22574-2		VY22574-2	935276171024	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
684	VY22574-2		VY22574-2	935276171026	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
685	VY22588-2		VY22588-2	935276943026	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
686	VY27026-2	VY27026-2 Q	VY27026-2	935265364157	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
687	VY27139-2	VY27139-2 B	VY27139-2	935264710557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
688	VY27193-2	VY27193-2 B	VY27193-2	935264713557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
689	VY27194-2	VY27194-2 A	VY27194-2	935264714112	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
690	VY27209-2	VY27209-2 E	VY27209-2	935264716557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
691	VY27357A2	VY27357A2 E	VY27357A2	935270310557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
692	VY86C610C-5	VY86C610C5 B	VY86C610C-5	935267032557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
693	VY86C710A	VY86C710A B	VY86C710A	935265822557	T	C	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. Consult Marketing.
694	X87C51RB2CU		87C51RB2 DIE/WAFER	935278098025	T	M	3	31-Dec-05	30-Jun-06	None	Standard Discontinuation. Packaged parts available. Consult Marketing.
695	X87C51RC2CU		87C51RC2 DIE/WAFER	935278114025	T	M	3	31-Dec-05	30-Jun-06	None	Standard Discontinuation. Packaged parts available. Consult Marketing.
696	XICM7555CCU	XICM7555C CU	LINEAR INDUSTRIAL	935171930025	T	M	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. No longer offering die sales. Consult Marketing.
697	XNE5234CU	XNE5234 CU	LINEAR INDUSTRIAL	935084620025	T	M	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. No longer offering die sales. Consult Marketing.

Philips Semiconductors, Inc.
 Product Discontinuation Notice DN55
 June 30, 2005

	Column 1 Type Number	Column 2 NA Part Number	Column 3 Description	Column 4 12NC	Column 5 Discontinuation Type Code	Column 6 Source Code	Column 7 Availability Code	Column 8 Last Time Buy Date	Column 9 Last Time Delivery Date	Column 10 Replacement Part	Column 11 Customer Comments
698	XSA5212ACU		TRANSIMPEDANCE AMPLIFIER	935271902025	T	S	1	30-Jun-05	30-Jun-05	None	Non-Manufacturable. No longer doing die sales. Consult Marketing.