

PHILIPS SEMICONDUCTORS
PRODUCT DISCONTINUATION NOTICE NUMBER DN-41
Dated June 30, 1999

CLARIFICATION OF PREVIOUSLY DISCONTINUED PRODUCTS

EXHIBIT C

This Exhibit C to Philips' Product Discontinuation Notice Number DN-41 contains clarification to, or additional information about, Philips Semiconductors' products that were listed under prior product discontinuation notices. This information includes known CORRECTION/DESCRIPTIONs to discontinued products as well as reinstatement (reactivation).

A. PART TYPES REACTIVATED

The following part types were listed on a previous discontinuation notice, but Philips product group management has elected to continue manufacture of these products instead of their discontinuation (reactivation).

| PHILIPS PART NUMBER | PHILIPS PKG | PHILIPS 12 NC NUMBER | WITHDRAWAL NOTICE # | REASON FOR RETENTION OR CORRECTION/DESCRIPTION | SPECIAL COMMENTS |
|---------------------|-------------|----------------------|---------------------|--|------------------|
| | | | | | |
| BYV26A | SOD57 | 933653480113 | DN40 | Re-activate –Customer requirement | |
| BYV26A | SOD57 | 933653480133 | DN40 | Re-activate –Customer requirement | |
| BYM26A | SOD64 | 933818480113 | DN40 | Re-activate –Customer requirement | |
| BYM26A | SOD64 | 933818480133 | DN40 | Re-activate –Customer requirement | |
| BYD17D | SOD87 | 933812230115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BYD17G | SOD87 | 933812240115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BYD17J | SOD87 | 933812250115 | DN40 | Re-activate –Customer requirement for 2K reels | |

| PHILIPS PART NUMBER | PHILIPS PKG | PHILIPS 12 NC NUMBER | WITHDRAWAL NOTICE # | REASON FOR RETENTION OR CORRECTION/DESCRIPTION | SPECIAL COMMENTS |
|---------------------|-------------|----------------------|---------------------|--|------------------|
| | | | | | |
| BYD17M | SOD87 | 933812270115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BYD37D | SOD87 | 933812280115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BYD37G | SOD87 | 933812290115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BYD37J | SOD87 | 933812300115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BYD37K | SOD87 | 933812310115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BYD37K | SOD87 | 933812310135 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BYD37M | SOD87 | 933812320115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BYD77A | SOD87 | 933812330115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BYD77B | SOD87 | 933812340115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BYD77C | SOD87 | 933812350115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BYD77D | SOD87 | 933812360115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| PRLL4001 | SOD87 | 933989430115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BZD27-C10 | SOD87 | 933867470115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BZD27-C11 | SOD87 | 933867480115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BZD27-C12 | SOD87 | 933867490115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BZD27-C15 | SOD87 | 933867510115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BZD27-C160 | SOD87 | 933867760115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BZD27-C18 | SOD87 | 933867530115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BZD27-C20 | SOD87 | 933867540115 | DN40 | Re-activate –Customer requirement for 2K reels | |
| BZD27-C22 | SOD87 | 933867550115 | DN40 | Re-activate -Customer requirement for 2K reels | |
| BZD27-C24 | SOD87 | 933867560115 | DN40 | Re-activate -Customer requirement for 2K reels | |
| BZD27-C27 | SOD87 | 933867570115 | DN40 | Re-activate -Customer requirement for 2K reels | |
| BZD27-C30 | SOD87 | 933867580115 | DN40 | Re-activate -Customer requirement for 2K reels | |
| BZD27-C33 | SOD87 | 933867590115 | DN40 | Re-activate -Customer requirement for 2K reels | |
| BZD27-C36 | SOD87 | 933867600115 | DN40 | Re-activate -Customer requirement for 2K reels | |
| BZD27-C39 | SOD87 | 933867610115 | DN40 | Re-activate -Customer requirement for 2K reels | |
| BZD27-C43 | SOD87 | 933867620115 | DN40 | Re-activate -Customer requirement for 2K reels | |
| BZD27-C47 | SOD87 | 933867630115 | DN40 | Re-activate -Customer requirement for 2K reels | |
| BZD27-C5V6 | SOD87 | 934010900115 | DN40 | Re-activate -Customer requirement for 2K reels | |
| BZD27-C68 | SOD87 | 933867670115 | DN40 | Re-activate -Customer requirement for 2K reels | |
| BZD27-C75 | SOD87 | 933867680115 | DN40 | Re-activate -Customer requirement for 2K reels | |
| BZD27-C7V5 | SOD87 | 933867450115 | DN40 | Re-activate -Customer requirement for 2K reels | |

| PHILIPS PART NUMBER | PHILIPS PKG | PHILIPS 12 NC NUMBER | WITHDRAWAL NOTICE # | REASON FOR RETENTION OR CORRECTION/DESCRIPTION | SPECIAL COMMENTS |
|---------------------|-------------|----------------------|---------------------|--|------------------|
| BZD27-C8V2 | SOD87 | 933867460115 | DN40 | Re-activate -Customer requirement for 2K reels | |
| OF4334 | SOD87 | 934037170115 | DN40 | Re-activate -Customer requirement for 2K reels | |
| BYX119G | SOD57 | 934049570133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C10 | SOD57 | 933601510133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C100 | SOD57 | 933601750133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C11 | SOD57 | 933601520133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C110 | SOD57 | 933601760133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C12 | SOD57 | 933601530133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C120 | SOD57 | 933601770133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C13 | SOD57 | 933601540133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C130 | SOD57 | 933601780133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C15 | SOD57 | 933601550133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C150 | SOD57 | 933601790133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C16 | SOD57 | 933601560133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C160 | SOD57 | 933601800133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C18 | SOD57 | 933601570133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C180 | SOD57 | 933601810133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C20 | SOD57 | 933601580133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C200 | SOD57 | 933601820133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C22 | SOD57 | 933601590133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C220 | SOD57 | 933601830133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C24 | SOD57 | 933601600133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C240 | SOD57 | 933601840133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C27 | SOD57 | 933601610133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C270 | SOD57 | 933601850133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C30 | SOD57 | 933601620133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C300 | SOD57 | 933601860133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C33 | SOD57 | 933601630133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C330 | SOD57 | 933601870133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C36 | SOD57 | 933601640133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C360 | SOD57 | 933601880133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C39 | SOD57 | 933601650133 | DN40 | Re-activate -Retention of single Ammopack | |

| PHILIPS PART NUMBER | PHILIPS PKG | PHILIPS 12 NC NUMBER | WITHDRAWAL NOTICE # | REASON FOR RETENTION OR CORRECTION/DESCRIPTION | SPECIAL COMMENTS |
|---------------------|-------------|----------------------|---------------------|--|------------------|
| BZT03-C390 | SOD57 | 933601890133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C43 | SOD57 | 933601660133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C430 | SOD57 | 933601900133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C47 | SOD57 | 933601670133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C470 | SOD57 | 933601910133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C51 | SOD57 | 933601680133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C510 | SOD57 | 933601920133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C56 | SOD57 | 933601690133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C62 | SOD57 | 933601700133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C68 | SOD57 | 933601710133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C75 | SOD57 | 933601720133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C7V5 | SOD57 | 933654140133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C82 | SOD57 | 933601730133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C8V2 | SOD57 | 933654150133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C91 | SOD57 | 933601740133 | DN40 | Re-activate -Retention of single Ammopack | |
| BZT03-C9V1 | SOD57 | 933601500133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV26D | SOD57 | 933703690133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV26E | SOD57 | 933703700133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV26B | SOD57 | 933653490133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV26C | SOD57 | 933653500133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV26G | SOD57 | 934030440133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV36E | SOD57 | 933731000133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV36G | SOD57 | 934030460133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV97G | SOD57 | 933521480133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV98 | SOD57 | 934020290133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV96E | SOD57 | 933500190133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV96E/EB | SOD57 | 934020600133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV96E/UN | SOD57 | 934041880133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV95A | SOD57 | 933500090133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV95B | SOD57 | 933500170133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV95C | SOD57 | 933500180133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV95C/EB | SOD57 | 934017960133 | DN40 | Re-activate -Retention of single Ammopack | |

| PHILIPS PART NUMBER | PHILIPS PKG | PHILIPS 12 NC NUMBER | WITHDRAWAL NOTICE # | REASON FOR RETENTION OR CORRECTION/DESCRIPTION | SPECIAL COMMENTS |
|---------------------|-------------|----------------------|---------------------|--|------------------|
| | | | | | |
| BYV95C/PC | SOD57 | 934023960133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV36C | SOD57 | 933730980133 | DN40 | Re-activate -Retention of single Ammopack | |
| 1N5059 | SOD57 | 933076440133 | DN40 | Re-activate -Retention of single Ammopack | |
| 1N5060 | SOD57 | 933251860133 | DN40 | Re-activate -Retention of single Ammopack | |
| 1N5061 | SOD57 | 933206080133 | DN40 | Re-activate -Retention of single Ammopack | |
| 1N5062 | SOD57 | 933076450133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYW55 | SOD57 | 933363620133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYW54 | SOD57 | 933363610133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYX10G | SOD57 | 933785320133 | DN40 | Re-activate -Retention of single Ammopack | |
| 1N4001G | SOD57 | 933498190133 | DN40 | Re-activate -Retention of single Ammopack | |
| 1N4002G | SOD57 | 933498200133 | DN40 | Re-activate -Retention of single Ammopack | |
| 1N4003G | SOD57 | 933498210133 | DN40 | Re-activate -Retention of single Ammopack | |
| 1N4004G | SOD57 | 933498220133 | DN40 | Re-activate -Retention of single Ammopack | |
| 1N4005G | SOD57 | 933498230133 | DN40 | Re-activate -Retention of single Ammopack | |
| 1N4006G | SOD57 | 933498240133 | DN40 | Re-activate -Retention of single Ammopack | |
| 1N4007G | SOD57 | 933498250133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYW56 | SOD57 | 933363630133 | DN40 | Re-activate -Retention of single Ammopack | |
| BY527 | SOD57 | 933581010133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV27-600 | SOD57 | 934041870133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV99 | SOD57 | 934021520133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV27-400 | SOD57 | 934036690133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV27-100 | SOD57 | 933543500133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV27-150 | SOD57 | 933543510133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV27-200 | SOD57 | 933552680133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV27-50 | SOD57 | 933543490133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYV2100 | SOD57 | 934041800133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYM26C/OS | SOD64 | 934041890133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYM36D | SOD64 | 933818560133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYW96D | SOD64 | 933500080133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYD53V | SOD81 | 934031740133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYD43V | SOD81 | 934031720133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYD33V | SOD81 | 934031700133 | DN40 | Re-activate -Retention of single Ammopack | |

| PHILIPS PART NUMBER | PHILIPS PKG | PHILIPS 12 NC NUMBER | WITHDRAWAL NOTICE # | REASON FOR RETENTION OR CORRECTION/DESCRIPTION | SPECIAL COMMENTS |
|---------------------|-------------|----------------------|---------------------|--|--|
| | | | | | |
| BYD43-20 | SOD81 | 934015540133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYD33M | SOD81 | 933741030133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYD33D | SOD81 | 933723400133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYD33G | SOD81 | 933723410133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYD33J | SOD81 | 933723420133 | DN40 | Re-activate -Retention of single Ammopack | |
| 1N4002ID | SOD81 | 933771190133 | DN40 | Re-activate -Retention of single Ammopack | |
| 1N4003ID | SOD81 | 933771200133 | DN40 | Re-activate -Retention of single Ammopack | |
| 1N4004ID | SOD81 | 933771210133 | DN40 | Re-activate -Retention of single Ammopack | |
| 1N4007ID | SOD81 | 933771240133 | DN40 | Re-activate -Retention of single Ammopack | |
| 1N4007ID/EB | SOD81 | 934038830133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYD13D | SOD81 | 933737730133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYD13G | SOD81 | 933737740133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYD13J | SOD81 | 933737750133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYD13K | SOD81 | 933737760133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYD13M | SOD81 | 933737770133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYD73G | SOD81 | 933753800133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYD73A | SOD81 | 933753740133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYD73B | SOD81 | 933753750133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYD73C | SOD81 | 933753760133 | DN40 | Re-activate -Retention of single Ammopack | |
| BYD73D | SOD81 | 933753770133 | DN40 | Re-activate -Retention of single Ammopack | |
| NE564 | N | 933350660602 | DN38 | Phase-Locked Loop | Re-Activate |
| NE567 | N | 933239150602 | DN38 | Re-activate -Tone Decoder/Phase-Locked Loop | Re-Activate |
| SA575 | N | 933887780112 | DN37 | Low Voltage Compandor | Re-Activate |
| SE564 | N | 935020600602 | DN38 | Phase-Locked Loop | Re-Activate |
| SE567 | D | 933953550602 | DN37 | Tone Decoder/Phase-Locked Loop | Re-Activate |
| SE567 | D | 933953550118 | DN37 | Tone Decoder/Phase-Locked Loop | Re-Activate |
| SE567 | N | 933293760602 | DN36 | Tone Decoder/Phase-Locked Loop | Re-Activate |
| 74HC9114 | N | 933987770112 | DN40 | 9 Wide Schmitt Trigger Inv | Re-activate. Contact Marketing for Availability. |
| 74HC9114 | D | 933987780112 | DN40 | 10 Wide Schmitt Trigger Inv | Re-activate. Contact Marketing for Availability. |
| 74HC9114 | D | 933987780118 | DN40 | 11 Wide Schmitt Trigger Inv | Re-activate. Contact Marketing for Availability. |
| 74HC9114 | U | 933987790005 | DN40 | 12 Wide Schmitt Trigger Inv | Re-activate. Contact Marketing for Availability. |
| 74HCT9114 | N | 933987800112 | DN40 | 9 Wide Schmitt Trigger Inv | Re-activate. Contact Marketing for Availability. |

| PHILIPS PART NUMBER | PHILIPS PKG | PHILIPS 12 NC NUMBER | WITHDRAWAL NOTICE # | REASON FOR RETENTION OR CORRECTION/DESCRIPTION | SPECIAL COMMENTS |
|---------------------|-------------|----------------------|---------------------|--|--|
| 74HCT9114 | D | 933987810112 | DN40 | 9 Wide Schmitt Trigger Inv | Re-activate. Contact Marketing for Availability. |
| 74HCT9114 | D | 933987810118 | DN40 | 9 Wide Schmitt Trigger Inv | Re-activate. Contact Marketing for Availability. |
| 74HCT9114 | U | 933987820005 | DN40 | 9 Wide Schmitt Trigger Inv | Re-activate. Contact Marketing for Availability. |
| 74HC7403 | N | 933999360112 | DN40 | 4-Bit X 64-Word FIFO | Re-activate, Contact Marketing for Availability |
| 74HC7403 | D | 933999370112 | DN40 | 4-Bit X 64-Word FIFO | Re-activate, Contact Marketing for Availability |
| 74HC7403 | D | 933999370118 | DN40 | 4-Bit X 64-Word FIFO | Re-activate, Contact Marketing for Availability |
| 74HCT7403 | N | 933999380112 | DN40 | 4-Bit X 64 Word Fifo | Re-activate, Contact Marketing for Availability |
| 74HCT7403 | D | 933999390112 | DN40 | 4-Bit X 64 Word Fifo | Re-activate, Contact Marketing for Availability |
| 74HCT7403 | D | 933999390118 | DN40 | 4-Bit X 64 Word Fifo | Re-activate, Contact Marketing for Availability |
| 74LV4094 | D | 935088040112 | DN40 | 8-Bit Shift and Store Register | Re-activate, Contact Marketing for Availability |
| 74LV4094 | D | 935088040118 | DN40 | 8-Bit Shift and Store Register | Re-activate, Contact Marketing for Availability |
| 74LV4094 | N | 935088050112 | DN40 | 8-Bit Shift and Store Register | Re-activate, Contact Marketing for Availability |
| 74LV4094 | DB | 935166090112 | DN40 | 8-Bit Shift and Store Register | Re-activate, Contact Marketing for Availability |
| 74LV4094 | DB | 935166090118 | DN40 | 8-Bit Shift and Store Register | Re-activate, Contact Marketing for Availability |
| 74LV4094 | PW | 935175020112 | DN40 | 8-Bit Shift and Store Register | Re-activate, Contact Marketing for Availability |
| 74LV4094 | PW | 935175020118 | DN40 | 8-Bit Shift and Store Register | Re-activate, Contact Marketing for Availability |
| 74LV4094 | PW | 935175020512 | DN40 | 8-Bit Shift and Store Register | Re-activate, Contact Marketing for Availability |
| 74LV4094 | PW | 935175020518 | DN40 | 8-Bit Shift and Store Register | Re-activate, Contact Marketing for Availability |
| 74LV251 | D | 935156080112 | DN40 | 8-Input Multiplexer | Re-activate, Contact Marketing for Availability |
| 74LV251 | D | 935156080118 | DN40 | 8-Input Multiplexer | Re-activate, Contact Marketing for Availability |
| 74LV251 | N | 935156090112 | DN40 | 8-Input Multiplexer | Re-activate, Contact Marketing for Availability |
| 74LV251 | DB | 935166050112 | DN40 | 8-Input Multiplexer | Re-activate, Contact Marketing for Availability |
| 74LV251 | DB | 935166050118 | DN40 | 8-Input Multiplexer | Re-activate, Contact Marketing for Availability |
| 74LV251 | PW | 935174670112 | DN40 | 8-Input Multiplexer | Re-activate, Contact Marketing for Availability |
| 74LV251 | PW | 935174670118 | DN40 | 8-Input Multiplexer | Re-activate, Contact Marketing for Availability |
| 74LV251 | PW | 935174670512 | DN40 | 8-Input Multiplexer | Re-activate, Contact Marketing for Availability |
| 74LV251 | PW | 935174670518 | DN40 | 8-Input Multiplexer | Re-activate, Contact Marketing for Availability |
| 74LV174 | D | 935067470112 | DN40 | HEX D-Type Flip Flop | Re-activate, Contact Marketing for Availability |
| 74LV174 | D | 935067470118 | DN40 | HEX D-Type Flip Flop | Re-activate, Contact Marketing for Availability |
| 74LV174 | N | 935067480112 | DN40 | HEX D-Type Flip Flop | Re-activate, Contact Marketing for Availability |
| 74LV174 | DB | 935166040112 | DN40 | HEX D-Type Flip Flop | Re-activate, Contact Marketing for Availability |
| 74LV174 | DB | 935166040118 | DN40 | HEX D-Type Flip Flop | Re-activate, Contact Marketing for Availability |

| PHILIPS PART NUMBER | PHILIPS PKG | PHILIPS 12 NC NUMBER | WITHDRAWAL NOTICE # | REASON FOR RETENTION OR CORRECTION/DESCRIPTION | SPECIAL COMMENTS |
|---------------------|-------------|----------------------|---------------------|--|---|
| 74LV174 | PW | 935174550112 | DN40 | HEX D-Type Flip Flop | Re-activate, Contact Marketing for Availability |
| 74LV174 | PW | 935174550118 | DN40 | HEX D-Type Flip Flop | Re-activate, Contact Marketing for Availability |
| 74LV174 | PW | 935174550512 | DN40 | HEX D-Type Flip Flop | Re-activate, Contact Marketing for Availability |
| 74LV174 | PW | 935174550518 | DN40 | HEX D-Type Flip Flop | Re-activate, Contact Marketing for Availability |
| 74HC7731 | N | 935020950112 | DN40 | Quad 64-Bit Static Shift Rgst | Re-activate, Contact Marketing for Availability |
| 74HC7731 | D | 935020970112 | DN40 | Quad 64-Bit Static Shift Rgst | Re-activate, Contact Marketing for Availability |
| 74HC7731 | D | 935020970118 | DN40 | Quad 64-Bit Static Shift Rgst | Re-activate, Contact Marketing for Availability |
| 74HCT7731 | N | 935020960112 | DN40 | Quad 64-Bit Static Shift Rgst | Re-activate, Contact Marketing for Availability |
| 74HCT7731 | D | 935020980112 | DN40 | Quad 64-Bit Static Shift Rgst | Re-activate, Contact Marketing for Availability |
| 74HCT7731 | D | 935020980118 | DN40 | Quad 64-Bit Static Shift Rgst | Re-activate, Contact Marketing for Availability |
| N74F776AQ | | | DN40 | | Re-activate |
| N74F862 | | | DN40 | | Re-activate |
| S87C552 | | | DN40 | | Re-activate. Contact Sunnyvale Microcontroller Group. |
| SA568AD | | 935060520602 | DN37 | Demand Change | Re-activate |
| SA568AD/T | | 935060520118 | DN37 | Demand Change | Re-activate |
| CP2121A | | 935205150557 | DN40 | Demand Change | Re-activate |
| TDA1313 | | | | | |
| CV2953 | B44 | 935134920557 | DN38 | Reinstate to RFS(Code 1) | Re-activate |
| CV3862 | B | 935260546518 | DN38 | Reinstate to RFS(Code 1) | Re-activate |
| CV3862 | B | 935260546557 | DN38 | Reinstate to RFS(Code 1) | Re-activate |
| CV3229 | N40 | 935136270112 | DN38 | Reinstate to RFS(Code 1) | Re-activate |
| CV3250 | A44 | 935136380118 | DN38 | Reinstate to RFS(Code 1) | Re-activate |
| CV2994 | N40 | 935135220112 | DN38 | Reinstate to RFS(Code 1) | Re-activate |
| CV5133 | N40 | 935260519112 | DN38 | Reinstate to RFS(Code 1) | Re-activate |
| CV3227 | A44 | 935136260112 | DN38 | Reinstate to RFS(Code 1) | Re-activate |
| CV5137 | A44 | 935260598112 | DN38 | Reinstate to RFS(Code 1) | Re-activate |
| CV5137 | A44 | 935260598118 | DN38 | Reinstate to RFS(Code 1) | Re-activate |

| PHILIPS PART NUMBER | PHILIPS PKG | PHILIPS 12 NC NUMBER | WITHDRAWAL NOTICE # | REASON FOR RETENTION OR CORRECTION/DESCRIPTION | SPECIAL COMMENTS |
|---|-------------|----------------------|---------------------|--|------------------|
| CV3252 | A44 | 935136390112 | DN38 | Reinstate to RFS(Code 1) | Re-activate |
| CV3838 | N | 935229200112 | DN38 | Reinstate to RFS(Code 1) | Re-activate |
| CV3865 | N | 935260776112 | DN38 | Reinstate to RFS(Code 1) | Re-activate |
| CV5139 | N40 | 935260663112 | DN38 | Reinstate to RFS(Code 1) | Re-activate |
| PCF8579HT/F1 | VSO56 | 9351870706 | DN38 | Reinstate | Re-activate |
| B: The following corrections are made to previously discontinued products. | | | | | |
| S87C552-4 | BA | 935177960551 | | P87C552UBB BA will not be available. | |
| BYG90-90 | | 934037200115 | DN40 | This product was discontinued as of DN40.Correction of Typo. | |
| | | | | | |
| | | | | | |