


CARRIER TAPE FOR MLP55-28L, MLP55-32L



Note

1. 10 sprocket hole pitch cumulative tolerance ± 0.2 .
2. Camber not to exceed 1 mm in 100 mm.
3. Material: black conductive polycarbonate.
4. Pocket position relative to sprocket hole measured as true position of pocket, not pocket hole.
5. All size in mm unless specified.

ECN: T09-0071-Rev. B, 16-Mar-09
 DWG: 93-5260-x