



TLA432-50: C4, C9, C11 entfallen

SSB-Electronic GmbH W.-Germany

TLA144-80 / TLA432-50

Zeichnungsnummer : 0050 Datum : 09.12.88