

7000 SERES O SANT MATINATER S

Agilent E1412A

Agilent E1412A 6.5-Digit High-Accuracy Multimeter, C-Size

Data Sheet

- 1-Slot, C-size, message based
- DCV, ACV, DCI, ACI, 2/4-wire Ω , frequency, period
- NULL, MIN/MAX, LIMIT, dB, dBm
- 1000 reading/s into internal memory at 4.5 digits
- Fast range/function changes
- Reading storage with internal memory

Description

The Agilent Technologies E1412A 6.5-Digit Multimeter is a **C-size, 1-slot, message-based VXI module.** It is identical in electrical design to the E1312A, differing only in size. It delivers the widest functionality in Agilent's DMM line. It also delivers high performance and Agilent high quality at prices you'd expect to pay for a 5.5-digit DMM.

This multimeter's wide product functionality includes volts, amps, ohms, and frequency with advanced tests including limit checks to drive a TTL output and dc voltage ratios. Standard measurements include ac/dc voltage, ac/dc current, 2- and 4-wire Ω , plus frequency/period. When measuring dcV, this multimeter can deliver 65 range changes per second and 30 function changes per second.

Refer to the Agilent Technologies Website for instrument driver availability and downloading instructions, as well as for recent product updates, if applicable.

Product Specifications

dc Specifications

Specifications are for 1-hour warm-up at an integration time of 100 PLCs.

dc Summary

dc voltage: 300 V max. ± 0.0019% Voltage accuracy (dc):

dc Accuracy ± (% of reading + % of range):

Specifications are for 1-hour warm-up at 6.5 digits.

dc voltage:

Range ⁽²⁾	Test Current or Burden Voltage	24 Hour ⁽¹⁾ 23° C ± 1° C	90 Day 23° C ± 5° C	1 Year 23° C ± 5° C	Temperature Coefficient 0° C - 18° C 28° C - 55° C
100.0000 mV		0.0030 + 0.0030	0.0040 + 0.0035	0.0050 + 0.0035	0.0005 + 0.0005
1.000000 V		0.0020 + 0.0006	0.0030 + 0.0007	0.0040 + 0.0007	0.0005 + 0.0001
10.00000 V		0.0015 + 0.0004	0.0020 + 0.0005	0.0035 + 0.0005	0.0005 + 0.0001
100.0000 V		0.0020 + 0.0006	0.0035 + 0.0006	0.0045 + 0.0006	0.0005 + 0.0001
300.0000 V		0.0020 + 0.0018	0.0035 + 0.0030	0.0045 + 0.0030	0.0005 + 0.0003
Range					
Resistance: ⁽³⁾	Test Current or Burden Voltage	24 Hour ⁽¹⁾ 23° C ± 1° C	90 Day 23° C ± 5° C	1 Year 23° C ± 5° C	Temperature Coefficient 0° C - 18° C
					28° C - 55° C
100.0000 Ω	1 mA	0.0030 + 0.0030	0.008 + 0.004	0.010 + 0.004	0.0006 + 0.0005
1.000000 kΩ	1 mA	0.0020 + 0.0005	0.008 + 0.001	0.010 + 0.001	0.0006 + 0.0001
10.00000 kΩ	100 μΑ	0.0020 + 0.0005	0.008 + 0.001	0.010 + 0.001	0.0006 + 0.0001
100.0000 kΩ	10 μΑ	0.0020 + 0.0005	0.008 + 0.001	0.010 + 0.001	0.0006 + 0.0001
1.000000 M Ω	5 μΑ	0.002 + 0.001	0.008 + 0.001	0.010 + 0.001	0.0010 + 0.0002
10.00000 M Ω	500 nA	0.015 + 0.001	0.035 + 0.001	0.054 + 0.001	0.0030 + 0.0004
100.0000 M Ω	500 nA \parallel 10 M Ω	0.300 + 0.010	0.800 + 0.010	0.800 + 0.010	0.1500 + 0.0002
Range					
dc current:	Test Current or	24 Hour	90 Day	1 Year	Temperature Coefficient
	Burden Voltage	23° C ± 1° C	23° C ± 5° C	23° C ± 5° C	0° C - 18° C 28° C - 55° C
10.00000 mA	<0.1 V	0.005 + 0.010	0.050 + 0.020	0.070 + 0.020	0.005 + 0.0020
100.0000 mA	<0.6 V	0.01 + 0.004	0.040 + 0.005	0.070 + 0.005	0.006 + 0.0005
1.000000 A	<1 V	0.10 + 0.006	0.130 + 0.010	0.150 + 0.010	0.005 + 0.0010
3.000000 A dc:dc Ratio:	<2 V	0.70 + 0.020	0.720 + 0.020	0.720 + 0.020	0.005 + 0.0020

Range⁽²⁾

100 mV to 300 V:

(Input Accuracy) + (Reference Accuracy) Input Accuracy = accuracy specification for the HI-LO input signal Reference Accuracy = accuracy specification for HI-LO reference input signal

Null, add 0.2 Ω additional error in 2-wire Ω function.

⁽¹⁾ Relative to calibration standards.

^{(2) 20%} overrange on all ranges, except 300 Vdc and 3 A range.

⁽³⁾ Specifications are for 4-wire Ω function, or 2-wire Ω using Math Null, Without Math

dc Voltage Characteristics

Measurement method: Continuously integrating, multi-slope

III A/D converter

A/D linearity: 0.0002% of reading + 0.0001% of

range

2/4-wire Ω : 100 M Ω

Input resistance:

0.1 V, 1 V, 10 V ranges: Selectable 10 M Ω or 10 G Ω

100 V, 300 V ranges: 10 M Ω ± 1% Input bias current: <30 pA at 25° C Input terminals: Copper alloy Input protection: 300 V on all ranges

Resistance

Measurement method: Selectable 4-wire or 2-wire Ω (Current

source referenced to low input)

Max. lead resistance: (4-wire Ω) 10% of range per lead for 100 Ω and 1 $k\Omega$ per lead on all other dc Current

ranges

Input protection: 300 V on all ranges

Shunt resistor: 0.1 Ω for 1 A and 3 A, 5 Ω for 10 mA

and 100 mA

Externally accessible 3 A, 250 V fuse Input protection:

Measurement Noise Rejection

60 Hz (50 Hz) (For 1 k Ω unbalance in LO lead.)

dc CMMR: 140 dB

Normal mode rejection(1) **Integration Time** 100 PLC/1.67s (2s) 60 dB⁽²⁾

10 PLC/167 ms (200 ms) 60 dB(2) 1 PLC/16.7 ms (20 ms) 60 dB(2) 0 dB <1 PLC/3 ms (800 μs)

(1) For power-line frequency \pm 0.1%.

(2) For power-line frequency \pm 1%, subtract 20 dB; for \pm 3%, subtract 30 dB.

(Speeds are for 4.5 digits, Delay 0 and Autozero OFF. Includes measurement and data transfer over VXI backplane.)

Function change: 30/s Range change: 65/s <30 ms Autorange time: 1000/s Max. internal trigger rate: Max. external trigger rate to memory: 1000/s

dc:dc Ratio

Measurement method: Input HI-LO/Reference HI-LO

Apply "Reference HI-LO" signal to Ohms 4-Wire Sense terminals."

Input HI to Input LO: 100 mV to 300 V

Reference HI to Input LO: <12 V on 100 mV to 10 V ranges

(autoranged)

Reference LO to Input LO: <2 V

Additional Error with Autozero OFF

Following instrument warm-up at calibration temperature \pm 1° C and <10 minutes.

100mV-100V ranges: add 0.0002% reading + 5 μV add 0.0006% reading 300 V range:

dc Operating Characteristics

Readings speeds for 60 Hz and (50 Hz) operation, Autozero OFF.

Function	NPLC	Digits	Reading/s	Additional Noise Error
DCV, DCI and Ω	100	6.5	0.6 (0.5)	0% of range
DCV, DCI and Ω	10	6.5	6 (5)	0% of range
DCV, DCI and Ω	1	5.5	60 (50)	0.001% of range*
DCV, DCI and Ω	.2	5.5	300	0.001% of range*
DCV, DCI and Ω	.02	4.5	1,000	0.01% of range*

*For 300 V range: use 0.003% of range for 5.5 digits and 0.030% of range for 4.5 digits. For all ranges: add 20 μV for dc Volts, 4 μA for dc current, or 20 $m\Omega$ for resistance.

Considerations

Settling considerations: Reading settling times are affected by

source impedance, cable dielectric characteristics, and input signal

Agilent recommends the use of Teflon Measurement considerations:

or other high impedance, lowdielectric absorption wire insulation

for these measurements.

ac Specifications

ac Summary

ac voltage: 300 V max. Voltage accuracy (ac): \pm 0.07%

ac Accuracy \pm (% of reading + % of range):

Specifications are for 1-hour warm-up at 6.5 digits,

Slow ac filter, sinewave input.

True RMS ac Voltage⁽³⁾:

Range ⁽²⁾	Frequency	24 Hour ⁽¹⁾ 23° C ± 1° C	90 Day 23° C ± 5° C	1 Year 23° C ± 5° C	Temperature Coefficient 0° C - 18° C 28° C - 55° C
100.0000 mV	3 Hz-5 Hz	1.00 + 0.03	1.00 + 0.04	1.00 + 0.04	0.100 + 0.004
100.0000 mV	5 Hz-10 Hz	0.35 + 0.03	0.35 + 0.04	0.35 + 0.04	0.035 + 0.004
100.0000 mV	10 Hz-20 kHz	0.04 + 0.03	0.05 + 0.04	0.06 + 0.04	0.005 + 0.004
100.0000 mV	20 kHz-50 kHz	0.10 + 0.05	0.11 + 0.05	0.12 + 0.05	0.011 + 0.005
100.0000 mV	50 kHz-100 kHz	0.55 + 0.08	0.60 + 0.08	0.60 + 0.08	0.060 + 0.008
100.0000 mV	100 kHz-300 kHz	5.00 + 0.50	5.00 + 0.50	5.00 + 0.50	0.020 + 0.020
1.000000 V to 300.000 V ⁽⁴⁾	3 Hz-5 Hz	1.00 + 0.02	1.00 + 0.03	1.00 + 0.03	0.100 + 0.003
1.000000 V to 300.000 V ⁽⁴⁾	5 Hz-10 Hz	0.35 + 0.02	0.35 + 0.03	0.35 + 0.03	0.035 + 0.003
1.000000 V to 300.000 V ⁽⁴⁾	10 Hz-20 kHz	0.04 + 0.02	0.05 + 0.03	0.06 + 0.03	0.005 + 0.003
1.000000 V to 300.000 V ⁽⁴⁾	20 kHz-50 kHz	0.10 + 0.04	0.11 + 0.05	0.12 + 0.05	0.011 + 0.005
1.000000 V to 300.000 V ⁽⁴⁾	50 kHz-100 kHz	0.55 + 0.08	0.60 + 0.08	0.06 + 0.08	0.060 + 0.008
1.000000 V to 300.000 V ⁽⁴⁾	100 kHz-300 kHz ⁽⁵⁾	5.00 + 0.50	5.00 + 0.50	5.00 + 0.50	0.200 + 0.020

True RMS ac Current(3):

Range	Frequency	24 Hour 23° C ± 1° C	90 Day 23° C ± 5° C	1 Year 23° C ± 5° C	Temperature Coefficient 0° C - 18° C 28° C - 55° C
1.000000 A	3 Hz-5 Hz	1.05 + 0.04	1.05 + 0.04	1.05 + 0.04	0.100 + 0.006
1.000000 A	5 Hz-10 Hz	0.35 + 0.04	0.35 + 0.04	0.35 + 0.04	0.035 + 0.006
1.000000 A	10 Hz-1 kHz	0.15 + 0.04	0.15 + 0.04	0.15 + 0.04	0.015 + 0.006
1.000000 A	1 kHz-50 kHz	0.40 + 0.04	0.40 + 0.04	0.40 + 0.04	0.015 + 0.006
3.000000 A	3 Hz-5 Hz	1.70 + 0.06	1.70 + 0.06	1.70 + 0.06	0.100 + 0.006
3.000000 A	5 Hz-10 Hz	0.95 + 0.06	0.95 + 0.06	0.95 + 0.06	0.035 + 0.006
3.000000 A	10 Hz-1 kHz	0.75 + 0.06	0.75 + 0.06	0.75 + 0.06	0.015 + 0.006
3.000000 A	1 kHz-50 kHz	1.00 + 0.06	1.00 + 0.06	1.00 + 0.06	0.15 + 0.06

⁽¹⁾ Relative to calibration standards.

^{(5) 300} Vac range limited to 50 kHz. For frequencies >50 kHz, signals must be \leq 1.5 x 10⁷ VHz.

Additional ac S	pecificat	ions:				Ī
	req. Erro f reading				ctor Errors inewave)*	(l
Frequency	Slow	ac Filter Medium	Fast	Crest Factor	Error (% of reading)	
10 Hz-20 Hz	0	0.74	_	1-2	0.05%	
20 Hz-40 Hz	0	0.22	_	2-3	0.15%	
40 Hz-100 Hz	0	0.06	0.73	3-4	0.30%	
100 Hz-200 Hz	0	0.01	0.22	4-5	0.40%	
200 Hz-1 kHz	0	0	0.18			
>1 kHz	0	0	0			

^{*}For frequencies below 100 Hz, slow ac filter specified for sinewave input only.

Noise Rejection

(For 1 k Ω unbalance in LO lead.)

c CMMR: 70 dB

^{(2) 20%} overrange on all ranges, except 300 Vac and 3A ranges which have 1% overrange.

^{(3) 100} mV to 100 V range specifications are for sine wave input >5% of range. For inputs from 1% to 5% of range and <50 kHz, add 0.1% of range additional error. For 50 kHz to 100 kHz, add 0.13% additional error. 300 V range specifications are for sinewave input >15% of range. For inputs from 3% to 15% of range and >50 kHz, add 0.30% of kHz, add 0.40% of range additional error.

⁽⁴⁾ For 300 V range, use (% reading) shown in table and multiply each (% range) \times 3.

True RMS ac Voltage

Measurement method: ac-coupled True RMS — measures

the ac component of the input with up to 300 Vdc of bias on any range. (Max ac+dc = 300 V rms.)

Crest factor: Maximum 5:1 at full scale

ac filter bandwidth:

 Slow:
 3 Hz-300 kHz

 Medium:
 20 Hz-300 kHz

 Fast:
 200 Hz-300 kHz

Input impedance: 1 M Ω ±2%, in parallel with 100 pF

Input protection: 300 Vrms all ranges

True RMS ac Current	
Measurement method:	Direct couple to the fuse and shunt. ac-coupled True RMS measurement (measures the ac component only).
Shunt resistor:	0.1 Ω for 1 A and 3 A ranges
Burden voltage: 1A range: 3A range:	<1 Vrms <2 Vrms
Input protection:	Externally accessible 3 A, 250 V fuse

ac Operating Characteristics

Maximum reading rates 0.01% of ac step additional error. Additional settling delay required when input dc level varies.

Function	Digits	Reading/s	ac Filter
ACV and ACI	6.5	7 s/reading	Slow
ACV and ACI	6.5	1	Medium
ACV and ACI	6.5	1.6 ⁽¹⁾	Fast
ACV and ACI	6.5	10	Fast
ACV and ACI	6.5	50 ⁽²⁾	Fast

(1) For External Trigger or remote operation using default settling delay (Delay Auto).

(2)Maximum useful limit with default settling delays used.

Frequency and Period Specifications

Frequency and Period Accuracy (% of reading)

Specifications are for 1-hour warm-up at 6.5 digits.

Function	Range ⁽²⁾	Frequency	24 Hour ⁽¹⁾ 23° C ± 1° C	90 Day 23° C ± 5° C	1 Year 23° C ± 5° C	Temperature Coefficient 0° C - 18° C 28° C - 55° C
Frequency, Period	100 mV to 300 V	3 Hz-5 Hz	0.10	0.10	0.10	0.005
Frequency, Period	100 mV to 300 V	5 Hz-10 Hz	0.05	0.05	0.06	0.005
Frequency, Period	100 mV to 300 V	10 Hz-40 Hz	0.03	0.03	0.03	0.001
Frequency, Period	100 mV to 300 V	40 Hz-300 kHz	0.006	0.01	0.01	0.001

⁽¹⁾ Relative to calibration standards.

(2) 20% overrange on all ranges, except 300 Vac range which has 1% overrange.

Systems Speeds

Autorange time:

Maximum useful limit with default settling delays used; Speeds are for $4.5 \ \text{digits}$, Delay 0, and Fast ac filter.

Function or range change:

5/s <0.8 s

50/sec

ASCII reading to GPIB:

Max. internal trigger rate: 50/s

 $\label{eq:max.prop} \textbf{Max. external trigger rate to memory:} \quad 50/s$

Additional Low-Frequency Errors (% of reading)

Input >100 mV. For mV input, multiply % of reading error x 10.

Frequency	6.5 digits	5.5 digits	4.5 digits
3 Hz-5 Hz	0	0.12	0.12
5 Hz-10 Hz	0	0.17	0.17
10 Hz-40 Hz	0	0.2	0.2
40 Hz-100 Hz	0	0.06	0.21
100 Hz-300 Hz	0	0.03	0.21
300 Hz-1 kHz	0	0.01	0.07
>1 kHz	0	0	0.02

Measuring Characteristics Reciprocal-counting technique. accoupled input using the ac voltage measurement function. Measurement method: Voltage ranges: 100 mV rms full scale to 300 V rms. Auto or manual ranges. Gate time: 10 ms, 100 ms, or 1 s Errors will occur when attempting to **Settling considerations:** measure the frequency or period of an input following a dc offset voltage change. The input blocking RC time constant must be allowed to fully settle (up to 1 s) before the most accurate measurements are possible. All frequency counters are susceptible Measurement considerations: to error when measuring low-voltage, low-frequency signals. Shielding inputs from external noise pickup is critical for minimizing measurement

	critical for minimizing measurem errors.		
Max. reading rate:	1K		
Operating Characteristics			
Speeds are for 4.5 digits, Delay 0, and Fa	ast ac filter.		
	Digits	Reading/s	
Frequency, Period	6.5	1	
	5.5	9.8	
Frequency, Period	4.5	80	
Systems Speeds			
Configuration rates:	14/s		
Autorange time:	<0.6 s		
Max. internal trigger rate:	80/s		
Max. external trigger rate to memory:	80/s		

max. meeriar erigger rate.	00/0
Max. external trigger rate to memory:	80/s
Characteristics	
Warmup time:	1 hour
State storage memory:	Power-off state automatically saved
Functions	
ldc:	3 A
lac:	3 A
Frequency:	300 kHz
Period:	3.3 μs
	Tm, Tc, RTD

General Specifications

VXI Characteristics		
VXI device type:	Message based	
Data transfer bus:	A16	
Size:	С	
Slots:	1	
Connectors:	P1/2	
Shared memory:	n/a	
VXI buses:	n/a	

Instrument Drivers - See the Agilent Technologies Website (http://www.agilent.com/find/inst_drivers) for driver availability and downloading.

n/a
n/a
No
Yes
Yes
No

	_	_	
	I _{PM}	I _{DM}	
+5 V:	0.2	0.1	
+12 V:	0.7	0.06	
–12 V:	0	0	
+24 V:	0	0	
–24 V:	0	0	
–5.2 V	0	0	
−2 V:	0	0	

Cooling/Slot		
Watts/slot:	9.40	
Δ P mm H ₂ O:	0.05	
Air Flow liter/s:	0.80	

Ordering Information

Description	Product No.
6.5-Digit Multimeter, High Accuracy	E1412A
ANSI Z540 Compliant Calibration	E1412A A6J

Agilent Technologies' Test and Measurement Support, Services, and Assistance

Agilent Technologies aims to maximize the value you receive, while minimizing your risk and problems. We strive to ensure that you get the test and measurement capabilities you paid for and obtain the support you need. Our extensive support resources and services can help you choose the right Agilent products for your applications and apply them successfully. Every instrument and system we sell has a global warranty. Support is available for at least five years beyond the production life of the product. Two concepts underlie Agilent's overall support policy: "Our Promise" and "Your Advantage."

Our Promise

Our Promise means your Agilent test and measurement equipment will meet its advertised performance and functionality. When you are choosing new equipment, we will help you with product information, including realistic performance specifications and practical recommendations from experienced test engineers. When you use Agilent equipment, we can verify that it works properly, help with product operation, and provide basic measurement assistance for the use of specified capabilities, at no extra cost upon request. Many self-help tools are available.

Your Advantage

Your Advantage means that Agilent offers a wide range of additional expert test and measurement services, which you can purchase according to your unique technical and business needs. Solve problems efficiently and gain a competitive edge by contracting with us for calibration, extra-cost upgrades, out-of-warranty repairs, and on-site education and training, as well as design, system integration, project management, and other professional engineering services. Experienced Agilent engineers and technicians worldwide can help you maximize your productivity, optimize the return on investment of your Agilent instruments and systems, and obtain dependable measurement accuracy for the life of those products.

By internet, phone, or fax, get assistance with all your test & measurement needs.

Online assistance:

www.agilent.com/find/assist

Phone or Fax

United States:

(tel) 1 800 829 4444

Canada:

(tel) 1 877 894 4414 (fax) (905) 282 6495

China:

(tel) 800 810 0189 (fax) 800 820 2816

Europe:

(tel) (31 20) 547 2323 (fax) (31 20) 547 2390

Japan:

(tel) (81) 426 56 7832 (fax) (81) 426 56 7840

Korea:

(tel) (82 2) 2004 5004 (fax) (82 2) 2004 5115

Latin America:

(tel) (305) 269 7500 (fax) (305) 269 7599

Taiwan:

(tel) 0800 047 866 (fax) 0800 286 331

Other Asia Pacific Countries:

(tel) (65) 6375 8100 (fax) (65) 6836 0252 (e-mail) tm_asia@agilent.com

Data Subject to Change © Agilent Technologies, Inc. 2001 Printed in the U.S.A. May 1, 2004 5965-5563E

