ALLEN&HEATH




WARNING — HIGH VOLTAGES


Power Supply Unit (PSU) work should only be carried out by qualified personnel.

We recommend that you use an approved Allen & Heath service centre for all power supply work.

Please contact your local Allen & Heath distributor for more details.

http://www.allen-heath.com/








INSERT SEND


* = GL2-S


INPUT CHANNEL















LINE IN


AUX OUT - STANDARD


SIGNAL


UNBALANCED LINE


RETURN SECTION GL2-S ONLY















GL2 TRANSFORMER - MAINS VIRING



- 7815

- 7915

- TI 783

03

0

0

0

(+)

(4)

(I)

0

PSU CHASSIS AAH72

KERNICK INDUSTRIAL ESTATE.

