## ALLEN&HEATH




## WARNING – HIGH VOLTAGES


## Power Supply Unit (PSU) work should only be carried out by qualified personnel.

We recommend that you use an approved Allen & Heath service centre for all power supply work.


Please contact your local Allen & Heath distributor for more details.

http://www.allen-heath.com/






## DC wiring



ALL VIRES ARE 16/02 UNLESS MARKED VITH \* (eg. BL\*). VIRES MARKED VITH \* (eg. BL\*) ARE 30/0.25.



ALL VIRES 16/02 UNLESS OTHERVISE MARKED

