ALLEN&HEATH




WARNING — HIGH VOLTAGES

Power Supply Unit (PSU) work should only be carried out by qualified personnel.

We recommend that you use an approved Allen & Heath service centre for all power supply work.

Please contact your local Allen & Heath distributor for more details.

http://www.allen-heath.com/



CHASSIS EARTH ARRANGEMENT



M3 NYLOK NUT (AB0102)
4BA EARTH TAGS (AK0002)
M3 HALF NUT (AB0094)
M3 SHAKEPROOF WASHER
(AB0244)
4BA CHASSIS EARTH TAG


STICK EARTH LABEL (AN2799)
NEXT TO EARTH TERMINAL


Main console unit removed for clarity


1 SSUE	REVI SI ON	BY	DATE	DRAWING TITLE	1//F// ALLEN & HEATH
1	PRODUCTION	IMc8	10-2-98		ALLEN GENERAL ESTATE.
				2e-4	PENRYN, CORNWALL TRID 9LU.
				20 -1	1
				BOLL A COEMBLY	HEATH TEL. 01326 372070 FAX. 01326 377097
				PSU ASSEMBLY	DRAWI NG No MACOO 204 ISSUE 1
					DRAW NG No MO02-321 ISSUE 1


2e TRANSFORMER - MAINS WIRING


= SLEEVED & UNCONNECTED.




















































MixWizard** 14:4:2 BLOCK DIAGRAM

