

# Service Technical Information

MODEL NO. ADC-M65 / M105 / EX108 / V107
SUBJECT Combinations of the Series-7 car stereo sets Do not sounds.

REF.No. :G - A0 - 087 - E0

DATE :25. OCT. 2000

<CONTENTS>

In combination of car stereo CD changer and a Series-7 car stereo head unit (see the model numbers listed below), no speaker sounds may be generated when a CD is played. If the actual occurrence of this problem is reported, please undertake the following countermeasure:

<COUNTERMEASURE>

Connect a conductor between Pins 3 and 8 of the DIN connector connected to the FELX DIN P.W.B. of the car stereo CD changer. Use a conductor about 2 cm long.



<NOTE>

The above countermeasure has already been undertaken for the products shipped in and after July 2000.

Relevant models

CDC-R507M	CDC-X507M	CDC-R517M
CDC-R707M	CDC-X707M	CDC-X7070M
CDC-R907M	CDC-X907M	
CT-R427M	CT-X427M	
CT-FR727M	CT-FX727M	
CT-FR927M	CT-FX927M	

G	R	Code No.	Access Code	Modified Ser. No.	Parts Schedule
-	-	-	-	-	-