

# Service Technical Information



MODEL NO. NSX-AJ20 / B75 / BL23 / DR1 / SZ20 etc
SUBJECT Notes on replacing $\mu$ -COM

REF.No. :G - A0 - 073- E0

DATE :25. SEP. 2000

<CONTENTS>

The CD mechanisms mounted on the models above are broadly divided into two different types.  $\mu$ -COM used on the CD mechanisms are not compatible with each other on different types. When replacing  $\mu$ -COM, be sure to identify a CD mechanism with reference to the table below: Determine a type of CD mechanism by a pick up that is mounted.

RDS	Deck Mecha	$\mu$ -COM Version	KSS-213F 	KSM-880 
No	Except 6ZM-3	Old	8A-NF9-604-010 UPD780226GF-015	8A-NF9-601-010 UPD780226GF-012
	6ZM-3	New	8A-NF9-604-110 UPD780226GF-019	8A-NF9-601-110 UPD780226GF-014
			8A-NF9-603-010 UPD780226GF-013	
Yes	Except 6ZM-3	Old		8A-NF9-602-010 UPD780228GF-059
		New	8A-NF9-606-010 UPD780228GF-073	8A-NF9-602-110 UPD780228GF-064

Applicable model

NSX-AJ20 / AJ22 / AJ24 / B75 / BL23 / BL24 / BL26 / BL28 / BL29 / BL34  
DR1 / DR5 / SZ20 / SZ21 / SZ22 / SZ23 / SZ27 / SZ30 / SZ35 / SZ36

<NOTE>

If a  $\mu$ -COM of an old version is mounted, replace it with one of a new version.

Ref.	Parts Code	Description	Remarks
IC901	8A-NF9-601-110	C-IC,UPD780226GF-014	AZG-1 ZD8
IC901	8A-NF9-602-110	C-IC,UPD780228GF-064	AZG-1 ZD8
IC901	8A-NF9-603-010	C-IC,UPD780226GF-013	AZG-1 ZD8
IC901	8A-NF9-604-110	C-IC,UPD780226GF-019	AZG-1ZD3 / ZD4
IC901	8A-NF9-606-010	C-IC,UPD780228GF-073	AZG-1ZD3 / ZD4

G	R	Code No.	Access Code	Modified Ser. No.	Parts Schedule
-	-	-	-	-	NOV.2000