


Heated Pentode Refrigerant Detector
12 Volt Battery Charger

Caution: Batteries should only be charged in temperatures between 50°F-104°F (10°C-40°C). Charging batteries outside this temperature range may cause permanent damage to batteries.



1. Install battery pack into detector or optional charging base.
2. Insert male plug into the charging jack under the handgrip of the detector or the jack in the optional charging base.
3. Insert "cigarette lighter" adapter into 12V-power receptacle.
4. When properly connected the LED on the unit or charging base will indicate the charging status.
5. New or completely discharged batteries will take approximately two (2) hours to fully re-charge. When the LED indicates that the batteries are fully charged, the unit is ready for operation.