

United States Of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate

Number SA00165BO

This Certificate issued to Avidyne Corporation
55 Old Bedford Road
Lincoln, Massachusetts 01773

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations.

Original Product Type Certificate Number : See attached FAA-Approved Model List (AML), Document No. AVACP-020, Rev (-), dated February 20, 2003, or later FAA-approved revisions for the list of approved airplane models and applicable regulations.
Make :
Model :

Description of Type Design Change:

Installation of Avidyne Corporation Datalink Coupler, Part Number 700-00015-000, in accordance with Avidyne Corporation Master Document List, Document No. AVACP-006, Revision 00, dated January 2, 2003, or later FAA-approved revisions.

Limitations and Conditions :

1. Instructions for Continued Airworthiness (ICA), Avidyne Corporation Document AVACP-009, Revision 01, dated January 2, 2003, or later FAA accepted revision shall be made available to the operator at the time of installation.
2. Compatibility of this design change with previously approved modifications must be determined by the installer.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : October 31, 2002

Date reissued :

Date of issuance : February 20, 2003

Date amended :



By direction of the Administrator

Robert G. Mann
(Signature)

Robert G. Mann
Manager
Boston Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.