AV360C Color Image Scanner

User's Manual

Version 1.0

(D/N 250-0009-0)

© Avision Inc. 1996

Trademarks

Microsoft is a U.S. registered trademark of Microsoft Corporation.

Windows and MS-DOS are trademarks of Microsoft Corporation.

IBM, PC, AT, XT are registered trademarks of International Business Machines Corp.

Other brands and product names herein are trademarks or registered trademarks of their respective holders.

Copyright

All rights reserved. No part of this publication may be reproduced, transmitted, transcribed, stored in a retrieval system, or translated into any language or computer language, in any form or by any means, electronic, mechanical, magnetic, optical, chemical, manual, or otherwise, without the prior written permission of Avision.

Material scanned by this product may be protected by governmental laws and other regulations, such as copyright laws, the customer is solely responsible for complying with all such laws and regulations.

Warranty

The information contained in this document is subject to change without notice

Avision makes no warranty of any kind with regard to this material, including, but not limited to, the implied warranties of fitness for a particular purpose.

Avision shall not be liable for errors contained herein or for incidental or consequential damages in connection with the furnishing, performance, or use of this material.

FCC Radio Frequency Interference Statement

This equipment has been tested and found to comply with the limits for a class B digital device, pursuant to Part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communication. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- * Reorient or relocate the receiving antenna.
- * Increase the separation between the equipment and receiver.
- * Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- * Consult the dealer or an experienced radio/TV technician for help.

CAUTION: Any changes or modifications not expressly approved by the manufacture of this device could void the user's authority to operate the equipment.

Table of Contents


1. INTRODUCTION	1-1
2. SCANNER INSTALLATION	2-1
2.1 INSTALLATION OF THE SCANNER	2-1
2.2 UNLOCKING THE SCANNER	
2.3 CONNECTING THE CABLE.	
2.4 DOCUMENT PLACEMENT	2-4
3. SCANNER DRIVER INSTALLATION	3-1
3.1 Auto-InstallationProgram	3-1
3.2 Uninstall the Scanner	
4SCANNER OPERATION & DOCUMENT PRINTING	4-1
4.1 ImageType	4-3
4.2 SCANNING PARAMETERS & IMAGE CONTROL	4-4
4.3 SCANNING.	4-7
4.4 Printing	
5. MAINTENANCE	5-1
6. TROUBLESHOOTING	6-1
6.1 Questions and Answers	6-2
6.2 TECHNICAL SERVICE	
7. SPECIFICATIONS	7-1
7.1 Model: AV260C	7 1

1. Introduction

Congratulations on your purchase of Avision AV360C color image scanner. Avision is one of the leading companies in the world to develop high performance scanners.

Before you install and operate the new scanner, please take a few minutes to read through this manual. It provides you with the proper instructions on how to unpack, install, operate and maintain the scanner.

Figure 1-1 shows how the scanner is packed. Please check all the items against your checklist. If you did not receive all the items, please contact your authorized local dealer immediately.



Manual, Driver Kit, AC Power Cord, D25P Cable, etc.
Scanner
Cushion
Carton

Figure 1-1 Scanner packing

2. Scanner Installation

Precautions


- * Keep the scanner out of direct sunlight. Direct exposure to the sun or excessive heat may cause damage to the unit.
- * Do not install the scanner in a humid or dusty place.
- * Be sure to use the proper AC power source.
- * Place the scanner securely on an even, flat surface. Tilted or uneven surfaces may cause mechanical or paper-feeding problems.
- * Retain the scanner box and packing materials for shipping purposes.

2.1 Installation of the Scanner

Please unpack the packing carefully, and check the contents against the checklist. If any items are missing or damaged, please contact your dealer immediately.

2.2 Unlocking the Scanner

As shown below, unlock the scanner by turning the scanner lock to the "use" position.




1. Shipping position

2. Use position

Figure 2-1 Unlocking the Scanner

2.3 Connecting the Cable

Connect the power cable and signal cable as shown below.




- 1. Scanner
- 3. D25P Cable
- 5. Printer Cable
- 2. Power Supply
- 4. PC Parallel Port

Figure 2-2 Avision AV360C scanner cable connection

2.4 Document Placement

As shown below, place the image to be scanned face down on the scanner.



- 3. Reference Frame
- 5. Glass

- 4. Document
- 6. Document Board

Figure 2.3 Document Placement

3. Scanner Driver Installation

To run at rated speed as recommended, the AV360C color image scanner must have the following minimum requirements:

- * IBM compatible PC 386/486 or Pentium;
- * Microsoft Windows 3.1 or Windows 95;
- * DOS 5.0 or higher;
- * One printer port available (enhanced parallel port recommended);
- * 2 megabytes of available hard disk space for installation;
- * 4 megabytes of RAM (8 megabytes or higher recommended);
- * A video graphics array (VGA) monitor;
- * A Microsoft Windows-compatible pointing device (e.g., the mouse);
- * A CD ROM drive.

3.1 Auto-Installation Program

Installation procedures of AV360C Scanner driver with Avision Auto-installation Program are as follows:

- 1. Start Windows 3.1 or Windows 95.
- 2. Insert AV360C CD kit into your CD ROM drive.
- 3. For Windows 3.1 or Windows 3.1 (See Figure 3-1,3-2) From the File Menu, choose RUN, type d:\driver\av360c.exe (d: the CD ROM drive in use), and then click O.K.

3 For Windows 95

Press the Start button, choose RUN, type d:\driver\av360c.exe (d: the CD ROM drive in use), and then click O.K.

4. Follow the on-screen instructions to complete the installation (usually just clicking O.K. will complete the installation).



Fig. 3.1




Fig. 3.2

3.2 Uninstall the Scanner

You can uninstall the scanner by double-clicking on the ninstall icon stored in the Avision driver group.






4. Scanner Operation & Document Printing

There are two types of application software interface to use with the AV360C scanner. TWAIN is the most popular interface among image-editing application software.

Scanning Images from within an Application (TWAIN)


- 1. Open your application and choose Select Source from the File menu. If the Select Source menu options are not available from the File menu, see the user guide of your application to learn how the TWAIN link is used.
- 2. A dialog box appears containing the different TWAIN sources that you can choose for bringing an image into your application.
- 3. Select AV360C/16 V3.2 as the source.
- 4. You need to select AV360C for just once except when you have used the dialog box to select a different source. In that case, you will need to select AV360C as the source again before you can reuse the Avision AV360C scanner.
- 5. Place the image to be scanned face down on the scanner.
- 6. From the File menu, selectAcquire.
- 7. AV360C TWAIN user interface will pop up on the screen. Click on the Preview or Scan button to get the image.

AV360C TWAIN user interface:



4.1 Image Type

As shown below, you can select the mode you want to use with your document or image. Just click on the corresponding button.



Line art

Line art includes only black and white areas. There are no intermediate shades of gray in between.

Error Diffusion

While taking up but a minimum storage space, error diffusion gives good image texture and excellent image details.

Halftone

Halftone simulates different shades of gray by varying the threshold value of a matrix.

Gray (256 levels gray scale)

Scanner recognizes each point in the image as a shade of gray (continuous tone). 8-bit gray gives more detailed information about the image.

True Color (16.7 million colors)

Color image has continuous tones along with its color hues.

4.2 Scanning Parameters & Image Control



Resolution: The number of dpi (dots per inch) that AV360C


uses for a scan.

Brightness: Adjusts the lightness or darkness of an image.

The higher the value, the brighter the image.

Contrast: Adjusts the range between the darkest and the

lightest shades in the image. The higher the contrast, the bigger the different gray scales.



Auto Level: Optimizes the scanned image.

Auto Area: Automatically sets the whole document as the

scan area, no matter what its size.

Descreen: Eliminates the Moire patterns commonly found in

printed matter.



Color Match: Adjusts the color quality of the image so that it comes close to that of the original. This function uses default parameters to adjust the image.

Reset: Resets the scanning parameters you set.

Invert: The invert command reverses the brightness and the color in the image. For color images, each pixel will be changed into its complementary color at the command of Invert.

Calibration: Defines "whiteness" for the scanner. Users are recommended to calibrate the light source if the scanned image looks undesirable or comes out to be too dark.

Quality/Speed Mode:

Users can select either mode to perform scanning according to their own need. Select quality mode scanning if your emphasis is on the quality of the scanned image. Else, select speed mode scanning if you want to speed up the scanning process.

Pixel/Inch/Cm:

Represents the different measure systems to be used in each scan.

Set Gamma: Adjusts the midtone of the image without losing details of the lightest and the darkest areas.

Image Information:

Gives related information of the scanned image.

4.3 Scanning



Preview: Previews your image roughly and allocates the area to

be scanned.


Scan: Scans the area with the parameters you set.

Exit: Cancels the current job.

Document Size: To designate the size of your document, just click


on its icon on the margin of the preview window

As shown in the figure below, in the Preview window, you can define the area to be scanned by dragging the four cursor auxiliary lines.



4.4 Printing

Connect the printer cable as shown below.



- 1. Scanner
- 2. Printer Cable
- 3. To PC parallel port 4. Scanner Cable

Figure 3.3 Printer cable connection

Attention:

- 1. Be sure to power on the scanner if you want to do passthrough printing.
- 2. Do not scan and print at the same time.
- 3. If your PC does not support EPP mode or have pass-through compatibility problem, please contact your authorized local dealer for an EPP card or an additional interface card.

5. Maintenance

Clean the Document Board Glass:

As shown below, wipe the scanner glass with a piece of soft clean cloth to rid the glass of dust or toner particles.




Figure 4-1 Clean the document board glass.

6. Troubleshooting

The scanner will automatically perform a simple self test each time it is initialized. This will help spot major system errors in the scanner itself.

If you have any problem with the operation of the scanner, please check the following troubleshooting hints.

6.1 Questions and Answers

Question: Why is it the scanned image always comes out

too dark?

Answer: 1) Modify the Gamma setting to 1.8 for your

monitor and, when printing, set Gamma to

2.2 for your printer.

2) Use the Brightness setting of the TWAIN user interface to get a brighter image.

Question: The scanning speed of my scanner is much

slower than that of those installed at other

computers. Can I speed it up?

Answer: In such case, please

a) Set you PC printer port to the EPP mode

from BIOS setting, or,

b) Add Avision scanner interface card to scan

at a higher speed.

Question: Why does my scanner scan at a very low speed?

Answer: If you have installed "Works for Windows," it

will install Window Printing System (WPS) in your WIN.INI file. This will take up the printer port time remarkably. You can remove the WPS

from your WIN.INI file, as follows:

From:

[MS Text Converters]

MSWorksWin=Works for Windows 2.0,C:\WINDOWS\MSAPPS\TEXTCONV\worksdos.sups, Works forDos 2.0=Works for DOS 2.0MSAPPS\TEXTCONV\workswin.com.ps

To:

[MS Text Converters]

MSWorksWin=Works for Windows 2.0,C:\WINDOWS\MSAPPS\TEXTCONV\worksdos.cnv Works for DOS 2.0=Works for DOS 2.0:\WINDOWS\MSAPPS\TEXTCONV\workswin.con

Question: The printer does not print the documents. Why?

Answer: Pass-through printing may pose a problem for

some printers. It is suggested that you

a) add a second printer card for printing purpose,

or,

b) add Avision scanner interface card to

perform scanning.

Please call your authorized local dealer for

support.

Question: Does it take long for the scanner to initialize?

Answer: If your printer port supports SPP mode only, it

takes about two minutes for the scanner to initialize. If your printer port supports EPP mode, the initialization speed is much faster, about 20 seconds. Generally, it takes a two to three minutes time for the Avision AV360C scanner lamp to warm up. It may be that your

scanner lamp is out of order if it works

otherwise.

Question: Why sometimes pass-through printing does not

work at all?

Answer: It may be that you forgot to power on the

scanner. When doing pass-through printing, please first remember to power on the scanner.

Else, without power, the scanner can not transfer the printing data/signals to the printer.

Question: Why doesn't my GDI printer work with the

Avision AV360C scanner?

Answer: Disable the "Auto Scan" function in the

application, and your printer will function all

right.

Question: Why some parallel port devices and software's

keypro do not work with the Avision AV360C

scanner?

Answer: The Avision AV360C scanner can do pass-

through printing all right, but not otherwise. As such, if you would like to connect some parallel port devices other than printer, please do not connect them to the same parallel port that

connect them to the same parallel port that

Avision AV360C currently uses. It is advisable that you use other parallel ports to connect these

devices orkeypro. For instance, you can

connect the Avision AV360C scanner to LPT1,

and connect other parallel port devices to LPT2.

Or you can add a data switch to avoid the

problem.

6.2 Technical Service

Technical support for Avision scanner is provided at the Avision Technical Assistance Center. Before you contact us, please prepare the following information:

- * Scanner serial & revision number (located on the bottom of the scanner);
- * Hardware configuration (e.g., your host CPU type, RAM size, free disk space, display card, interface card...);
- * The name and version of your scanning software application;
- * The version of your scanner driver.

Please call us at:

US and Canada Area: Avision Labs., Inc.

Address: 48521 Warm Springs Blvd. #312 Fremont,

CA 94539

Tel: 510-440-8785 Fax: 510-440-8337

Web Site: http://users.aimnet.com/~avision

E-mail: avision@aimnet.com

Other Area: Avision Inc.

Address: No. 20, Creation Road I, Science-Based

Industrial Park, Hsin-Chu, Taiwan, R.O.C.

Tel: 886-3-5782388. Fax number: 886-3-5777017 BBS: 886-3-5786149

CompuServe: 101400,444

Internet: avision@shts.seed.net.tw

- Note: 1. You can find the latest driver and document in Avision BBS. Our service is 24 hours a day. The communication setting is 2400-19200 BPS, 8N1S.
 - 2. You will be asked to enter your first name, last name and password at all times. The same name and password must always be used to enter Avision BBS.

7. Specifications

All specifications are subject to change without notice.

7.1 Model: AV360C

Scanner Type: Flatbed

Optical Resolution: up to 300 dpi * 600 dpi (H*V)

Scanning Modes: Black & White mode

Halftone mode (64-step)

Error diffusion

8-bit gray scale(256 levels)

24-bit color (16.7 Millions of color)

Scanning Speed: 15 sec/page (letter size, color

mode, 100 dpi)

Document Size A4, B5, A5, business card

Interface: Printer port (supports SPP/EPP

for PC)

Power Source: 110Vac or 220Vac, 50-60Hz,

external

Power Consumption: 12 watts (12Vdc,1A)

Dimensions: (WxDxH) 414 mm x 306 mm x 92 mm

Weight: 3.9 kg.

EC Declaration of Conformity

According to EN45014

Manufacturer's Name: Avision Inc..

Manufacturer's Address: No. 20, Creation Road I,

Science-Based Industrial Park, Hsin-Chu, Taiwan, R.O.C.

declare that the product

Model Number: AV360C

conforms to the following Product Specifications:

Emission: EN 50081-1 (1992)

EN 55022 (Class B)

(Conducted Radiated) (1994) EN 60555-2 (Harmonics) (1987) EN 60555-3 (Flicker) (1987)

Immunity:

EN50082-1 (1992)

IEC 1000-4-2 (ESD) (1995) IEC 1000-4-3 (RS) (1995) IEC 1000-4-4 (EFT/Burst)

(1995)

IEC 1000-4-5 (SURGE) (1995)

Date: December, 1995