

STATION
TAIL NO.
DATE



BOEING CARD NO. 27-698-00
AIRLINE CARD NO.

SKILL AIRPL	WORK AREA STAB COMPT	RELATED TASK	INTERVAL S 4C	PHASE 99XXX	MPD REV 014	TASK CARD REVISION DEC 22/06
TASK SPCL DETAIL		TITLE STABILIZER TRIM ACTUATOR		STRUCTURAL ILLUSTRATION REFERENCE 3-3	APPLICABILITY AIRPLANE ENGINE ALL ALL	
ZONES 311 312			ACCESS PANELS 312AR NOTE			

MECH	INSP	MPD ITEM NUMBER 27-698-00
		<p>SPECIAL DETAILED - INTERNAL: STABILIZER TRIM ACTUATOR-LOWER GIMBAL LUG ASSEMBLY BS 1708.5, WL 239.9 (TYPE 1 STRUCTURE)</p> <p>INTERVAL NOTE: THRESHOLD: 50000 CYC (200, 300PASS) 40000 CYC (300F, 400E)</p> <p>ACCESS NOTE: REQUIRES ACTUATOR ATTACH PIN REMOVAL.</p> <p>NOTE: SEE DOC D622T001-DTR, DTR CHECK FORM 27-40-101A FOR ALTERNATIVE REPEAT INSPECTIONS.</p> <p>NOTE: THE NDI METHOD(S) NECESSARY TO ACCOMPLISH THE INTENT OF THIS INSPECTION IS CONTAINED IN THE 767 NON-DESTRUCTIVE TEST MANUAL D634T301. THE INSPECTION PROCEDURES ARE CONTAINED IN PART 4, SUBJECT 27-40-01.</p>

5 6 4 0	EFFECTIVITY	SPCL DETAIL	STABILIZER TRIM ACTUATOR
			27-698-00 PAGE 1 OF 1 DEC 22/06