

5730 Series Accessories

CW Sensor Probe Interconnects (without data adapter)

41-2A	Sensor/Probe Interconnecting Cable (5ft.)(M/M)
41-2A/10	Sensor/Probe Interconnecting Cable (10ft.)(M/M)
41-2A/20	Sensor/Probe Interconnecting Cable (20ft.)(M/M)
41-2A/50	Sensor/Probe Interconnecting Cable (50ft.)(M/M)
41-2A/100	Sensor/Probe Interconnecting Cable (100ft.)(M/M)

CW Sensor Adapters

95000601A	Adapter 50 Ohm N/75 Ohm N(M/F) (2520, 4200A, 4220A and 4300)
95109001A	Sensor Data Adapter (Smart Sensor 4230A, 5230, 9230)
95109101A	Data Adapter with Cable (5ft)
95109101A	Data adapter with cable instead of 41-2A
95109102A	Data Adapter with Cable (10ft)

RF Voltage Probe Accessories

91-6C	Unterminated BNC Adapter (F) (92BD)
91-6F	Unterminated Type F Adapter (F) 92BD, 92EA)
91-6G	Unterminated BNC Adapter (M) (92BD)
95200101D	RF Probe (5230,92XX Series & 92EA) includes 41-2A and printout
95200201B	50 Ohm BNC Adapter (F) (92EA, 4230, 92XX Series)
95200301A	50 Ohm Tee Adapter N (F/F) (92EA, 5230,92XX Series)
95200401A	Probe Tip (92EA, 5230, 92XX Series)
95200501A	100:1 Voltage Divider (92EA, 5230, 92XX Series)
95200601B	75 Ohm BNC Adapter (F) (92EA, 5230, 92XX Series)
95200701A	75 Ohm Tee Adapter N (F) (92EA, 92XX Series)
95200801B	Unterminated BNC Adapter (F) (92EA, 5230,92XX Series)
95201101A	Set of Accessories, 50 Ohm (92EA) Compatible with 952001 Probe, Including: 952003, 952005, 952008,952013, 91-15A
95201102A	Set of Accessories, 50 Ohm (5230, 92XX Series) Compatible with 952001 Probe, Including: 952003,952008, 952013, 91-15A
95201201A	Set of Accessories, 75 Ohm (92EA) Compatible with 952001 Probe, Including: 952005, 952007, 952008,952013, 91-15A/1
95201202A	Set of Accessories, 75 Ohm (9200C) Compatible with 952001 Probe, Including: 952007, 952008, 952013,91-15A/1
95201301A	Accessory Case (92EA, 5230, 92XX, 4530 Series)
95201603B	Low Frequency Probe (5230, 92XX Series& 92EA) 10 Hz to 100 MHz
95205801A	100:1 Divider (10 Hz to 20 MHz) Compatible with 952016 Probe