

Service Information

COPIER

☐HARDWARE

☐SOFTWARE

Copyright Canon (UK) Limited

Model: Network Printer Board-F1

Network Multi PDL Printer Board-H1

Network Printer Board-K1

Ref. No.: 99-OIPD0-B0038

Date: June 1, 1999

Approved by:

Shinya Kishimata

Location : SYSTEM SOFTWARE

Subject: PATCH FILE 52093.PS RELEASE

Reason: Job Log Export Support

Patch files, 52093.ps(File Size=4148 bytes) and 52093.efi(File Size=20492 bytes) were released to support the Job Log Export of Web Spooler in Network Printer Board-F1 v1.0/1.0a and Network Multi PDL Printer Board-H1/K1 v1.0.

Installation Notes:

- 1. For PS and PS/PCL System
 - (1.1) Download the file 52093.ps to the print or direct queue with Fiery Downloader.
 - (1.2) Reboot the server.
 - (1.3) Print the configuration page and check that "52093" is printed out in Update Information on the configuration page.
 - (1.4) Connect to PDL board through a browser
 - (1.5) Select Web Spooler.
 - (1.6) Show the Job Log list on Web Spooler.
 - (1.7) Select File Tab to verify that the "Export Job Log" option is now available.

2. For PCL Only System

- (2.1) Select "Setup" at Boot up screen.
- (2.2) Install the Software through the parallel port.
- (2.3) Download the file 52093.efi with PDL Downloader.
- (2.4) Exit Setup and reboot.
- (2.5) Print the configuration page and check that "52093" is printed out in Update Information on the configuration page.
- (2.6) Connect to PDL board through a browser
- (2.7) Select Web Spooler.
- (2.8) Show the Job Log on Web Spooler.
- (2.8) Select File Tab to verify that the "Export Job Log" option is now available.