

**MODEL:** **GP 605 / 555 / 605P**

**SUBJECT:** **Missing Part Number**

**Detail:**

The **shaft** attached to the lifter plate FB4-1355 (*Reference figure 104, item 13*) is not shown with a part number, the number for this part is:-

**FB4-2020-000 Lifter shaft**

Please place an A5 copy of this ATI in your library parts catalogue.

