

MODEL: GP605 / GP555

SUBJECT: ADF availabilty

Detail:

The ADF for the GP605 has now been made available as a separate part for exchange of troublesome units in the field. The full unit can be obtained using the part number:

FG6-2724-000

Changing this unit should only be carried out as a last resort after normal fault finding has failed to rectify any problems.