

**Model :** GP605  
GP605P

**GP555**

**Ref. No. :** FF-T01-K1-000058-01

**Date :** August 7, 2000

© Canon (UK) Limited

**Location :** OZONE FILTER FOR FM2

**Subject :** THOROUGH REGULAR CLEANING OF OZONE FILTER FOR FM2

**Reason :** If the ozone filter for FM2 is used when it is dirty, the internal temperature may rise due to clogging of the filter and a block may occur with toner in the developing assembly.  
The regular maintenance of the ozone filter for FM2 is required to be conducted thoroughly.

**Details :** <Symptom>  
The block occurs with toner in the developing assembly.

<Cause>

When the ozone filter for FM2 is kept using without the regular maintenance with the recommended frequency (every 250K or less), the temperature rises due to clogging of the ozone filter and a block may occur in the developing assembly.

<Factory measure>

None.

**Servicing Work :**

The cleaning of the ozone filter for FM2 is to be conducted in the regular maintenance (every 250K or less).

**Service Parts :**

None.

**Affected machines:**

None.