

Service Information

COPIER

☒ **HARDWARE**

☐ **SOFTWARE**

Model: GP605 Series

Ref. No. : FF-T01-K1-000084-01

Date : July 18, 2002

© Canon (UK) Limited

Location: Items in the Shipment Box

Subject: Changing the Composition of Items in the Shipment Box

Reason: Changes have been made to the items to include with the machine to facilitate the factory work; they are mostly in the number of pieces. With these changes, the instructions in the Service Manual for installation have also been updated.

Detail:

1. Change in the Items in the Shipment Box

Parts Name	Description
Deck Size Label	Eliminated. (It is combined with the cassette size label and attached to the same mount.)
Universal Cassette Label	Eliminated.
Binding Screw (M4x8; w/ spring washer; black)	The screw used for the multifeeder band is added to the items included in the shipment box, and the step performed to remove the screw has been eliminated.
Size (Inch) Fixing Member	A change has been made to the quantity: instead of 3 pieces, 2 pieces are provided for each cassette.

2. Change in the installation Procedure

The procedure is stored as a separate file with this service information on NOTES/Intranet/DealerNet..

Affected Machines:

There is no change to the item classification used into the factory because of these changes.