

Service Information

COPIER	
⊠HARDWARE	
□SOFTWARE	

Model: Network Printer Board-F1 Ref. No.: FF-T01-V1-000092-01

(00-OIPD0-B0058)

Date: June 5, 2000

© Canon (UK) Limited

Location: MEMORY MODULE

Subject: CHANGE OF STANDARD AMOUNT OF MEMORY INSTALLED

Reason:

In Network Printer Board-F1, the amount of memory installed is switched from the current "32MB

DRAM DIMM" to "64MB DRAM DIMM (32MBx2)".

Service Parts:

No change

Affected Machine

It is switched from the production in and after June 2000.

With this change, the product orders are changed as follows.

F61-7403-030 Network Printer Board-F1, USA F61-7403-720 Network Printer Board-F1, AMS/UK F61-7403-722 Network Printer Board-F1, FRN F61-7403-724 Network Printer Board-F1, GER F61-7403-726 Network Printer Board-F1, ITA