

## Service Information

 **HARDWARE**
 **SOFTWARE**

**Model :** iR1210  
iR1270F

iR1230

**Ref.No. :** FF-T01-L6 -000048-UK1

**Date :** Sep.10.2002

© Canon (UK) Limited

**Location :** Reader Assembly

**Subject :** For countermeasure against black lines, the copy board glass is changed to that performed low  $\mu$  treatment

**Reason :**

Countermeasure against black lines

**Outline :**

To avoid attaching dirt on the copy board glass, the glass that low  $\mu$  treatment is performed is used instead.

**The implementation date at the factory and the serial numbers concerned will be notified when they become definite.**

For moving the parts center, the change of the service parts is scheduled from the January 2003 onward.

**Effective on :**

### Parts

Class	Stock	Compatibility
	0:Not Stocked(Disuse) 4:Until the stocks have been used up 1:Stocked(New) 5:Qty change only 2:Stocked for previous models 3:Stocked for other models	A:Old $\leftarrow$ $\rightarrow$ New B:Old $\rightarrow$ New C:Old $\leftarrow$ New D:Not compatible

Product Code	Part Name	Part No.	UNIT No.	Qty	RevNo.	Class	Stock	Available from	Compatibility	Location
ALL	Old	GLASS,COPYBOARD	FF6-1435-000	1			4		C	
	New	GLASS,COPYBOARD	FF6-1435-020	1			1			

