


Canon

ATI-AZ-003

MODEL: iR2200/ 2800 / 3300**SUBJECT:** Inner 2-Way Tray-A1**Detail:****IMPORTANT POINT TO BE FOLLOWED IN INSTALLING INNER 2WAY TRAY-A1**

When an inner 2way Tray-A1 is installed, there is a possibility of two connectors being inserted alternatively, and this will cause a machine malfunction. At worst, it will result in breakage of sensors of DC Controllers.



Please be sure that those two connectors are inserted into the appropriated jack.
(13-pin connector should be left and 12-pin with a short line be right).