


MODEL: iR2200/ 2800 / 3300

SUBJECT: Handling of Raiser PCB for Token Ring Option

Detail:

This is to notify you of a precaution in handling the Raiser PCB Board Assembly.



There is a possibility of the Raiser PCB being damaged by electrostatic or other external factors.

Please handle it with extra care and **NEVER** touch the connector terminals.