

SOFTWARE QUALITY ASSURANCE CENTRE, DIVISION 'E'

Systems Service Information

GP/ iR related Products

Original S.I. No.	Type	Description / Symptom	Date Issued
2000			
V1-000054-01	GP160	Network interface device firmware upgrade	31/01/00
V1-000055-01	PCL5e Driver	Version 4.2 CCD Driver, 1.2x Fax Driver	29/02/00
V1-000059-01	Bugs	Y2K Patch for NIB in MDC	31/01/00
V1-000060-02	N/W M PDL P/B H1, N/W P/D-K1/F1	Problem printing ruled lines in SAP-R3 Environment	29/02/00
V1-000061-01	N/W M.PDL P/D D1, N/W P/B-E1	Problem printing ruled lines in SAP-R3 Environment	29/02/00
V1-000063-01	GP160	PCL5e/PCL6 Printer Drive for Windows NT 4. Ver. 1.01 (suitable for installation in Windows 2000)	05/05/00
V1-000067-01	N/W PDL P/D-D1	To enable Windows 2000 driver.	05/04/00
V1-000072-01	S/Ware	NetSpot Ver 3.1.3	13/02/01
V1-000077-01	GP335/405	GP Scan gear V2.00	11/0400
V1-000078-01	GP215/225	GP Scan gear V2.10	11/04/00
V1-000079-01	N/W M.PDL P/D D1, N/W P/B-E1	H.D. Part Change	11/04/00
V1-000080-01	N/W M PDL P/B H1, N/W P/D-K1/F1	DIMM Part Change	11/04/00
V1-000082-UK1	CWS- N/W P/B-F1	GP605 Printer Board-F1 Command Workstation Support (Ver. 2.0 Pro)	11/01/01
V1-000083-01	S/Ware	PCL5e Printer Driver Version 4.40 for Windows2000 Release	20/06/01
V1-000089-01	CWS- N/W P/B-F1	Patch for X6e Ver. 2.0 Pro to ensure banner page is delivered to same tray as print job.	11/01/01
V1-000088-01	N/W Board-F1	Novell Banner page delivered to different tray than rest of job.	25/05/00
V1-000092-01	N/W Board-F1	Standard memory increased from 32mb to 64mb	12/06/00
V1-000093-01	N/W PB-F1 N/W M PDL PB-H1/K1	Hard disk capacity increased	12/06/00
V1-000095-UK1	N/W M.PDL PB-D1/H1 N/W P B-E1/F1/K1	Win NT4 Terminal Service Editor Support Information	15/06/00
V1-000097-01	NetSpot 3.1.4	NetSpot 3.1.4 release	07/09/00
V1-000098-01	S/Ware	Release of CCD driver Version 4.41 (with Windows 2000 WHQL)	18/09/00
V1-000101-01	S/Ware	Release of CCD fax driver Version 1.30 (with Windows 2000 WHQL)	18/09/00
V1-000102-01	Windows Me	Information related to Windows Millennium Support for LBP/CLC/GP/iP Products	07/09/00

SOFTWARE QUALITY ASSURANCE CENTRE, DIVISION 'E'

Systems Service Information

GP/ iR related Products

Original S.I. No.	Type	Description / Symptom	Date Issued
V1-000109-01	S/Ware	Release of Post Script Driver	20/02/01
V1-000110-01	S/Ware	PCL5e Printer Driver V4.5 release	12/02/01
V1-000111-01	S/Ware	PCL6 Printer Driver V2.10 release	07/02/01
V1-000115-01	S/ware	PCL5e Ver4.41 driver, PCL6 ver 2.21 driver, fax driver ver 1.30	19/02/01
V1-000116-02	S/Ware	PCL5e ver 4.51, PCL6 ver 2.21, Fax Driver ver 1.30	19/02/01
V1-000119-01	S/Ware	User Software CD-ROM (post Script Printer Driver) Modification	21/02/01
V1-000120-01	S/Ware	GP/iR Scan Gear v2 Windows Millennium Edition Support	21/02/01
V1-000121-01	S/Ware	GP/iR Scan Gear v2.10 Windows Millennium Edition Support	21/02/01
V1-000122-01	S/Ware	NetSpot 3.2.1 Release	21/02/01
V1-000123-01	S/Ware	NetSpot 3.2.2. Release	12/02/01
V1-000125-01	S/Ware	Network Printer Board-J2 Release	17/04/01
V1-000126-02	S/Ware	System Software V2.1 Release	08/06/01
V1-000127-01	S/Ware	System Software V2.1Pro Release	08/06/01
V1-000128-02	S/Ware	System software V2.1 released	27//06/01
V1-000129-02	S/Ware	System Software V2.1 released	27/06/01
V1-000130-01	S/Ware	Patch file 1-2H9UA.EFI Release	06/06/01
V1-000131-08	S/Ware	Release of iR-M1 (System Software 1.1)	27/11/01
V1-000133-03	IR-L1 Cont	Release of system Software V1.00	06/05/02
V1-000134-01	IR-L1/M1	Release of System Software Patch to change default IP Address.	14/05/02
V1-000135-02	S/Ware	Inclusive of system software CD Rom with printer kits.	10/12/01
V1-000140-01	Printer Board-D1/F1/H1	Release of Patch for Banner Page	14/05/02
V1-000141-02	N/W M-PDL PB-P1 NW PB-R1	Introduction of Network Multi PDL PB-1/R1 (Differences between PB-H1/K1	22/08/02
V1-000142-04	N/W M-PDL PB-P1 NW PB-R1	System Software (GP405, iR400)	19/11/02
V1-000147-02	N/W M-PDL Kit-B3	Differences between NW M-PDL P.Kit-B3 and P.Kit-B1/B2	14/05/02
V1-000149-01	Send Kit-A1	Send Kit-A1 for iR8500 Series	19/11/02
V1-000150-01	iR-L1 Cont.	Release of iR-M1 to prevent lock-up when handling large PDF's	06/05/02
V1-000151-03	IR-L1 Cont	Release of System Software V1.0	09/01/03
V1-000153-01	N/W M-PDL PB-H1,	X3e / X6e Printer Board patch file to correct	08/07/02

SOFTWARE QUALITY ASSURANCE CENTRE, DIVISION 'E'

Systems Service Information

GP/ iR related Products

Original S.I. No.	Type	Description / Symptom	Date Issued
	N/W PB-K1/F1	page miscount when duplexing	
V1-000154-01	NIC-iN-E5 Printer Board-N1	Errors caused by a fault in the programming of the firmware	12/11/02
V1-000155-02	IR-M2 Cont	Release of System Software V1.0	09/01/03
V1-000157-01	NIC-iN-E5 Printer Board-N1	NW Printer Board-N1 PCL Version 2	12/11/02
V1-000158-01	NIC iN-E5 Printer Board-N1	Release of Version 3 Firmware	12/11/02
END			