Canon

Service Information

COPIER	
⊠HARDWARE	
SOFTWARE	

Model: GP555 Ref. No.: FF-T01-K1-000028-01

Date: July 2, 1999

© Canon (UK) Limited

Location: INTRODUCING A NEW PRODUCT

Subject: INTRODUCING THE GP555/IMAGE RUNNER 550

Reason : The GP555 (100/230V model) and imageRUNNER 550 (North American model) will soon be

marketed, and this bulletin communicates their differences from the GP605/imageRUNNER 600.

Details : < Differences in Specifications >

The copying speed is 55 cpm max. (A4/LTR).

The original orientation detection mechanism has been removed.

< Serial Numbers >

GP555 100V F13-5618: LNP00001 or later 230V F13-5682: ANC00001 or later F13-5672: BNC00001 or later F13-5692: CNC00001 or later F13-5652: DNC00001 or later F13-5622: FNC00001 or later

imageRUNNER 550 120V F13-5638: NNT00001 or later

Servicing: For information on servicing, see the GP605 Service Manual (for Japanese, FY8-12DC-000; for

English, FY8-13FD-000) and the image RUNNER 600 Service Manual.

For information on parts, see the GP605 Parts Catalog (Y8-31DU-010) and image RUNNER600 Parts

Catalog.

Service Parts Differences from the GP605/imageRUNNER 600

FIGURE &	GP605	GP555	Q'ty	Description	Remarks
KEY No.	Part number	Part number	2 13	Description	Remarks
100-65	As single part	FG6-5390-000	1	Front Cover	
950	FG6-1911-000	FG6-5323-000	1	Image Processor PCB	
970	FG6-1946-000		0	Original Orientation Detection PCB	

FIGURE &	iR600	iR550	Q'ty	Description	Remarks
KEY No.	Part number	Part number	2 13	Description	Kemarks
100-65	As single part	FG6-5390-000	1	Front Cover	
950	FG6-1911-000	FG6-5323-000	1	Image Processor PCB	
970	FG6-1946-000		0	Original Orientation Detection PCB	