

Model: GP605
GP605P

GP555

Ref. No. : FF-T01-K1-000070-01

Date : December 18, 2000

©Canon(UK)Limited

Location: Transfer / Separate Corona Assembly

Subject: Improvement in Lifetime of Separation Corona Wire

Reason: In case the machine is used under H/H environments, there is a possibility that re-transfer occurs as the separation corona wire fails to reach its expected lifetime, 250,000 sheets. Therefore, the current cleaning pad is replaced with a reinforced polishing pad with the aim of cleaning the corona wire better.

Details: <Cause>

There is a possibility that re-transfer may occur before the separation corona wire reaches its expected lifetime, 250,000 sheets under H/H environments.

<Measure>

The current cleaning pad is replaced with the reinforced polishing pad for improving the cleaning capability.

Servicing Work:

In case of the use under H/H environments, the cleaning pad should be replaced with the reinforced polishing pad.

Service Parts:

No.	Description		Part number	Q'ty	Stock	Inter-change-ability	PC. ----- Stock date
1	Old	CLEANING FELT	FA5-7690-000	4→0	F	↓ No ↑ Yes ↓ ↑	580-21A
	New	CLEANING FELT	FB5-3110-000	0→4	D		
2	Old	HOLDER, FELT	FF5-7891-000	1→0	C	↓ No ↑ Yes ↓ ↑	580-21
	New	HOLDER, FELT	FF5-7891-020	0→1	D		

Affected Machines:

iR550	UL	F13-5638	NNT05638 and later
iR60	UL	F13-5633	NQF00109 and later

iR600 UL F13-5631 NLE12961 and later