



Service Information

COPIER

HARDWARE

SOFTWARE

Model : Network Printer Board-F1 v2.0/v2.0Pro

Number: FF-T01-V1-000119-01

(00-OIPD0-B00109)

Date : October 12, 2000

Location : User Software CD-ROM

Subject : User Software CD-ROM (Post Script Printer Driver) Modification

Reason : A new CD-ROM is released because of the following modifications in the User Software of "Network Printer Board-F1 v2.0/2.0P".

- Windows PS Printer Driver: WHQL Certified
- Macintosh Printer Driver: Adobe PS Driver updated from v8.5.1 to v8.7

For the WHQL Certified Driver, refer to the Service Information No. FF-T01-V1-000109-01 (00-OIPD0-I0090).

In Mac PS Driver, printing via TCP/IP is available by using Adobe PS8.7 (use "Apple DeskTop Printer Utility").

With the updated Adobe PS, the support OS is "Mac OS8.1" or later (for details, refer to the Readme file).

Details :

Here are the file configurations of CD-ROM.

.Windows.

\Deutsch	\WIN9x	\v2.0	\v2.0P	: with Cat File
	\WINNT40	\v2.0	\v2.0P	
	\WIN2000	\v2.0	\v2.0P	: with Cat File
\English(international)	\WIN9x	\v2.0	\v2.0P	: with Cat File
	\WINNT40	\v2.0	\v2.0P	
	\WIN2000	\v2.0	\v2.0P	: with Cat File
\English(United States)	\WIN9x	\v2.0	\v2.0P	: with Cat File
	\WINNT40	\v2.0	\v2.0P	
	\WIN2000	\v2.0	\v2.0P	: with Cat File
\Espanol	\WIN9x	\v2.0	\v2.0P	: with Cat File
	\WINNT40	\v2.0	\v2.0P	
	\WIN2000	\v2.0	\v2.0P	: with Cat File
\Francias	\WIN9x	\v2.0	\v2.0P	: with Cat File
	\WINNT40	\v2.0	\v2.0P	
	\WIN2000	\v2.0	\v2.0P	: with Cat File
\Italiano	\WIN9x	\v2.0	\v2.0P	: with Cat File
	\WINNT40	\v2.0	\v2.0P	
	\WIN2000	\v2.0	\v2.0P	: with Cat File
\Downloader				Fiery Downloader for Win

.Macintosh.

\Deutsch	\v2.0	\v2.0P	: Adobe PS8.7 base	
\English(international)	\v2.0	\v2.0P	: Adobe PS8.7 base	
\English(United States)	\v2.0	\v2.0P	: Adobe PS8.7 base	
\Espanol	\v2.0	\v2.0P	: Adobe PS8.7 base	
\Francias	\v2.0	\v2.0P	: Adobe PS8.7 base	
\Italiano	\v2.0	\v2.0P	: Adobe PS8.7 base	
\Downloader				Fiery Downloader for Mac
\Fonts				

Remarks :

- (1) The time of the change to CD-ROM included in Products will be reported separately.
- (2) To distinguish from the existing CD-ROM, the EFI Parts Number is modified to 45018267.