

Model : Network Printer Board-F1
 Network Multi PDL Printer Board-H1
 Network Printer Board-K1

Ref. No. : FF-T01-V1-000080-01
 (00-OIPD0-B0044)

Date : April 7, 2000

© Canon (UK) Limited

Location : 32MB MEMORY MODULE

Subject : PARTS NUMBER MODIFICATION WITH 32MB MEMORY MODULE MODEL NUMBER MODIFICATION

Reason :
 The 32MB Memory Module model number of Network Printer Board-F1, Network Multi PDL Printer Board-H1 and Network Printer Board-K1 was modified (from 2-bank type to 4-bank type). With this modification, no modifications regarding the specifications.

Service Parts :

No.	Description		Part number	Q'ty	Stock	Inter-change-ability	----- EFI P/N
1	Old	DIMM ASS'Y, UG54S6608GSG	FE1-5022-000	1→0	C		45014200
	New	DIMM ASS'Y	FE1-5022-010	0→1	D		

Notice :
 (1) The new DIMM (4-bank type) and the old DIMM (2-bank type) can be mixed in use.
 (2) **For Network Multi PDL Printer Board-D1/Network Printer Board-E1, this memory module is unavailable.**

Affected Machine :
 Here is the cut-in serial number for the new DIMM:
 Network Printer Board-F1 Serial Number : J00039249 or later
 Network Multi PDL Printer Board-H1 Serial Number : J00039191 or later (from Top Line Factory)
 Network Multi PDL Printer Board-H1 Serial Number : K00327 or later (from SCI Factory)
 Network Printer Board-K1 Serial Number : K02322 or later