

**Model:** Saddle Finisher-F2**Ref. No. :** FF-T01-W-000144-01**Date :** April 13, 2001

© Canon (UK) Limited

**Location:** Saddle Finisher Controller PCB Assembly**Subject:** Updating the ROM Program (Ver. 4.01)**Reason:** The ROM program has been updated and released as Ver. 4.01; this bulletin communicates points of importance.

## History of Updates

Ser. Info. No.	Ver. No.	Description	Date
FF-T01-W-000144-01	Ver. 4.01	Facilitating factory work	April 13, 2001
	Ver. 3.03	First Production	

**Details:**

## &lt;Changes in Ver. 4.01&gt;

No.	Item	Description
1	Facilitating factory work	The version is upgraded to improve the ease of adjustment work at the factory.

**ROM Combination:**

Combinations of the Saddle Finisher Software and Other Software (System Software/DCONT, etc.)

Ver. No.								Date
FIN	Saddle	System Software	DCONT	BOOT	RCONT	ADF	RUI	
10.02	4.01 3.03	10.45	5.01	9.49	<u>4.04</u>	<u>6.02</u>	10.36 2.11	April 13, 2001
		5.01	4.04	7.47	<u>3.02</u>			
		2.17	3.04	5.45	<u>2.02</u>			
9.01	4.01 3.03	5.01	5.01	7.47	<u>3.02</u>	<u>6.02</u>	2.11	January 19, 2001
		2.17	4.04	5.45	<u>2.02</u>			
		1.60	3.04		<u>1.12</u>			
8.03	4.01 3.03	5.01	5.01	7.47	<u>3.02</u>	<u>6.02</u>	2.11	
		2.17	4.04	5.45	<u>2.02</u>			
		1.60	3.04		<u>1.12</u>			

- All above combinations have been verified.
- **If for RCONT Ver. 2.02 or later, be sure to use ADF Ver. 6.02 or later.**
- RUI need not be installed for proper operation.
- For a history of updates made to software other than the Saddle Finisher software (i.e., System Software/ADF/DCONT), refer to the appropriate Service Information bulletins.

**Service Parts:**

No.	Description		Part number	Q'ty	Stock	Inter-changeability	PC. Stock date
1	Old	EP-ROM	FF3-4105-000	1→0	C	↓ No    ↑ Yes ↓     ↑	Q90
	New	EP-ROM	FF3-4105-040	0→1	D		
2	Old	Saddle Controller PCB Ass'y	FG3-1311-020	1→0	C	↓ No    ↑ Yes ↓     ↑	Q90
	New	Saddle Controller PCB Ass'y	FG3-1311-030	0→1	D		

**Affected Machines:**

To be communicated as soon as identified.