


If your Cordless 7 sensor is not functioning properly, please refer to the following points:






Sensor and Magnet position

Position the magnet so that it passes in front of the sensor marking line.


Spacing between the sensor marking line and the magnet should be less than 5mm.



Best positions for the magnet and sensor

Try to position the face of the sensor towards the magnet as much as possible. Refer to the pictures below.

Area and distance where magnet sensitivity is optimized





The round 'bump' on the sensor should not face the magnet.

